	New	Mexico Envi	ronment	Department ·	Ground Wa	ater Quality Bureau - Closed/Inactive St	tate Clean Up S	ites		
	may vary. Coordinates may have be		ng google ea	rth, but other less o	accurate methods	may have been used .				
2	ty, then alphabetically by Site Name. Jurther action or CAR approved, or re		nroaram for	nrocessina such as	SOS/CERCIA HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may he archived or tro	ansferred with the referral		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
1000 Park Ave SE	1000 Park Ave SE	Albuquerque	Bernalillo	35.085469		soil vapor sampling for chlorinated solvents	unknown	samples results were below action levels	closed	7/23/2007
14th & Coal	14th & Coal	Albuquerque	Bernalillo	35.082147	-106.664078	Dewatering sewer line, BTEX	6/7/1984	water was properly disposed	closed	6/6/1984
14th and Coal trench dewatering	14th and Coal	Albuquerque	Bernalillo	35.08241	-106.67648	during a sewer line trench dewatering project BTEX was found	6/6/1984	dewatering and discharge to storm drain was ceased	closed	6/1/1984
203 Murray Street	203 Mury St.	Albuquerque	Bernalillo	35.08241	-106.67648	PCE discovered in GW from PSTB MWs	unknown	MNA	closed	11/9/2006
215 Hartline St.	215 Hartline St.	Albuquerque	Bernalillo	35.070256°	-106.668919°	Domestic well sampling following illegal dumping across street	1/8/2014	COA removed soil	inactive	10/27/2014
830 Broadway	830 Broadway	Albuquerque	Bernalillo	35.091401	-106.642371	Automotive repair shop with dry well, BTEX and solvents in soil	unknown	Source removal, MW installed	referred to VRP (Marble Arno)	11/17/2015
A.S. Horner	6280 SR 303 SE	Albuquerque	Bernalillo	35.08241	-106.67648	Spill, AST Refueling	5/16/2000	CAR approval	closed	8/26/2002
ABF Freight Systems	4800 Lincoln NE	Albuquerque	Bernalillo	35.141948	-106.588733	200 gal acetic acid spill	10/22/1996	acetic acid neutralized and absorbent removed	closed	1/17/1997
Aceves Domestic Well	4329 Meade SW	Albuquerque	Bernalillo	35.08241	-106.67648		unknown	results below stds	closed	4/9/2007
Albright Oil Co	1800 4th St NW	Albuquerque	Bernalillo	35.102021		petroleum contaminated soil	pre 1995	soil excavation HWB took lead and 3	closed	3/28/1996
Albuquerque Excavators	Isleta and Celeste	Albuquerque	Bernalillo	35.08241		heavy equipment company with hydrocarbon contaminated soil throughout yard	pre 2004	MWs installed under GWQB oversight	referred	
Albuquerque Metals Co.	3339 2nd St. SW	Albuquerque	Bernalillo	35.116881	-106.642093	Well, Supply contaminated	6/23/1985	sampled Soil sampling showed no	inactive	
Albuquerque Metals Recycling	3339 2nd St., SW	Albuquerque	Bernalillo	35.116881	-106.642093	metals recycling facility reported to puncture auto gas tanks and spill on ground	1997	contamination. CERCLA pre-screen showed As in a MW upgradient to the ATSF Tie Treating facility	inactive	
Albuquerque Metals Recycling	3339 Second Street SW	Albuquerque	Bernalillo	35.116881	-106.642093	Fire suppression water - heavy metals	7/25/2011	Direct push soil and ground	closed	11/10/2011
Albuquerque Sports Plex	9704 Lousiana NE	Albuquerque	Bernalillo			Release of diesel from AST during fire	Aug-96	Removal of AST, piping and impacted soil	closed	unknown
Alfred Luna Home	101 Woodland NW	Albuquerque	Bernalillo	35.111477		concern of pesticide disposal on property	pre 1/00	samples showed no evidence of pesticides	closed	8/16/2000
Alta Transportation	7920 Ranchitos Loop NE	Albuquerque	Bernalillo	35.170602	-106.612682	Loss of 1300 gal of dyed diesel from tanker,	4/19/2015	soil excavation	close	6/16/2016
Aluminum Sales Corp	1928 7th St NW	Albuquerque	Bernalillo	35.104194	-106.65281	TPH soil contamination from a Phase 2 ESA	pre 1996	sampling showed continued TPH in soil	inactive	
Amerigas/Van Waters & Rogers	3301 Edmonds Ave	Albuquerque	Bernalillo	35.08241	-106.67648	Discharge, CI-solvents		CERCLA site	CERCLA	
APD Parking lot	4th and Marquette NW	Albuquerque	Bernalillo	35.088208		discovery of petroleum contaminated soil	pre 10/2/2000	soil borings showed contaminated was contained by a clay layer	closed	11/17/2000
Approved/Mesa Oil	4532 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	old used oil AST, oil release to soil and AMAFCA channel	4/5/2004	soil excavation, removal of ASTs	closed	7/14/2005
Arnies Cleaners	8217 Menaul Blvd NE	Albuquerque	Bernalillo	35.109492°	-106.552295°	Release of PCE from Dry Cleaners	unknown	assessment	transferred to VRP	4/24/2018
ATA San Jose Pipeline	3300 South Broadway, Albuquerque, NM	Albuquerque	Bernalillo			pertroleum hydrocarbons pipeline fuel release discovered in late 1980's	unknown	pipeline replacement and long term soil vapor extraction system	closed	5/7/2009
Atex LUST	3501 Isleta	Albuquerque	Bernalillo	35.08241	-106.67648	LUST	1983	referred to PSTB	referred	
Atlas Oil Diesel Spill	7843 Tramway Blvd NE	Albuquerque	Bernalillo	35.172	-103.497257	37 gallons of diesel spill at gas station during dump, flowed into drain on to AMFCA RoW	4/20/2015	Excavation of impacted soil beside tankfield and below outfall	closed	6/12/2015
ATSF Auto Unloading	Appr 2000 ft S of Woodward and Williams	Albuquerque	Bernalillo			Fuel release from ASTs	unknown	product recovery and GW monitoring	closed	8/1/2000
ATSF Tie Treating Facility	3300 2nd St. SW	Albuquerque	Bernalillo	35.044191	-106.654897	creosote tie treating facility	1908-1972	referred to CERCLA-SOS	referred	
Ayala Residence	7516 Vista del Arroyo NE	Albuquerque	Bernalillo	35.137549	-106.561535	oil pant waste supposedly discharge to soil	Jul-95	sampling showed no solvents or paint waste	closed	6/1/1997
Barcelona Mobile Home Park	Coors and Barcelona T9N,R2E,3.4	Albuquerque	Bernalillo	35.08241	-106.67648	septic tank leach field study	1988	report published	closed	6/12/1988
Barr St., Charlene Warwick property	110 Barr Rd SE	Albuquerque	Bernalillo	35.08241	-106.67648	meth lab discharged to septic system	pre 7/15/04	3 MW installed and GW was clean	closed	1/26/2005
Bass LUST Site - TCE	4257 Isleta SW	Albuquerque	Bernalillo	35.08241	-106.67648	PSTB sampling showed low levels of TCE	unknown	GWQB investigation and domestic well sampling showed all results BLD	closed	5/1/2010
BCK Hydraulics	3405 Stanford NE	Albuquerque	Bernalillo	35.119542		phase 2 showed TPH, Cd, Pb in soil fill	8/19/1992	unknown	inactive	
Bell Gas Bernalillo County Equipment Yard	2200 Isleta NE Edith and Ritchfield NW	Albuquerque Albuquerque	Bernalillo Bernalillo	35.08241 35.08241		Spill, leaking tank diesel contaminated soil	6/2/1995 pre 9/98	soil excavation	inactive closed	11/10/1998
Big Chief Fina	9700 2nd St NW	Albuquerque	Bernalillo	35.134801		TPH in soils and PSTB site	unknown	soil excavation of surficial soil contamination, referred		10/1/2007
BNSF Trumbull Spill	100 Trumbull Ave SW	Albuquerque	Bernalillo	35.068288	-106 651047	150 gal of used oil spilled during offloading	6/26/1999	to PSTB soil excavation	closed	8/26/1999
Bogan Ave Contaminated soil	Tract 5-A-1, Reindeer Addition	Albuquerque	Bernalillo	00.000200		during excavation contaminated soil was discovered	pre 4/7/97	soil excavated, some	closed	9/23/1997
							p	capped with asphalt		

start sharts impact of the start sharts impact of the starts a (a) Power (a) (a) Power (b) (New	Mexico Envii	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive S	itate Clean Up S	ites		
Balance construction of a construction				ng google ea	rth, but other less	accurate methods	may have been used .				
balanceDesiteOpenOpenLangelapanLangelapanDesite				program for	processing such as		R/RCRA SIMR/RCRA ato Filos for sitos closed prior to 200	0 may be archived or tra	uncformed with the referral		
Number Number Number Ausgram Result Sold200 S								•		Status ³	Date
Back Paper Co No. Back Sing Add. Sing Back Sing Single Sin	Brake Masters								Lifts taken out of service, soil removal, cleaning of		
Name Name <t< td=""><td>Brothers Plating Co.</td><td></td><td>Albuquerque</td><td>Bernalillo</td><td></td><td></td><td>metal contaminated soil</td><td>Feb-92</td><td>SOS- Emergency Removal</td><td>closed</td><td>6/14/1992</td></t<>	Brothers Plating Co.		Albuquerque	Bernalillo			metal contaminated soil	Feb-92	SOS- Emergency Removal	closed	6/14/1992
ubbits proferND books yr ENo. yr yr endir yr	Cal Gas Propane Co	4120 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	analytical data	unknown		closed	
minute NATA of balance minute NATA minute NATA <thm< td=""><td>Cal-Maine Egg Farm</td><td>9100 Broadway SE</td><td>Albuquerque</td><td>Bernalillo</td><td>34.953753</td><td>-106.669908</td><td>groundwater from excess chicken manure and egg</td><td>unknown</td><td></td><td>referred to VRP</td><td>1/6/2017</td></thm<>	Cal-Maine Egg Farm	9100 Broadway SE	Albuquerque	Bernalillo	34.953753	-106.669908	groundwater from excess chicken manure and egg	unknown		referred to VRP	1/6/2017
unind Code15 Jours StringMougeneRenderControlMougeneRenderControlMougeneRenderControlMougeneMouge	Candelaria Well #3	3715 Edith NE	Albuquerque				been removed	8/31/1992		closed	
acc Residue de Calcione juit autrigant de calcione 01 - Jonne de calcione Alongenza Rende Salance Salanc	Capital Recycling										8/24/1994
Base and London 10 Out and You Chair and You C											
Chardbard Chardbard Control Contro Control Control	Casa Chevrolet and Collision One	7201 and 7501 Lomas NE	Albuquerque	Bernalillo	35.087312	-106.564159		pre 8/5/98		closed	1/12/1999
Water Hard ControlAdductionAddu	CCI U-Joints, Inc.	4220 Edith Blvd. NE	Albuquerque	Bernalillo	35.125422	-106.632451		7/12/2010	direct push soil investigation	closed	2/2/2012
under solution under solution<	water study	Coors Blvd and Coors Pl	Albuquerque	Bernalillo	35.199515	-106.660823	evaluation of GW for contaminants	Aug-88		closed	
ApperLefter Array Samup seriesAdduptionBernalImageImageBernalBernalImageBernalB	Childers Manufacturing	6th and Bezemek	Albuquerque	Bernalillo	35.104392	-106.650663	water heater manufacturer discharged into a dry well	pre 1995	monitoring	closed	6/26/1998
Likhow Im Sin Small Mean Benalty Benalty Sin Stratt Sin Stratt Benalty Sin Stratt Sin Stratt <td>City of ABQ Sewer line break, KAFB</td> <td>Tijeras Arroyo Sanitary Sewer</td> <td>Albuquerque</td> <td>Bernalillo</td> <td></td> <td></td> <td>interceptor line collapse spilling raw sewage</td> <td>5/6/2004</td> <td>soil samples to 40 '</td> <td>closed</td> <td>1/26/2005</td>	City of ABQ Sewer line break, KAFB	Tijeras Arroyo Sanitary Sewer	Albuquerque	Bernalillo			interceptor line collapse spilling raw sewage	5/6/2004	soil samples to 40 '	closed	1/26/2005
Multionent Y1) Pain shup S2 Bunn Yatu SE Abuqunqu Bernality 3.0.0774 3.0.0774 Multion Pain Section Section Pain Pain Section Pain Pain Pain Pain Pain Pain Pain Pai	Clubhouse Inn	1315 Menaul NE	Albuquerque	Bernalillo	35.109211	-106.629927	Phase 2 showed TPH soils	pre 5/98	collected. ND in GW. Site overlaid with asphalt	closed	8/24/1998
Deck Diminist Number	CNM (fomerly TVI) Paint shop	525 Buena Vista SE	Albuquerque	Bernalillo	35.076746	-106.624129	Limited Phase 2 showed low levels of metals in soil from dry well discharges.	unknown	show any significant vadose zone	closed	5/1/2010
number paper Point/Brown Mackie Fpeins spacer Point/Brown Mackie Fpeins (Sob Ocpper Ave NE)Abuquerque Abuquerque BernaliaBernalia Sob Sob Sob 	Conoco Phillips North (currently Holy Energy), Albuquerque, NM	4036 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	petroleum products at Bulk Terminal in early 90s and	pre 1990s	air sparging, SVES, MNA	closed	9/11/2012
apper Point Bioron Mackie Parilybiolon Coper Ave NEAbuguerupBenalii33.08000cls.53.23cl	Continental Express Trucking	I-40 and mile 150	Albuquerque	Bernalillo	35.08241	-106.67648	150 gal of diesel spill	12/30/1994	soil excavation	closed	1/27/1995
change Center, Suite 900 6600 Menaul Abuqueryue Bemailio 35.111341 1-106.649610 Livater separator hydraulic fluid release discovery unknown sol excavation does 27.72014 oronado Landtill L-25 and Alameda Abuqueryue Bemailio Coll Low weels of CE in rground water. (1) of pAbug continues monitoring. Part of Indfill excavated by private company under revolving loan fund. unknown GW monitoring inactive inactive ummings Southwest Abuguery Ww comer of Broadway and Merkight Rd Abugueryue Bemailio 35.1002 :-106.65904 performer release to soil; groundwater monitoring eneroval of performanter elosed provision constrainter olosed provision constrainter elosed provision constrainter olosed provision constrainter olosed provision constrainter olosed provision constrainter constrainter constrainter olosed provision constrainter constrainter olosed provision constrainter constrainter constrainter constrainter constrainter constrainter colosed	Copper Point/Brown Mackie Facility	10500 Copper Ave NE	Albuquerque	Bernalillo	35.080006	-106.532367	chlorinated solvents accumulated in SW corner of	11/1/2009	vapor intrusion with chlorinated solvents. A vapor abatement system was installed and operated that eliminated vapor	closed	5/23/2014
chanced Landfill Sch Alameda Abuquerque Benallo Lens continges monitoring. Part of landfill excavated by unknown GW monitoring. Bandito ummage Southeest Abuquerque Abuquerque Benallo Sch ale statute	Coronado Center, Suite 900	6600 Menaul	Albuquerque	Bernalillo	35.111341	-106.64961		unknown		closed	2/7/2014
ummings Southwest Albuquerque McKight R2 Not other of Broadway and McKight R2 Albuquerque Bernaillio Bernaillio Image: Control (Control (Contro) (Contro) (Control (Control (Control (Control (Control (Control (Coronado Landfill	I-25 and Alameda	Albuquerque	Bernalillo			continues monitoring. Part of landfill excavated by	unknown	GW monitoring	inactive	
unn Edwards Paint215 Rossmore Rd., SWAlbuquerqueBernalilio35.030661 -106.60389 Release from paint manufacturer's AST ad spills.pre 2013assessmentreferred to VRP $1/22/2010$ arthgrains Baking Co.111 Montaño NEAlbuquerqueBernalilio 35.137631 -106.632703 hydraulic lifts in garage caused soil contaminationunknown $assessment$ closed $1/21/2010$ 4 Amonete5715 El Prado NWAlbuquerqueBernalilio 35.08241 -106.67648 $cmpplaint$ Oct-89Sampled domestic wellclosed $1/21/2010$ Barato Junk Yard301 Tower SEAlbuquerqueBernalilio 35.08241 -106.67648 $cmpplaint$ Oct-89Sampled domestic wellclosed $1/24/1989$ chantment ElectronicsSol Isleta SWAlbuquerqueBernalilio 35.04926 -106.67648 hase 2 showed TPHpre 2/2/202soil borings and MWinstale Come diselel cont. soil @14 feetclosed $1/12/2199$ nvironmental Management2Ada nd Woodward SEAlbuquerqueBernalilio 35.04926 -106.67648 fradic accident and 120 gl disels spilt $4/13/1999$ soil excavationclosed $1/12/2002$ npeles Motorycele Shop7204 dh Nodward SEAlbuquerqueBernalilio 35.14977 -106.67648 $Aracident spilt cacident and 120 gl disels spilt4/13/1999soil excavationclosed3/7/2005npeles Motorycele Shop7204 dh ShwAlbuquerqueBernalilio35.14977-106.652812radicacident spilt $	Cummings Southwest Albuquerque		Albuquerque	Bernalillo					contaminated soil during	closed	9/4/2001
Arthgrains Baking Co.11 Montaño NEAlbuquerqueBernallilo35.137631-106.632703hydraulic lifts in garage caused soil contaminationunknownsoil sampling and excavationClosed1/2/2010d Amonette5715 El Prado NWAlbuquerqueBernallilo33.08241-106.67648ComplaintOct-89Sampled domestic wellClosed1/2/1/989Barato Junk Yard001 Tower SEAlbuquerqueBernallilo33.08241-106.67648inspection to show pollution prevention for businessAug-00inspectionclosed2/2/0202Inchantment ElectronicsSoil lokat SWAlbuquerqueBernallilo35.08241-106.67648phase 2 showed TPHpre 2/2/02soil borings and MWclosed4/26/2002Invironmental ManagementOnd Woodward SEAlbuquerqueBernallilo35.049505-106.65676traffic accident and 120 gal of diesel spilt4/13/1990soil excavationclosed1/1/2/1990Invironmental ManagementOnd Moodward SEAlbuquerqueBernallilo35.149777106.639222used oil spillpre 2/05soil excavationclosed3/1/2005Inver Ready Oil Co.101 Anderson SEAlbuquerqueBernallilo35.149777106.639221truck accident spilt diesel spilt10/15/1992soil excavationclosed3/1/2005Inver Ready Oil Co.101 Anderson SEAlbuquerqueBernallilo35.10834-106.65031AST overfilt caused 123 gal of diesel spill5/12/1966cloatentingclosed3/20/1966 <tr< td=""><td>Duke City Lumber</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>4/00/0047</td></tr<>	Duke City Lumber										4/00/0047
arting and grang as balang Co.111 Montano NeAlbiquerqueBemailio3.5.137.631-106.637.648CompaintOut.63.2708 (variable)variableexcavationclosed1/2/1/2010d Amonette5715 El Prado NWAlbuquerqueBemailio35.08241-106.67648inspection to show pollution prevention for businessAug-00inspectionsoil borings and MWBarato Junk Yard3010 Tower SEAlbuquerqueBemailio35.08241-106.67648inspection to show pollution prevention for businessAug-00inspectionsoil borings and MWnchantment Electronics500 Isleta SWAlbuquerqueBemailio35.04245-106.676748phase 2 showed TPHsoil borings and MWinspectionclosed4/26/2002nvironmental Management2nd and Woodward SEAlbuquerqueBemailio35.049505-106.656767traffic accident and 120 gal of diesel spilt4/13/1999soil excavationclosed1/1/2/1995pres Zinzu Sing10508 Menaul NEAlbuquerqueBemailio35.049505-106.656767traffic accident and 120 gal of diesel spilt4/13/1999soil excavationclosed1/1/3/1993ver-Ready Oil Co.101 Anderson SEAlbuquerqueBemailio35.049505-106.656767traffic accident spilt diesel10/15/192soil excavationclosed1/1/3/1993ver-Ready Oil Co.101 Anderson SEAlbuquerqueBemailio35.14977-106.632231track accident spilt diesel10/15/192soil excavationclosed1/1/3/1993 <td></td>											
Barato Junk Yard 310 Tower SE Albuquerque Bernalillo 35.08241 -106.6768 inspection to show pollution prevention for business increae Aug-00 inspection spection to show pollution prevention for business increae nchantment Electronics 500 Isleta SW Albuquerque Bernalillo 35.08241 -106.67648 phase 2 showed TPH pre 2/2/02 soil borings and MW installed. Some diesel cont. soil @14 feet closed 4/26/2002 nvironmental Management pries Motorycle Shop 7201 4th St NW Albuquerque Bernalillo 35.08241 -106.656767 trafic accident and 120 gal of diesel spill 4/13/1999 soil excavation closed 37/205 nvironmental Management pries Motorycle Shop 7201 4th St NW Albuquerque Bernalillo 35.14977 106.658272 trak accident spill diesel 101/15/1992 soil excavation closed 37/205 nver-Ready Oil Co. 101 Anderson SE Albuquerque Bernalillo 35.12594 -106.658263 Aroverfill caused 1239 gal of diesel spill 51/2/1996 soil excavation, storm rain cleaning closed 3/2/1996 ver-Ready Oil Co. 101 Anderson SE Albuquerque Bernalillo 35.12594 -106.653263 <									excavation		
Barato Junk Yard Soft Tower SE Albuduerque Bernalilio 33.58241 -106.67648 icense Albuduer Binact Soft Soft Soft Soft Soft Soft Soft Soft	Ed Amonette						inspection to show pollution provention for business				12/4/1989
Inchantment Electronics 500 Isleta SW Albuquerque Bernalilio 35.08241 -106.67648 phase 2 showed TPH pre 2/2/02 installed. Some diesel cott. soil @14 feet closed 4/26/2002 nvironmental Management 2nd and Woodward SE Albuquerque Bernalilio 35.049505 -106.6566767 traffic accident and 120 gal of diesel spilt 4/13/1999 soil excavation closed 3/12/1999 opies Motorcycle Shop 7201 4th St NW Albuquerque Bernalilio 35.149777 -106.632322 used oil spill pre 2/05 soil excavation closed 3/72005 mest Chavez Trucking 10508 Menaul NE Albuquerque Bernalilio 35.108892 -106.652312 truck accident spilt diesel 10/15/1992 soil excavation, storm drain cleaning closed 1/13/1993 ver-Ready Oil Co. 101 Anderson SE Albuquerque Bernalilio 35.12594 -106.65268 runoding diesel spill cause 120 gal fl/22/1996 soil excavation, storm drain cleaning closed 3/20/1996 ver-Ready Oil Co. 4911 Jefferson NE Albuquerque Bernalilio 35.12594 -106.65268 75 gal of diesel spill cause 120 gal 1/12/1996 soil exc	El Barato Junk Yard	3010 Tower SE	Albuquerque	Bernalillo	35.08241	-106.67648		Aug-00		closed	
Invironmental Management2nd and Woodward SEAlbuquerqueBernalilio 35.049505 -106.656767 traffic accident and 120 gal of diesel spilt $4/13/1999$ soil excavationclosed $11/12/1999$ opies Motorcycle Shop7201 4th St NWAlbuquerqueBernalilio 35.149777 -106.639222 usd oil spillpre 2/05soil excavationclosed $37/2005$ innest Chavez Trucking10508 Menaul NEAlbuquerqueBernalilio 35.149777 -106.639222 usd cident spilt diesel10/15/1992soil excavationclosed $37/2005$ ver-Ready Oil Co.101 Anderson SEAlbuquerqueBernalilio 35.10809 -106.650331 AST overfill caused 1239 gal of diesel spill $512/1996$ closed soil eccavation, storm drain cleaning spillclosed $3/20/1996$ ver-Ready Oil Co.400 Edith NEAlbuquerqueBernalilio 35.12594 -106.632281 unloading diesel spill cause 120 gal $1/22/1996$ containing and absorbing spillclosed $3/20/1996$ FE Transportation Service Truck4911 Jefferson NEAlbuquerqueBernalilio 35.12594 -106.632281 unloading diesel spill cause 120 gal $1/12/1996$ containing and absorbing spillclosed $3/20/1996$ FE Transportation Service Center1912 2nd St NWAlbuquerqueBernalilio 35.103686 $-106.659367676767676767676767676767676767676767$	Enchantment Electronics	500 Isleta SW	Albuquerque	Bernalillo	35.08241	-106.67648	phase 2 showed TPH	pre 2/2/02	installed. Some diesel	closed	4/26/2002
Instruction Model Model Bernallilo 35.108892 -106.523512 ruck accident spilt diesel 10/15/1992 soil excavation closed 1/13/1993 ver-Ready Oil Co. 101 Anderson SE Albuquerque Bernallilo 35.108892 -106.650331 AST overfill caused 1239 gal of diesel spill 5/12/1996 soil excavation, storm drain cleaning closed 6/23/1996 ver-Ready Oil Co. 400 Edith NE Albuquerque Bernallilo 35.12594 -106.63228 unloading diesel spill cause 120 gal 1/22/1996 containing and absorbing spill closed 3/20/1996 ET transportation Services Truck 4911 Jefferson NE Albuquerque Bernallilo 35.137686 -106.593563 75 gal of diesel release from an accident 1/13/2000 absorbed fuel closed 2/9/2000 cocident 1912 2nd St NW Albuquerque Bernallilo 35.103348 -106.645031° Soil contamination from Oil/Water Separator 2/1/2012 soil excavation closed 2/9/2000	Environmental Management										
ver-Ready Oil Co. 101 Anderson SE Albuquerque Bernalillo 35.06303 -106.65033 AST overfill caused 1239 gal of diesel spill 5/12/1996 soil excavation, storm drain cleaning closed 6/23/1996 ver-Ready Oil Co. 4600 Edith NE Albuquerque Bernalillo 35.12594 -106.65033 AST overfill caused 1239 gal of diesel spill 1/22/1996 soil excavation, storm drain cleaning closed 3/20/1996 FE Transportation Services Truck ccident 4911 Jefferson NE Albuquerque Bernalillo 35.137686 -106.659356 75 gal of diesel release from an accident 1/13/2000 absorbed fuel closed 2/9/2000 restone Service Center 1912 2nd St NW Albuquerque Bernalillo 35.103348° -106.645031° Soil contamination from Oil/Water Separator 2/1/2012 soil excavation closed 2/9/2000											
Ver-Ready Oil Co. 4600 Edith NE Albuquerque Bernalillo 35.125944 -106.632281 unloading diesel spill cause 120 gal 1/22/1996 containing and absorbing spill closed 3/20/1996 TE Transportation Services Truck 4911 Jefferson NE Albuquerque Bernalillo 35.137686 -106.593563 75 gal of diesel release from an accident 1/13/2000 absorbed fuel closed 2/9/2000 restone Service Center 1912 2nd St NW Albuquerque Bernalillo 35.103348° -106.645031° Soil contamination from Oil/Water Separator 2/1/2012 soil excavation closed 7/27/2012	Ernest Chavez Trucking Ever-Ready Oil Co.								soil excavation, storm		
FE Transportation Services Truck A911 Jefferson NE Albuquerque Bernalillo 35.137686 -106.593563 75 gal of diesel release from an accident 1/13/2000 absorbed fuel closed 2/9/2000 restone Service Center 1912 2nd St NW Albuquerque Bernalillo 35.103348° -106.645031° Soil contamination from Oil/Water Separator 2/1/2012 soil excavation closed 7/27/2012	Ever-Ready Oil Co.								containing and absorbing		
restone Service Center 1912 2nd St NW Albuquerque Bernalillo 35.103348° -106.645031° Soil contamination from Oil/Water Separator 2/1/2012 soil excavation closed 7/27/2012	FFE Transportation Services Truck										
	Accident Eirestone Service Center										
	First Native American Corp.										112112012

¹ Latitudo and Longitude and				•		Iter Quality Bureau - Closed/Inactive S				
	may vary. Coordinates may have be		ng google earti	h, but other less a	ccurate methods	may have been used .				
	y, then alphabetically by Site Name.		program for pr	ocassing such as	OS/CERCIA HW/	3/RCRA, SWB/RCRA etc. Files for sites closed prior to 200) may be archived or t	ansforred with the referral		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Folev's Dept. Store	6600 Menaul NE	Albuquerque	Bernalillo	35.109054		hydraulic oil release from elevator	pre 2/16/00	soil excavation	closed	8/25/2000
Forke Bros. Auctioneers	13510 Central SW	Albuquerque	Bernalillo	35.068101		petroleum contaminated soil and sandblasting residue	pre June 99	soil excavation	closed	11/12/1999
Former Amity Leather	6700 Bluewater NW	Albuquerque	Bernalillo	35.086192		Soil vapor survey showed low levels of TCE	unknown	assessment	closed	3/13/2001
								Additional sampling		
Former Dion's Pizza	5939 4th St NW	Albuquerque	Bernalillo	35.143138	-106.640452	A limitted Phase 2 showed TPH at 20 feet in subsurface	unknown	showed no further	closed	7/13/2011
								contamination		
								given dtw and TPH		
Former Friendly Cadillac site	1601 Central NE	Albuquerque	Bernalillo	35.090344	-106.665	hydraulic lift contaminated soil	pre 3/92	concentrations @ 30 ft, no	closed	3/1/1992
								excavation was required		
								soil excavation and MW		
Former Pintura Paint	6536 4th St NW	Albuquerque	Bernalillo	35.149059	-106.639207	fire fighting waste water had VOCs	7/16/1996	installation; ground water	closed	3/30/1998
								was below standards		
Fox Candelaria	2501 Candelaria NE	Albuquerque	Bernalillo	35.115653	-106.616697	Superfund SI conducted from past solvent release	pre 2/2/05	sample MW, clean	closed	9/15/2005
								additional soil vapor sampling showed		
Francis Home - VOC Vapors	8404 Rio Verde PI, NW	Albuquerque	Bernalillo	35.179006	-106 681763	Low levels of BTEX and CI solvents found in soil vapor	unknown	detections but very low to	closed	2/3/2012
		/ libuquerque	Derritanile	00.170000	100.001700	at private residence	unutown	not warrant further	000000	2/0/2012
								corrective action.		
Frito Lay	1550 Mission Ave	Albuquerque	Bernalillo	35.140284	-106.60812	Spill, motor oil	12/15/2000	CAR approval	closed	2/20/2001
Gallegos, Michael domestic well	PO Box 11, Star Route	Albuquerque	Bernalillo			domestic well sample taken	unknown	samples showed ND and	closed	
						· ·		installed new well		=//// 0000
Gardner Zemke	4600 Lincoln West of McLeod and Jefferson	Albuquerque	Bernalillo	35.142028		Discovery of Chlorinated Solvents in Soil PCB's, metals and Chlorinated solvents discovered in	1994	Soil Vapor analysis soil excavation and GW	closed referred to EPA /	7/1/1998
GE Apparatus	NE	Albuquerque	Bernalillo			soils	unknown	monitoring	closed	2006
GE Aviation Plan Building 9 Oil								Ũ		
Sump Pit	Woodward and Broadway SE	Albuquerque	Bernalillo	35.048847	-106.646552	oil sump with TPH	unknown	assessment and soil remov	closed	4/14/2008
GE Plant, Albq		Albuquerque	Bernalillo			Cutzon WS5050 coolant spill	Nov-87	see CERCLA file	referred	
General Waste	3049 Edith NE	Albuquerque	Bernalillo	35.115461	-106.634997	discovery of petroleum stained soil in 4/03	unknown	soil excavation and samplin	closed	9/1/2003
Gino's Restaurant & Lounge	1401 Coors SW	Albuquerque	Bernalillo	35.100503	-106.707039	Sampling, nitrate	pre 92		inactive	
Gino's Restaurant and Lounge	unknown	Albuquerque	Bernalillo			high NO3 in water sample	pre 93	installed treatment system	closed	
						A l'annu Dal Ohamaina l'an l'anna da Chanadana anna ia		UST was emptied and		
Graves Oil and Butane	105 Dale Ave SE	Albuquerque	Bernalillo	35.08241	-106.67648	Adjacent RekChem site disposed of hazardous waste in UST	pre 7/90	removed; soil samples below showed no	closed	6/12/1992
						031		contamination		
Groendyke Aviation fuel spill	6346 St Rd. 47	Albuquerque	Bernalillo	34.985046	-106.655357	tanker truck accident and 3000 gal spill	7/11/2005	soil excavation	closed	11/8/2005
				-				no source found and 6		
Gulfstream Lomas	111 Lomas NW	Albuquerque	Bernalillo	35.09081	-106.646922	BTEX reportedly found in well	unknown	MWs installed with MNA	closed	12/11/2009
								as abatement		
Harrison Contractors	4201 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648		May-87	sampled domestic wells	closed	5/1/1987
Hertz Co.	3601 Osuna 8500 Bluewater Rd NW	Albuquerque	Bernalillo	35.154279		50 gal of gasoline spilt from AST non-PCB transformer oil leak	4/1/1998 9/15/1998	soil excavation soil excavation	closed closed	5/15/1998 12/22/1998
Honeywell Hutchinson Fruit Co. (same as Sun		Albuquerque	Bernalillo	35.082083					ciosed	see Sun Valle
Valley Fruit Co)	7110 2nd St NW	Albuquerque	Bernalillo	35.134801	-106.638023	petroleum hydrocarbon contaminated soil	pre 9/91	Phase 2 ESA report	closed	Fruit Co. 2006
								soil excavation, passive		
I-25 Gasoline Spill	I-25, 2.5 miles N of Tramway on Sandia Pueblo	Albuquerque	Bernalillo			a Truck accident caused a 2000 gal release of gasoline	10/31/1990	soil vapor extraction, GW	closed	post 7/93. Puet had jurisdiction
	Salidia Fuebio							monitoring		nau junsuictio
-40 Frontage Rd in Carnuel	16908 E. I-40 Frontage Rd.	Albuquerque	Bernalillo	35.08241	-106 67648	Limited Phase 3 showed TPH in soil at a maximum	unknown	soil results showed no	closed	11/1/2008
	g					concentration of 180 ppm.		threat to GW		
Idaho Timber LLC	6300 St Hwy 47	Albuquerque	Bernalillo	34.985448	-106.655271	during Phase 2 ESA contaminated soil was encountered @ 50'	pre 5/3/06	MW show GW was clean	closed	7/14/2006
								soil excavation by property		
Illegal dumping of used oil drums	east of 98th and I-40	Albuquerque	Bernalillo			illegal dumping of 6 drums caused used oil discharge	12/4/2000	owner	closed	2/9/2001
Isleta & Don Felipe SW USGS	Isleta & Don Felipe	Albuquerque	Bernalillo			Well contamination (isopropyl toluene), USGS, SOS	Dec-94	CERCLA screen	inactive	
Monitor Well		Albuquerque				(11) ,, ,				
Jack's Auto Parts	4320 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	burying of used oil and antifreeze	pre 12/00	soil excavation	closed	3/30/2001
								soil vapor samples and		
JB Cleaners	1615 Eubank NE	Albuquerque	Bernalillo	35.098395	-106.532883	during Phase 2 ESA PCE found in soil vapor	pre 1/4/06	calculations showed no potential to contaminate	closed	4/16/2006
						-		GW @ 600'		
JF McGill Contracting Co								soil excavation per Fire		
(emulsified asphalt plant)	4959 Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	petroleum contaminated soil	pre 95	Marshall	closed	6/17/1995
JM Thomas Forest Products	5851 Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	250 gal diesel fuel release	8/18/2003	soil excavation	closed	9/26/2003
MF Transmission CO	6629 Lomas NE	Albuquerque	Bernalillo	35.087357	-106.573781	vehicle hydraulic lift releases	pre 2006	soil sampling	closed	12/8/2006
R Hale Contracting	505 Carmony Rd. NE	Albuquerque	Bernalillo	35.127841	-106.623706	TPH soil contamination from a Phase 2 ESA	pre 3/30/05	soil excavation	closed	7/30/2007
KAFB / Condensate Release	Fuels Drive	Albuquerque	Bernalillo	35.049858°	-106,579153°	30 gallons of a mixture of water and condensate were	2/1/2017	soil excavation	closed	11/28/2017
						released during the dismantling of an SVE system				
KAFB / Drilling fluids leak, KAFB-	BFF IDW yard, south of	Albuquerque	Bernalillo	35.050625°		50 gallon leak of drilling fluid (water) from lined roll-off	3/20/2017	soil excavation	closed	4/28/2017

	New N	lexico Envi	ronment I	Department ·	- Ground Wa	ater Quality Bureau - Closed/Inactive St	ate Clean Up S	Sites		
	may vary. Coordinates may have bee	en determined us	ing google ear	th, but other less o	accurate methods	may have been used .				
2	y, then alphabetically by Site Name. urther action or CAR approved, or res	ferred to another	program for p	processing such as	SOS/CERCLA. HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may be archived or t	ransferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
KAFB / Golf Course Pond Clearning Coolant Leak	KAFB Golf Course Pond	Albuquerque	Bernalillo	35.023396°	-106.528257°	Spill of ~2.5 gallons of water and ethylene glycol from vehicle	7/11/2017	soil excavation	closed	8/11/2017
KAFB / NC-135	Short and Randolph	Albuquerque	Bernalillo	35.049927°	-106.582633°	Spill of diesel or jet fuel	10/20/2017	soil excavation	closed	3/15/2018
KAFB / SNL Burn Site	Lurance Canyon Burn Site	Albuquerque	Bernalillo			fuel burning testing facility - BTEX, PAH, NO3 contamination in ground water	unknown	HWB RCRA permit oversight	referred	
KAFB / Well development water KAFB 106239	Ridgecrest Drive SE just east of San Pedro Drive	Albuquerque	Bernalillo	35.054816°	-106.576549°	Spill of 150 gal of well development water from KABF- 106239	1/8/2017	soil excavation	closed	3/17/2017
KAFB Bldg 2022	Kirtland Air Force Base	Albuquerque	Bernalillo			sewage overflow at Bldg 20220	1/19/2000	sewage recovery and disinfection	closed	4/18/2000
KAFB Dielectric oil release	arroyo north of High Energy Research Technology Facility	Albuquerque	Bernalillo			release of 10 gal of oil	8/22/1995	soil excavation	closed	6/17/1995
KAFB Fuel Depot	Fuels Drive & Randolf Avenue, Kirtland Air Force Base, Albuquerque, New Mexico	Albuquerque	Bernalillo			Aviation gasoline discharges caused vadose zone and GW contamination with LNAPL to 500 ft bgs.	unknown	SVES since 2000 and LNAPL recovery since 2007. HWB assumed regulatory oversight in 2010.	referred	
KAFB Hanger 1002	SW of Randolph and San Mateo	Albuquerque	Bernalillo			water line break flowed to oil water separator, releasing water and petroleum product into Tijeras arroyo	8/8/1999	OWS cleaning and soil sampling	closed	10/29/1999
KAFB HCL Release	Bldg 858, NE Section of Tech Area 1	Albuquerque	Bernalillo			discovery of HCL release from an acid tank	4/10/2000	neutralization of soil	closed	4/24/2000
KAFB heating oil	Manzano Administration Area	Albuquerque	Bernalillo			closure and capping of old heating oil lines	n/a	closure of lines and soil sampling was ND	closed	6/1/1996
KAFB/Sandia McCormack Ranch	McCormick Ranch, SW corner of base	Albuquerque	Bernalillo			use of NH4-NO3 for explosives	unknown	HWB-RCRA oversight	inactive	
Karen Box property	204 Murry SE	Albuquerque	Bernalillo	35.08241	-106.67648	old MWs from a LUST site showed PCE ~30	pre 8/31/04	PSTB conducted further investigation and PCE attenuated to below stds.	closed	11/9/2006
Keers Environmental	1701 Broadway SE	Albuquerque	Bernalillo	35.066636		truck accident caused 20 gal of diesel release	8/24/1999	soil excavation	closed	1/13/2000
Kelley's Transmission	1816 Central SW	Albuquerque	Bernalillo	35.091666	-106.666658	vehicle hydraulic lift releases, and oil water separator releases	pre 4/05	12 lift removals, OWS removal, soil excavation, MW sampling	closed	3/23/2007
KKOB Transmitter site	2nd Street NW Transmitter location	Albuquerque	Bernalillo	35.08241	-106.67648	vandalism caused 25 gal of diesel spill	3/20/1997	soil excavation	closed	7/8/1997
K-Mart Automotive	4th St. and Menaul	Albuquerque	Bernalillo	35.110931	-106.646553	hydraulic lifts in garage caused soil contamination	pre 1999	soil excavation	closed	11/19/1999
Larry H Miller Commercial Property	8528 Lomas NE	Albuquerque	Bernalillo	35.087296	-106.551516	During building demolition hydraulic lift contamination found	unknown	soil excavation and capping	closed	9/23/2011
Layton Bros. Drums	608 General Chenault	Albuquerque	Bernalillo	35.068411	-106.544423	drum cleaning and recycling center had sump with possible leakage	9/6/1984	samples showed no evidence of soil contamination and disposal according to HWB regs	closed	6/13/1985
Leatherback	100 Trumbull Ave SE	Albuquerque	Bernalillo			Petroleum impacted soil discovered during property transfer, likely from historical tar paper manufacturing	before 1998	Monitoring wells did not show contamination	closed	3/6/2001
Lee's Automotive	2401 Wyoming Blvd NE	Albuquerque	Bernalillo	35.111214°	-106.551176°	Spill from 5 hydraulic lifts	11/22/2016	soil excavation	closed	1/31/2017
Lewis St Sewer Line Overflow	Lewis Av. Between Arno and Broadway	Albuquerque	Bernalillo			1.2 million gallons of sewer overflow into stormwater pond	3/14/2007	pump sewage to WWTP	closed	5/25/2007
Lobo Engine	900-902 2nd St. NW	Albuquerque	Bernalillo	35.076582		soil investigation showed TPH	pre 95	soil borings and MW showed below stds	closed	6/17/1995
M&S Chevron	5640 4th St	Albuquerque	Bernalillo	35.13912	-106.641125	release of 242 gal of gas during UST filling discharging into storm drain	7/17/2002	pumping of 30000 gal of water to storm drain to clean	closed	11/1/2002
Martinez Town Sewage Spill	Arno and Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	Stormwater flowed into sewer line causing overland flow	7/31/2006	Repaired stormwater line that flowed into sewer line and soil excavation	closed	6/7/2010
Mary Medina MB Oil	119 Marlowe Lane NE I-40 MM 151	Albuquerque Albuquerque	Bernalillo Bernalillo	34.166233	-106.026069	Sampling, private well truck accident released 1000 gal of diesel	5/21/1987 1/6/1999	sampled well soil excavation	inactive closed	5/24/1999
McDonalds	Eubank and Candelaria	Albuquerque	Bernalillo	35.116175	-106.533236	subsurface investigation showed low levels of acetone	Aug-90	soil sample results showed	closed	1/10/1991
MCT Industries	I-25 and Stadium (Cesar Chavez)	Albuquerque	Bernalillo	35.08241		150 gal of diesel spill	6/8/1994	no threat absorbed fuel	closed	7/26/1994
Melloy Dodge Commercial Poperty		Albuquerque	Bernalillo	35.092014		Limited Phase 3 showed TPH in soil.	unknown	soil excavation and soil samples collected to depth.	closed	4/5/2010
Mesa del Sol Landfill	S. Broadway Landfill, E of I-40 S of Tijeras Arroyo	Albuquerque	Bernalillo	35.08241		former landfill	unknown	closure under SWB	referred	
Montesa Park Convenience Center		Albuquerque	Bernalillo	35.08241	-106.67648	during fueling and lubrication of vehicles, petroleum hydrocarbon was discharged	pre 94	soil excavation	closed	6/16/1994
Motor Cargo	11030 Cochiti SE	Albuquerque	Bernalillo	35.069977		Spill, hydrazine	3/6/2000	CAR approval	closed	6/30/2000

1						ater Quality Bureau - Closed/Inactive St	tate Clean Up	Sites		
•	may vary. Coordinates may have b		ng google ear	th, but other less a	ccurate methods	may have been used .				
2	ty, then alphabetically by Site Name Further action or CAB approved, or r		program for r	rocessing such as	SOS/CERCIA HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may be archived or t	ransferred with the referral		
Site Name ²	Location	City ²	County ²	Latitude 1		Event	Discharge Date	Action Taken	Status ³	Date
North Albuquerque Acres Landfill	Elena Dr and Barstrow, NE	Albuquerque	Bernalillo	35.08241		Developer conducted excavation from former landfill under SWB regulations	unknown	Neighbors were concerned with landfill exposure and ground water concerns. Subsequent sampling showed no soil contamination	closed	1/1/2007
Oil Sludge Disposal Trenches One Executive Center/ WHEXC One Park Place	5100 Broadway SE 8500 Menaul Blvd. NE 2125 Louisiana NE	Albuquerque Albuquerque Albuquerque	Bernalillo Bernalillo Bernalillo	35.004338 35.109187 35.10026	-106.549626 -106.568829	discovery of TPH-tar disposal trenches Spill, elevator hydraulic leak Spill, elevator hydraulic leak	1980s 1/4/2000 9/27/2000	soil excavation CAR approval CAR approval	closed closed closed	11/9/2010 2/7/2000 10/10/2000
Pam Ebeltoft Pep Boys Store #696	509 Jefferson SE 5651 San Mateo NE	Albuquerque	Bernalillo Bernalillo	35.072814 35.144001		Complaint hydraulic lift contaminated soil subsurface investigation showed low levels of	3/9/2000 pre 2000	inspection/letter soil excavation contamination related to a	closed closed	4/12/2000 2/7/2000
Phillips Semi Conductor PNM Albq. Service Center	9201 Pan American Freeway 4201 Edith NE	Albuquerque	Bernalillo Bernalillo	35.188273 35.125488	-106.634609	leak from UST line	unknown 1986	former landfill, HWB jurisdiction referred to PSTB	referred/closed referred	
PNM Albq. Service Center PNM Manufactured Gas Plant	4201 Edith NE Central and John St.	Albuquerque Albuquerque	Bernalillo Bernalillo	35.125488 35.083824	-106.645877	petroleum hydrocarbon contaminated soil old MPG plant discovered	pre 1995 pre 1950	soil excavation major soil excavation Remediation via RCRA	closed closed	6/17/1995 6/26/2002
PNM Person Generating Station PNM Reeves Station	3800 Broadway Blvd SE 4400 Paseo del Norte NE	Albuquerque	Bernalillo Bernalillo	35.027618 35.170482		Multiple releases of chlorinated, petroluem and metals alleged PNM landfill with possible drums	various pre 94	Permit soil vapor survey and 3 MWs installed showed no	closed	6/17/1996
Ponderosa Products Inc.	1701 Bellamah St. NW	Albuquerque	Bernalillo	35.100827	-106.664441	Discharge, WW/nitrates, formaldehyde	1/16/1984	stds violation Settlement agreement, 1/4 sampling	closed	2/2/2002
Postal Service Main Yard Presbyterian Hospital Energy	1135 Broadway NE 1100 Central SE	Albuquerque	Bernalillo Bernalillo	35.072184 35.082586		tar release from old tank transfer of diesel caused 50 gal release	pre 1980 4/17/2000	soil excavation	closed closed	6/20/2001 5/17/2000
Center Prime Inc.	4531 Wyoming NE	Albuquerque	Bernalillo	35.131112		truck accident and 150 gal of diesel spilt	10/27/1997	soil excavation soil excavation and GW	closed	2/20/1998
Pronto Service Co. Pronto Waste Oil Recycling	1107 Coors SW 4700 Broadway St. SE	Albuquerque Albuquerque	Bernalillo Bernalillo	35.098989 35.08241	-106.67648	PCB oils contaminated soil Spill, PCBs	pre 1982 1983	monitoring EPA Removal	closed closed	6/5/1985 6/5/1983
Quality Jeep Eagle Chrysler Plymouth	8101 Lomas Blvd	Albuquerque	Bernalillo	35.087382	-106.556788	hydraulic lift contaminated soil	pre 95	lift removal and soil excavation	closed	4/4/1996
Quality Pontiac	1300 Lomas NE	Albuquerque	Bernalillo	35.091873	-106.629952	petroleum hydrocarbon contaminated soil	pre 2001	soil and soil vapor sampling showed no threat to GW or human exposure	closed	3/1/2003
Quality Pontiac	1300 Lomas NE	Albuquerque	Bernalillo	35.091873	-106.629952	Demolition of buildings on property	NA	Removal of hydraulic lifts and Oil-Water Separator - No contamination noted.	closed	3/31/2014
Ray's Automotive	1909 4th St NW	Albuquerque	Bernalillo	35.103998	-106.64797	during solvent investigation in area the autoshop had visual discharge areas. 2 MWs were installed to determine if site was a source.	unknown	analytical results from upgradient MW showed the site was not a source of the solvent plume.	closed	9/28/2006
REK Chem- Graves Oil Ritchie Bros. Auctioneers	105 Dale St. Alameda and Edith NE	Albuquerque	Bernalillo Bernalillo	35.004 35.192186		Illegal Dumping petroleum contaminated soil and sandblasting residue	1988 pre 1998	UST removed, legal action soil excavation	semi-orphan closed	3/5/2001
Robert's Oil Truck Accident Robert's Oil Truck Accident	Broadway and Rio Bravo Gibson and Mulberry	Albuquerque	Bernalillo Bernalillo	35.08241 35.059182	-106.64664 -106.635439	truck accident lost 8700 gal of gas 2000 gal of gasoline spill high Pb in shop and concern over employee exposure.	4/14/1999 9/30/1995	soil excavation soil excavation	closed closed	7/21/1999 3/30/1996
Rubi's Metals, Inc. Rust Tractor	2227 Mayflower Rd 400 Osuna Rd NE	Albuquerque	Bernalillo Bernalillo	35.08241 35.151456	-106.67648	40ft well on-site showed 6.41 ppb Pb. diesel spill into unlined pond	pre 1981 Jul-85	testing of blood.	inactive closed	6/7/1985
Rust Tractor Albq.	400 Osuna NE	Albuquerque	Bernalillo	35.151456	-106 623269	old evaporative largoon showed hydrocarbon	pre 1988	soil excavation and boring to 100 feet was clean	closed	6/8/1997
Sacramento Landfill	Paseo del Norte and I-25	Albuquerque	Bernalillo	35.17429	-106.583738	Triage scoring showed medium concern for bldg of Albq. Sports Store	pre 95	triage score and letter	inactive	7/11/1995
Safety Clean Truck Accident	Hwy 66, off I-40 East	Albuquerque	Bernalillo			Truck accident discharged waste oil.	5/7/1996	soil excavation	closed	
San Jose Community Awareness Council Private well survey	San Jose Community	Albuquerque	Bernalillo	35.08241	-106.67648	sampling to evaluate VOC impacts in domestic wells		results showed no VOC impacts	closed	10/1/1992
Sandia Peak Services	Primrose Lift Station	Albuquerque	Bernalillo			25,000 gal of sewage overflow	11/2/1994	soil excavation and disinfection pump to Albq. WWTP and	closed	1/1/1995
Sandia Peak Services Sandia Peak Services	Primrose Lift Station Tennyson and Tramway	Albuquerque	Bernalillo Bernalillo			5000 gal of sewage spill from lift station malfunction 400 gal of sewage spill due to pump failure	8/10/2000	soil disinfection	closed	1/8/2001 4/21/2000
Seven Bar Airport	Cottonwood Mall	Albuquerque	Bernalillo	35.08241		petroleum hydrocarbon spill	1990?	soil excavation soil survey and soil gas	closed	2/27/1995
SHB Agra	4700 Lincoln NE	Albuquerque	Bernalillo	35.141957	-106.590893	use of solvents and soil investigation	pre 1994	sampling showed no impacts	closed	6/20/1996

Site Name ² Location Sigma Minerals Corp UNM Sou Smith's Fuel Center 111 Coor Soil Contamination Eubank a Solv-Ex 2121 Mer South Valley Livestock Auction 7715 Bro South Valley Superfund Site Woodwar South Valley Superfund Site Woodwar South Valley Superfund Site Broadway Steamatic Commercial Property 3007 San Steer Tank Lines 4508 Bro Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg	Iphabetically by Site Name. tion or CAR approved, or referred to on Cit buth Golf Course Landfill Albuqu ors NW Albuqu and Candelaria Albuqu enaul NE Albuqu roadway SE Albuqu ard and Broadway SE Albuqu ay and Rio Bravo Albuqu and Pero NE Albuqu roadway SE Albuqu ah St W Albuqu an Pedro NE Albuqu roadway SE Albuqu an Netro NE Albuqu ad St NW Albuqu ad St NW Albuqu	to another pro City ² C Jquerque B Jquerque B			SOS/CERCLA, HW/ Longitude ¹ -106.710796 -106.533236 -106.621611	may have been used . B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 Event Lab and Milling Co Disposed of residual ore and waste in landfill During pre-construciton for a gas station TPH soils were encountered in the parking lot run off depression. discovery of petroleum contaminated soil from UST shallow surface contamianted with petroleum hydrocarbons	may be archived or tr Discharge Date pre 1957 unknown pre 2/22/90	Action Taken data did not show contamination concern soil excavation and sampling refer to PSTB direct push soil investigatio	Status ³ closed closed referred closed	Date 9/24/2008
³ Status may consist of closed/no further activity Sigma Minerals Corp UNM Souther activity Sigma Minerals Corp UNN Souther activity Smith's Fuel Center 111 Coorth Soil Contamination Eubank at a solv-Ex South Valley Livestock Auction 7715 Browner activity South Valley Superfund Site Woodware Southern Pueblo Agency Southwest Energy Distributors Broadway Steamatic Commercial Property Ster Tank Lines 4508 Browner activity Sun Valley Fruit Co 7110 2nd Sundelley Rechanical & Utility Co. San Deig Sundance Mechanical & Utility Co. San Deig	tion or CAR approved, or referred to an Cit outh Golf Course Landfill Albuqu ors NW Albuqu and Candelaria Albuqu enaul NE Albuqu roadway SE Albuqu ard and Broadway SE Albuqu h St Albuqu ay and Rio Bravo Albuqu oradway SE Albuqu d St NW Albuqu uewater NW Albuqu	City ² C Jquerque B Jquerque B	County ² Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo	Latitude ¹ 35.083232 35.116175 35.109218 35.08241 35.048847	Longitude ¹ -106.710796 -106.533236 -106.621611	Event Lab and Milling Co Disposed of residual ore and waste in landfill During pre-construciton for a gas station TPH soils were encountered in the parking lot run off depression. discovery of petroleum contaminated soil from UST shallow surface contamianted with petroleum	Discharge Date pre 1957 unknown	Action Taken data did not show contamination concern soil excavation and sampling refer to PSTB	closed closed referred	9/24/2008
Site Name ² Location Sigma Minerals Corp UNM Sou Smith's Fuel Center 111 Coor Soil Contamination Eubank a Solv-Ex 2121 Mer South Valley Livestock Auction 7715 Brox South Valley Superfund Site Woodwar Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Steer Tank Lines 4508 Brox Sundell Property 7500 Blue Sundell Property Sool Blue Sundance Mechanical & Utility Co. San Dieg	n Cit pouth Golf Course Landfill Albuqu pors NW Albuqu and Candelaria Albuqu enaul NE Albuqu roadway SE Albuqu ard and Broadway SE Albuqu ay and Rio Bravo Albuqu an Pedro NE Albuqu and St NW Albuqu albuqu Albuqu an Ario NE Albuqu and St NW Albuqu Albuqu Albuqu Albuqu Albuqu Albuqu Albuqu	City ² C Jquerque B Jquerque B	County ² Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo	Latitude ¹ 35.083232 35.116175 35.109218 35.08241 35.048847	Longitude ¹ -106.710796 -106.533236 -106.621611	Event Lab and Milling Co Disposed of residual ore and waste in landfill During pre-construciton for a gas station TPH soils were encountered in the parking lot run off depression. discovery of petroleum contaminated soil from UST shallow surface contamianted with petroleum	Discharge Date pre 1957 unknown	Action Taken data did not show contamination concern soil excavation and sampling refer to PSTB	closed closed referred	9/24/2008
Sigma Minerals Corp UNM Sou Sigma Minerals Corp UNM Sou Smith's Fuel Center 111 Coor Soil Contamination Eubank a Solv-Ex 2121 Mer South Valley Livestock Auction 7715 Brou South Valley Superfund Site Woodwar Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Stearnatic Commercial Property 3007 San Steer Tank Lines 4508 Bro Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	outh Golf Course Landfill Albuque ors NW Albuque and Candelaria Albuque enaul NE Albuque roadway SE Albuque ard and Broadway SE Albuque ay and Rio Bravo Albuque an Pedro NE Albuque roadway SE Albuque an Pedro NE Albuque ad St NW Albuque uewater NW Albuque	Aquerque B Aquerque B Aquerque B Aquerque B Aquerque B Aquerque B Aquerque B Aquerque B Aquerque B	Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo	35.083232 35.116175 35.109218 35.08241 35.048847	-106.710796 -106.533236 -106.621611	Lab and Milling Co Disposed of residual ore and waste in landfill During pre-construciton for a gas station TPH soils were encountered in the parking lot run off depression. discovery of petroleum contaminated soil from UST shallow surface contamianted with petroleum	pre 1957 unknown	data did not show contamination concern soil excavation and sampling refer to PSTB	closed closed referred	9/24/2008
Smith's Fuel Center 111 Coor Soil Contamination Eubank a Solv-Ex 2121 Mer South Valley Livestock Auction 7715 Brock South Valley Superfund Site Woodwar South Valley Superfund Site Woodwar South Valley Superfund Site Broadway Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Steer Tank Lines 4508 Brock Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	and Candelaria Albuqu enaul NE Albuqu roadway SE Albuqu ard and Broadway SE Albuqu h St Albuqu ay and Rio Bravo Albuqu an Pedro NE Albuqu oroadway SE Albuqu d St NW Albuqu	aquerque B aquerque B aquerque B aquerque B aquerque B aquerque B aquerque B aquerque B aquerque B	Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo	35.116175 35.109218 35.08241 35.048847	-106.710796 -106.533236 -106.621611	in landfill During pre-construciton for a gas station TPH soils were encountered in the parking lot run off depression. discovery of petroleum contaminated soil from UST shallow surface contamianted with petroleum	unknown	contamination concern soil excavation and sampling refer to PSTB	closed referred	
Soil Contamination Eubank at Solv-Ex South Valley Livestock Auction 7715 Brock 7715 Brock South Valley Superfund Site Woodwar South Valley Superfund Site Woodwar South Valley Superfund Site Broadway Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Steamatic Commercial Property 3007 San Steer Tank Lines 4508 Brock Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	and Candelaria Albuqu enaul NE Albuqu roadway SE Albuqu ard and Broadway SE Albuqu h St Albuqu ay and Rio Bravo Albuqu an Pedro NE Albuqu oradway SE Albuqu oradway SE Albuqu uewater NW Albuqu	Jquerque B Jquerque B Jquerque B Jquerque B Jquerque B Jquerque B Jquerque B Jquerque B	Bernalillo Bernalillo Bernalillo Bernalillo Bernalillo	35.116175 35.109218 35.08241 35.048847	-106.533236 -106.621611	encountered in the parking lot run off depression. discovery of petroleum contaminated soil from UST shallow surface contamianted with petroleum		sampling refer to PSTB	referred	
Solv-Ex 2121 Mer South Valley Livestock Auction 7715 Bro. South Valley Superfund Site Woodwar Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Stearnatic Commercial Property 3007 San Steer Tank Lines 4508 Bro. Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	enaul NE Albuqu roadway SE Albuqu ard and Broadway SE Albuqu h St Albuqu ay and Rio Bravo Albuqu an Pedro NE Albuqu roadway SE Albuqu dd St NW Albuqu	aquerque B aquerque B aquerque B aquerque B aquerque B aquerque B aquerque B	Bernalillo Bernalillo Bernalillo Bernalillo	35.109218 35.08241 35.048847	-106.621611	shallow surface contamianted with petroleum	pre 2/22/90			10/04/0005
South Valley Livestock Auction 7715 Bro. South Valley Superfund Site Woodwar Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Steamatic Commercial Property 3007 San Steer Tank Lines 4508 Bro. Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	roadway SE Albuqu ard and Broadway SE Albuqu h St Albuqu ay and Rio Bravo Albuqu an Pedro NE Albuqu roadway SE Albuqu dd St NW Albuqu uewater NW Albuqu	uquerque B uquerque B uquerque B uquerque B uquerque B uquerque B	Bernalillo Bernalillo Bernalillo	35.08241 35.048847	-100.021011			direct push soil investigation	closed	40/04/0005
South Valley Superfund Site Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Steamatic Commercial Property 3007 San Steer Tank Lines 4508 Bro Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	ard and Broadway SE Albuqu h St Albuqu ay and Rio Bravo Albuqu an Pedro NE Albuqu oradway SE Albuqu ind St NW Albuqu uewater NW Albuqu	Jquerque B Jquerque B Jquerque B Jquerque B Jquerque B	Bernalillo Bernalillo	35.048847	-106.67648					10/31/2005
Southern Pueblo Agency 1881 8th Southwest Energy Distributors Broadway Steamatic Commercial Property 3007 San Steer Tank Lines 4508 Bro Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodward	h St Albuqi ay and Rio Bravo Albuqi an Pedro NE Albuqi coadway SE Albuqi nd St NW Albuqi uewater NW Albuqi	uquerque B uquerque B uquerque B	Bernalillo			domestic well samples showed elevated nitrates.	unknown	well results showed nitrate above standards	inactive	
Steamatic Commercial Property 3007 San Steer Tank Lines 4508 Bro. Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Support Transportation Corridor Woodward	an Pedro NE Albuqu toadway SE Albuqu ad St NW Albuqu uewater NW Albuqu	uquerque B uquerque B	Bernalillo		-106 65/3/8	Chlorinated solvents found in City productions well Maintenance yard with AST and TCE in MWs	unknown 2000	referred to Superfund NOD sent 6-00	referred inactive	
Steer Tank Lines 4508 Bro. Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodward	roadway SE Albuqu ad St NW Albuqu uewater NW Albuqu	uquerque B		35.08241	-106.67648	gallons of diesel	4/1/1997	soil excavation	closed	5/15/1997
Steer Tank Lines 4508 Bro. Sun Valley Fruit Co 7110 2nd Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodward	roadway SE Albuqu nd St NW Albuqu uewater NW Albuqu	uquerque B	Bernalillo	35.116479		PCE discovered in soils on-site	pre 1996	small SVES operation.	closed	7/14/1996
Sunbell Property 7500 Blue Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor Woodwar	uewater NW Albuqu	Jquerque B	Bernalillo	35.08241		diesel contaminated soil	pre 99	soil excavation	closed	1/22/2001
Sundance Mechanical & Utility Co. San Dieg Sunport Transportation Corridor		100 100	Bernalillo	35.134801		Phase 2 ESA showed VOCs in soil	pre 8/30/06	soil excavation	closed	9/22/2006
Sunport Transportation Corridor	ego and San Mateo Albuqu	uquerque B	Bernalillo	35.085384	-106.717135	jewelry and plating shop showed metals and solvents in vadose zone	pre 1990	soil venting with SVES and GW monitoring	closed	6/18/1998
		uquerque B	Bernalillo	35.193194		truck accident lost 300 gal of diesel	4/21/2000	soil excavation	closed	8/8/2000
	ard and I-25 Albuqu	uquerque B	Bernalillo	35.08241	-106.67648	study of South Valley Superfund site and Chevron Bulk Terminal wells to be abandoned if new interstate exit is built.	NA	study still in progress		
Sunshine Buick 2801 Car		uquerque B	Bernalillo	35.112989	-106.60425	hydraulic lift contaminated soil	pre 6/22/1995	soil excavation and hydraulic lift removal	closed	6/20/1995
Sunshine Buick - Expertech 5501 McL Mateo	cLeoad and 5200 San Albuqu	uquerque B	Bernalillo	35.13865	-106.584151	hydraulic lift contaminated soil	pre 4/28/99	soil excavation and capping	closed	5/1/1999 and 5/23/14
Sunway Strip - Davis Cleaners 2906 Jua	ian Tabo NE Albuqu	uquerque B	Bernalillo	35.115037	-106.515615	Phase 2 showed chlorinated solvents in soil and soil vapor	pre 6/26/2008	additional analysis showed no threat to ground water	closed	6/9/2012
Swift Transportation I40- and I	d Exit 158 Albuqu	uquerque B	Bernalillo	35.08241	-106.67648	truck accident lost 100 gal of diesel	8/27/98	soil excavation	closed	6/20/1998
Trans World Airlines Albq Airp	rport Albuqu	uquerque B	Bernalillo	35.08241	-106.67648	site assessments showed jet fuel in soil	1988	soil assessment and pipeline integrity showed no impacts to GW.	closed	6/13/1988
Treeland Nursery 308 Osur	una NE Albuqu	uquerque B	Bernalillo	35.08241	-106.67648	during Phase 2 contaminated soil was discovered	pre 97	soil excavation and no GW stds exceeded in MWs	closed	12/1/1998
Truly Nolan 510 Cano	ndelaria NE Albuqu	uquerque B	Bernalillo	35.116555	-106.634497	pesticide soil contamination discovered.	unknown	soil excavation and sampling	closed	3/15/2009
Twin Mountain Construction Juan Tab	abo and I-40 Albuqu	uquerque B	Bernalillo	35.076628	-106.515142	50 gal of hydraulic oil spill	7/9/1997	soil excavation	closed	9/26/1997
	r Track: Paseo del Norte, Albuqu	uquerque B	Bernalillo	35.08241	-106.67648	site assessment showed some metals and TPH in	7/1/1999	soil excavation	closed	6/21/1999
United Road 2501 United	a, Edith		Bernalillo	35.111452		Surface Solis	8/29/2016			11/23/2016
						40 gallon of diesel spilled from ruptured saddle tank		Sorbent applied to asphalt soil excavation prior to	closed	
UNM football stadium Stadium a	n and University Albuqu	uquerque B	Bernalillo	35.06847	-106.630898	gas spills from lawn equipment	pre 2001	building new stands	closed	2/15/2001
UNM Hospital Lomas an	and Campus Albuqu	uquerque B	Bernalillo	35.08241		diesel supply line damaged and 120 gal spilled	1/14/1999	soil excavation	closed	2/26/1999
UNM Hospital Chill Water Tank UNMH	Albuqu	uquerque B	Bernalillo			chill water tank showed leaks and loss of Mn based coolant	pre 1995	GW monitoring	closed	6/18/1998
UNM South Golf Course University	ity and I-25 Albuqu	uquerque B	Bernalillo	35.08241		well anatysis to determine potential impacts from Persons Generating Station	NA	analytical results were below laboratory detection limits	closed	9/15/1994
	dg, near Martin Luther vd, Redondo W. Dr.	uquerque B	Bernalillo			during construction hydraulic oil spill from equipment	pre 11/06	soil excavation	closed	2/14/2007
US Forest Service 12th St. Yard 12th St Yard		uquerque B	Bernalillo	35.08241	-106.67648	phenols in FS well pre 1990	pre 1990	sampled in 97 and ND	closed	7/22/1997
	oadway NE Albuqu	uquerque B	Bernalillo	35.072184	-106.645711	spill of 50 gal of diesel	7/14/2000	soil excavation	closed	8/25/2000
			Bernalillo	35.072184	-106 645711	During excavation for a new building footings, TPH	unknown	soil excavation	closed	9/23/2008
			Bernalillo	35.098178		contaminated soil was discovered. 9 yards of petroleum contaminated soils	pre 1993	soil excavation	closed	9/13/1993
	-4, Vista Del Norte, Atlas		Bernalillo	33.090178		discovery of petroleum contaminated soil	pre 1993 pre 4/26/06	soil excavation	closed	5/12/2006
		uquerque B	Bernalillo	35.076393	-106.72811	Petroleum tank removal	8/16/1991	tank removal	referred	
			Bernalillo	35.08241	-106.67648	discovery of TPH-tar disposal trenches	1980s	soil excavation	closed	11/9/2010
Western Refining 3209 Broa	roadway SE Albuqu	uquerque B	Bernalillo	35.114345		pin hole in comingle pipeline release discovered in 3/07	unknown	soil excavation	closed	12/14/2012
Western Refining (former Chevron) Asphalt Plant						at bulk fuel terminal		SVES, soil excavation,		

						ter Quality Bureau - Closed/Inactive S	tate Clean Up S	ites		
2	may vary. Coordinates may have be	en determined usi	ng google ea	rth, but other less	accurate methods	may have been used .				
	y, then alphabetically by Site Name. urther action or CAR approved, or re	ferred to another	program for (processing such as	SOS/CERCLA, HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000) may be archived or tra	ansferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Western Truck School	424 Kinley Ave NE	Albuquerque	Bernalillo	35.096732	-106.641183	hydrocarbon soils discovered	pre 91	soil excavation	closed	7/31/1997
Windmill Ranch	6400 Coors Blvd	Albuquerque	Bernalillo	35.163252	-106.67727	diesel contaminated soil	pre 97	passive SVES, GW monitoring	closed	5/4/1999
Wittler Automotive	121 Elizabeth NE	Albuquerque	Bernalillo	35.071307	-106.524898	Phase 2 ESA showed TPH in shallow soils	unknown	Soil analytical results showed no further corrective action needed	closed	8/23/2013
Woodward and Second, Groendyke Accident	Woodward and Second	Albuquerque	Bernalillo	35.049505	-106.656767	truck accident spilt 120 gal of diesel	4/13/1999	soil excavation	closed	11/12/1999
Zangara Dodge	8528 Lomas NE	Albuquerque	Bernalillo			Phase I/ Phase II ESA conducted	Before 1996	Unknown	inactive	unknown
Advance Manufacturing	700 N Hill Rd	Bernalillo	Bernalillo	35.332468	-106.523316	cutting oil discharges and presence of solvents	1991	soil excavation and GW monitoring	closed	9/6/2000
Ink Spot		Bernalillo	Bernalillo			lined wastewater pond was removed	pre 1997	sampling below liner showed clean soils	closed	8/7/1997
Carnue-Dead Man's Curve (Hertlzer well)	37 Atencio Rd.	Carnuel	Bernalillo			gas, MTBE, nitroaromatics, NO3	pre1988	CERCLA/PSTB investigation	referred	
Sandia Dye and Cartridge/Herzler	37 Atencio Rd.	Carnuel	Bernalillo	35.062357	-106.455818	petroleum and arms wastes may have been introduced	pre 1995	soil and site assessment	closed	2/5/1997
Corrales Apple Orchard	Corrales Rd/ Camino de Lucia	Corrales	Bernalillo	35.002337		in a domestic well Pesticide Application	pre-1996	CAR approval	closed	11/23/1997
	Condies Ru/ Camino de Lucia	Conales	Demailio			resticide Application	pre-1996		cioseu	11/23/1996
Cottonwood Die Off, Margaret Armstrong	209 Villa Oriada	Corrales	Bernalillo	35.239335	-106.622588	GW investigation to determine if GW quality was impacting cotonwood die off	NA	sampling of 4 GW grab samples and domestic well. No GW impacts associated with tree die off	closed	7/19/2007
Sanchez Well	2138 Raymac Rd	Los Padillas	Bernalillo	34.166233	-106.026069	Sampling, private well	9/26/1983	results showed no impact	closed	6/5/1983
Placitas Pipeline Spill/Cedar Creek	Cedar Creek Subdivision	Placitas	Bernalillo			Spill, jet fuel	12/1/1999	CAR approval, trans to SWQB	transferred	7/7/2002
Former Woody's Truck Stop	Sedillo Hill	Sedillo	Bernalillo	35.092049		petroleum hydrocarbon spill AST	1986	CAR	closed	6/8/1986
Waste Management	Hwy 217, 3 mile S of Hwy 66	Sedillo	Bernalillo			truck accident caused 160 gal diesel spill	11/2/1998	soil excavation soil borings, soil, domestic	closed	12/14/1998
Bernalillo County E. Mountain. Transfer Station	I-40 and Zuzaks Exit	Tijeras	Bernalillo	35.089549	-106.372506	TPH soil contamination	Apr-91	well samples collected. All	closed	7/19/1999
Don Ward & Co. of New Mexico	Tiejeras Canyon, Montoya School/Ideal Cement	Tijeras	Bernalillo			Spill, AST leak	1988	sampled, school supply	inactive	6/11/1988
Joe's Trucking	SR S. 14, 1/4 mile S of Buckboard Rd	Tijeras	Bernalillo	35.089549	-106.372506	370 gal of diesel spilt when AST tipped over	5/31/1994	soil excavation	closed	6/30/1994
Texaco Bulk Plant (Former)	3209 Broadway SW, Albuquerque, NM	Albuquerque	Bernillo	35.04603333	-106.64811944	diesel, gasoline - depth to water 20-30 feet bgs	1995	Soil Vapor Extraction System (closed), ground water pump and treat completed. Compliance monitoring completed. Agreement terminated with NMED and Chevron	completed closed	3/23/2016
NMDOT Datil	US 60 & NM 12	Datil	Catron	34.1449	-107.84289	PCE found in area monitor wells below WQCC standard	unknown	Nearby NMDOT facilities didn't use PCE. PSTB is investigating other facilities in area.	closed	4/11/2006
USFS fuel spill	Reserve Administrative Site	Reserve	Catron	33.708918	-108.761348	mobile AST with fuel for perscribed burns leaked	12/1/94	soil excavation	closed	2/1/1995
BNSF Chisum Siding	RR mil 119.5, 4.6 mi NW of Dexter	Dexter	Chaves	33.195659	-104.366833	locomotive tank leak of 2000 gal diesel	12/25/1998	soil excavation	closed	7/19/1999
Robinson Custom Harvesting	Derby Road near Dexter	Dexter	Chaves			washing of trucks and discharge of manure, TPH to field and road	Jul-93	DP required letter sent 5- 26-94	referred to permitting	unknown
Helena Chemical Co.	504 Lake Arthur Hwy	Lake Arthur	Chaves	33.000835	-104.363886	windshield washer and herbicide sprayed on soil		soil excavation and sampling	closed	6/15/2009
ABC Propane	813 N. Virginia	Roswell	Chaves	33.401215	-104.521064	bulk plant investigation	none	No tanks over 55K gals.	closed	Feb. 2006
Denios Cleaners	514 W. 2nd St.	Roswell	Chaves	33.394021	-104.529985	PCE in ground water.	unknown	Referred to Superfund Oversight Section.	referred	6/26/2015
Great SW Aviation	100 Southwest Way - Airport	Roswell	Chaves			bulk plant investigation	none	No tanks over 55K gals.	closed	Feb. 2006
Merlo Well	Brown Rd West of Roswell, 4718 W. 2nd St.	Roswell	Chaves	33.394133	-104.584149	BTEX reportedly found in well	4/4/1977	if new data shows BTEX is present will be referred to PSTB	inactive	
New Mexico Machinery	2801 SE Main	Roswell	Chaves	33.343611	-104.5075	AST leaked diesel	discovered 7/8/15	soil excavation	closed	10/20/2015
New Products and Development Company	4301 SE Main St.	Roswell	Chaves	33.361961	-104.512111			closed	closed	7/1/1990
Nova Bus	46 E. Martin	Roswell	Chaves	33.31489		50 gal of diesel spill from overfilling truck	5/30/2000	soil excavation	closed	8/4/2000
PCE Roswell, Bell Texaco/Union Plaza Conoco		Roswell	Chaves			suspected false positive or cross-contamination of consultant's sample from 411 N. Kansas, Roswell		confirmation negative	closed	September '05 sampling event
Richard Distributing Co.	1500 N Garden Ave	Roswell	Chaves	33.408763		old small AST with soil contamination	pre 88	GW monitoring	closed	3/6/1998
Roswell Central	Downtown Roswell	Roswell	Chaves	33.394825	-104.522765	PCE in ground water	unknown	Monitoring. Referred to Superfund Oversight Section.	referred	6/26/2015

	New N	lexico Envii	ronment	Department -	Ground Wa	ter Quality Bureau - Closed/Inactive S	tate Clean Up S	Sites		
	may vary. Coordinates may have bee	n determined usi	ing google ear	th, but other less a	ccurate methods	may have been used .				
2	y, then alphabetically by Site Name. uther action or CAB approved, or ref	erred to another	program for	processing such as	SOS/CERCIA HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 200	0 may be archived or t	ransferred with the referral		
	Location	City ²		Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Site Name ²	1		County ²	1	Longitude	Jet fuel spill from aircraft accident. Soil contamination of	Discharge Date	microblaze application and	1	1
Roswell International Air Center	Mathis and Gail Harris St.	Roswell	Chaves	33.310979		80x100 It		MNA of soil Solid Waste Bureau	closed	2/20/2014
Roswell Landfill	3006 W. Brasher	Roswell	Chaves	33.350117	-104.572143	PCE/TCE measured in landfill monitoring wells	unknown	jurisdiction Tresspassing plume.	referred	2/10/2010
Roswell Sonic	1209 W. 2nd St.	Roswell	Chaves	33.394671		PCE in ground water.	unknown	Referred to Superfund Oversight Section.	referred	6/26/2015
Southwest Radiographs Steere Tank Lines	519 E. Chisum St S. Main and Hobson	Roswell Roswell	Chaves Chaves	33.376351 33.321365		x-ray machine and spill of AgNO3 tank truck spill lost 2500 gal of JP-8	pre 97 7/7/1998	soil excavation soil excavation	closed closed	3/30/1998 7/27/1998
Transportation Manufacturing Corp	T11S, R24E, S32 and 33	Roswell	Chaves			phase 2 showed low levels of TPH in soil	pre 95	unknown	inactive	
Ramah Ranch	El Moro, 35.102076;-108.275521	El Moro	Cibola			discovery of solid rocket fuel on ranch from innerant DOD rocket, perchlorate	unknown	site assessment and referral to HWB	referred	
BNSF Grants (formerly Ramsey Oil)	210 W. Santa Fe Avenue	Grants	Cibola	35.149859	-107.84895	Diesel, BTEX in ground water.	pre 2002	Enhanced in-situ bioremediation - under Voluntary Remediation Program.	referred	1/17/2002
Dwight Small	1512 Ice Caves Road	Grants	Cibola	35.145944	-107.87601	improper solid waste disposal suspected potential ground water contaminant releases	pre 2010	GWQB sampled soil and found minimal detections. SWB jurisdictin	referred	
USFS Lobo Canyon herbicide	Cibola FS, 4 miles new of Grants	Grants	Cibola			30 drums buried in 70s	pre 70	soil removal	closed	4/21/2004
WW Construction Inc.	Hwy 125 mile 4.5	McCarty	Cibola	05 400 400		truck accident that spilled 250 gal of diesel	8/2/2000	soil excavation	closed	8/25/2000
-	619 W 66th	Milan	Cibola	35.189406		old UST sump runoff from service station is trespassing on neighbor's	pre5/98	samples showed clean SWB required stormwater	closed	7/1/1999
Ever Ready Oil - Milan	817 W. Hwy 66	Milan	Cibola	35.189406	-107.892015	property	pre 2008	control	referred	
TA - Petro Truck Stop #13	I-40 and Horizon Blvd	Milan	Cibola	35.182408		diesel spill at AST truck stop	1996	soil excavation	closed	6/18/1996
Perkins Well, Eagle Nest	32 County Road B11	Eagle Nest	Colfax	36.551956		domestic well sample showed low levels of MTBE. Unknown source	unknown	monitoring	inactive	
Duran Oil Co.	700 Woodrow Ave	Raton	Colfax	36.872509	-104.447263	small AST farm with overfill of 3500 gal of diesel	10/15/1997	soil excavation	closed	6/20/1997
Kaiser Steel ASTs	York Canyon Mine Complex, Box 100 Raton, 87740	Raton	Colfax			unauthorized discharge of diesel		NOD sent	closed	9/1/1998
Knight Transportation	I-25 mile 453	Raton	Colfax	36.882972		truck accident caused 100 gal diesel spill	8/4/2008	soil excavation	closed	12/15/2008
Prices Mobile Home Park Raton ASTs	1135 Price St I-25 and 2nd exit heading N	Raton Raton	Colfax Colfax	36.88633		report of tenant spraying oil on ground AST spills	2/8/2011 10/15/1997	stopped practice soil excavation	closed closed	2/28/2011 6/19/1998
Raton Car Crushing	637 Lincoln	Raton	Colfax	36.909523	-104 431644	report of car and refrigerator crushing activities and	unknown	investigation and collaborated with Raton code enforcement shown	closed	12/1/2013
						Ū		no threat to ground water		
	4th Ave and Cedar St.	Raton	Colfax	36.897428		400 of emulsion oil was buried on yard	pre 1993	soil excavation	closed	post 1994
Texaco Bulk Plant	945 2nd St.	Raton	Colfax	36.913038		bulk terminal investigation showed low levels of fuel	pre 1992	subsurface investigation	closed	5/4/1992
Total Truck Stop Jaritas Ranch	Hwy 87 and I-25 ~12mi E of Springer on Hwy 56	Raton Springer	Colfax Colfax			80 gal of diesel spill from faulty equipment livestock dipping vat soil contamination	11/11/1996 pre 7/5/05	soil excavation soil excavation	closed closed	1/3/1997 1/10/2006
Springer - Esquibel Fuel Release	SR 21 and Frontage Rd.	Springer	Colfax	36.366014		Report of fuel release from an unregistered UST	1996	installation of trenches, soil sampling, and passive vent removal. Results		11/4/2014
Texaco Bulk Plant	Colbert Ave and 11th St	Springer	Colfax	36.366014	-104.591194	Phase 2 ESA showed VOCs in soil and in one MW	pre 1992	showed no contamination GWQB responded saying that prioritization ranking was low would not be assigned	inactive	
Atrazine in Domestic well	1672 Hwy 60/84, 1725 CR 11	Clovis	Curry	34.419211	-103.225374	report of Atrazine spill from farmer	pre 2001	sampling of wells were ND for Atrazine and no evidence of discharge	closed	12/18/2001
Barnett and Sons Paving Contractor	2405 W. 7th	Clovis	Curry	34.404644	-103.234562	report of used oil, pesticides, drum burial near south pit	pre 99	inspection revealed no evidence of discharge.	closed	10/7/1999
Clovis pipeline terminal	34° 22' 52.68"N, 103° 12' 30.36"W	Clovis	Curry	34.3814	-103.2083	undocumented release(s)	unknown	none	closed	9/23/2008
Clovis POTW	SR 318 and Hwy 84	Clovis	Curry	34.453936		GW contaminated from POTW and Landfill DP-79	unknown	Referred to SWB and PPS		
Cook's Truck Stop	East of Clovis	Clovis	Curry			letter from Dist office saying NO3 levels in truck stop well is improving following sewage line extension	unknown	monitoring	closed	
Koch Pipeline/ Clovis	1/2-mi. S of W. Brady and S.Thornton	Clovis	Curry			former bulk terminal showed petroleum hydrocarbons in soil	unknown	soil assessment to depth	closed	5/1/2009
Melugin Spill	East 7th St and Schepps Blvd	Clovis	Curry	34.404903		Discovery of leaking drums, possible pesticides	unknown	soil excavation	closed	7/17/1995
Payless Rental	620 East 21st St.	Clovis	Curry	34.41937	-103.198646	report of small used oil spill with TPH at 475	6/6/2000	soil excavation	closed	6/27/2000
	Eco Tank Services, Box 27116	Clovis	Curry			jet fuel spill soil contamination below dairy lust site. Not PSTB	pre 1995	soil excavation soil sampling showed	closed	12/5/1995
Rajen Dairy LUST site	Rt1 Box 264b	Clovis	Curry	34.393324	-103.288349	related	pre 1992	contamination	referred	1

1						ater Quality Bureau - Closed/Inactive S	tate Clean Up Si	tes		
2	may vary. Coordinates may have b		ing google ea	rth, but other less	accurate methods	may have been used .				
2	y, then alphabetically by Site Nam Irther action or CAR approved, or I		r program for	processing such as	SOS/CERCLA, HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 200	0 may be archived or tra	nsferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude 1	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Southwestern Public Service Center	Clovis Yard	Clovis	Curry			soil vapor survey looking for chlorinated solvents	pre 1994	soil vapor results and inventory showed no contamination and not related to low level solvents found in municipal well	closed	6/16/1998
Southwestern Public Service Center	Norris St, T2N, R36E,	Clovis	Curry	34.453936	-103.198495	low hits of PCE in supply wells lead investigation to SPS Center and Clovis Landfill	pre 1988	soil vapor survey and site inventory showed no solvents	closed	3/13/1995
Xcel Energy right-of-way	913 Cypress St.	Clovis	Curry	34.407139	-103.226072	trespass dumping of used motor oil	on-going by trespasser	soil excavation and posted "no dumping" signs	closed	in process
Zia Spraying Services Cannon AFB	Clovis Airport Melrose Bombing	Clovis Melrose	Curry Curry	34.453936 34.431081		long term pesticide spills referred to ROS in 1995 275 heating oil UST leaked	1980s to possibly 1995 pre 11/94	unknown	inactive inactive	
United Petroleum Transport	50 yrd N of Hwy 70 on Hwy 60	Texico	Curry			5000 diesel spill from truck accident	9/20/06	soil excavation and land farming	closed	12/1/2006
Village of Texico - Well KKR	Hamlin and College St.	Texico	Curry	34.389858	-103.054028	discovery of carbon tetrachloride in new supply well at conc. ~7 ppb	unknown	redevelop well	closed	August-91
American Freightways	US 60 and 6th st	Fort Sumner	De Baca	34.474712	-104.258786	truck accident 400 gal of diesel	Oct-00	soil excavation	closed	12/20/2000
Fort Sumner Truck Stop	US 84 and St. Rt 212	Fort Sumner	De Baca	34.477593	-104.236148	small AST Truck stop with soil and GW contamination	pre 93	site assessment and referral to PSTB	referred	
Fort Sumner Truck Stop	West Fort Sumner Ave		De Baca			orphaned AST	pre 1985	referred to PSTB 9-02	referred	6/24/1997
El Paso Elec. Co.	108 W. Afton	La Mesa	Dona Ana	32.082544		transformer oil	1/3/2017	soil excavation	closed	1/18/2017
El Paso Elec. Co.	3901 Watson Place	Las Cruces	Dona Ana	32.265178	-106.769028	transformer oil	1/12/2017	soil excavation	closed	1/27/2017
Southwest Envirotech	DP-1355	Afton siding	Doña Ana			spill of grease trap waste (2000 gal) from vac truck missing outlet cap	5/21/07	road grading	closed	
Anthony Water and Sanitation District WWTP	4th Street	Anthony	Doña Ana	32.02185900	-106.60025700	nitrate, TDS	NA	Site is regulated under an active DP.	Referred to PPS	4/8/2016
El Paso Electric Co.	1130 Dairy Farm Rd.	Anthony	Doña Ana	32.012901	-106.606193	transformer oil	1/17/2011	soil excavation	closed	6/30/2011
El Paso Electric Co.	1310 N. 4th St.	Anthony	Doña Ana			transformer oil	7/8/2014	soil excavation	closed	8/5/14
El Paso Electric Co. El Paso Electric Co.	147 Shrode 4895 N. Vinton	Anthony Anthony	Doña Ana Doña Ana	32.012901 32.012901		transformer oil transformer oil spill	6/11/2010 6/24/08	soil excavation soil excavation	closed closed	6/30/2011 6/30/2011
El Paso Electric Co.	4901 Vinton	Anthony	Doña Ana	32.012901		transformer oil	7/5/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	800 W. Washington	Anthony	Doña Ana	32.012901		hydraulic fuel & transformer oil	9/5/2013	soil excavation	closed	9/30/13
El Paso Electric Co.	Hwy. 213 & Hwy. 404	Anthony	Doña Ana			transformer oil	11/2/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	5205 Hwy. 28	Anthony	Doña Ana			transformer oil	5/26/2016	soil excavation	closed	7/8/2016
El Paso Electric Co.	1590 N. 4th St.	Anthony	Doña Ana	32.0225		capacitor oil	7/2/2015	soil excavation	closed	4/15/2016
El Paso Electric Co. El Paso Electric Co.	724 N. 4th St. 1010 Leifeste	Anthony Anthony	Doña Ana Doña Ana	32.006667	106.6025	transformer oil transformer oil	8/6/2015 10/6/2016	soil excavation soil excavation	closed closed	4/15/2016 10/25/2016
El Paso Electric Co.	1415 Anthony Road	Anthony	Doña Ana	32.019592°	-106 603446°	2 gal transformer oil spill	6/21/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	1590 N. 4 th Street	Anthony	Doña Ana	32.024111°		30 gal. Transformer/Bushing oil spill	1/31/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	1590 N. 4th Street	Anthony	Doña Ana	32.024111°		100 gal. Regulator oil spill	2/3/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	1590 N. 4th Street	Anthony	Doña Ana	32.024111°		11 gal. Capacitor oil spill	2/14/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	400 N. Anthony Drive	Anthony	Doña Ana	32.003589°	-106.606087°	2 gal. Hydraulic oil spill	5/23/2017	soil excavation	closed	7/7/2017
Santa Fe Pacific Pipeline Partners		Anthony	Doña Ana			500 gal of diesel spilt during pipeline relocation	7/28/1992	soil excavation	closed	11/1/1992
Soto Oil, Sharp Oil		Anthony	Doña Ana			phase 2 showed low levels of TPH in soil	3/4/1999	soil sampling	closed	5/4/1999
United Petroleum Transport McAnally Egg Facility	I-10 and Hwy. 404 415 San Benito Rd	Anthony Berino	Doña Ana Doña Ana	32.02459 32.073485°	-106.588781 -106.619825°	truck accident lost 7,300 gals. of diesel Egg farm operation from '70s to 2011, impacted gw with	7/11/04 unknown	soil excavation assessment	closed transferred to	12/21/2004 2/12/2016
Salopek Farms	1950 W. Berino Blvd.	Berino	Doña Ana	32.068064	-106.622724	nitrate, chloride, TDS nitrate	unknown	soil excavation and sampling; final report not	VRP	1/5/13
El Paso Electric Co.	10801 Hwy. 28	Chamberino	Doña Ana	32.055005		transformer oil	6/23/2010	yet submitted soil excavation	closed	6/30/2011
El Paso Electric Co.	644 Hermosa	Chaparral	Doña Ana	32.016565		transformer oil	7/25/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	654 Paseo Real	Chaparral	Doña Ana	32.023247		transformer oil	2/12/2013	soil excavation	closed	3/1/13
El Paso Electric Co.	656 Luna Azul	Chaparral	Doña Ana	32.030935		hydraulic fluid leak from EPEC truck	5/11/05	soil excavation	closed	09/23/05
El Paso Electric Co.	753 Broadmoor	Chaparral	Doña Ana	32.008464		transformer oil spill	12/5/05	soil excavation	closed	1/27/2006
El Paso Electric Co.	768 Nogales 804 Jennifer Nicole	Chaparral	Doña Ana	32.03213		transformer oil	1/6/2014	soil excavation	closed	1/30/14
El Paso Electric Co. El Paso Electric Co.	511 NM Hwy. 213	Chaparral Chaparral	Doña Ana Doña Ana	32.043056 32.007379°		transformer oil 15 gal. Transformer oil spill	1/13/2016 3/28/2017	soil excavation soil excavation	closed closed	2/15/2016 7/7/2017
DAC Health Center	5595 Elks Dr.	Doña Ana	Doña Ana	32.394934	-106.817516		9/2/04	soil excavation	closed	10/27/2006
Doña Ana Mutual Water and Sewer	5041 El Camino Real	Doña Ana	Doña Ana	32.394934		sewer main rupture	12/15/2007	soil removal	closed	6/18/2008
Doña Ana Mutual Water and Sewer	750-ft downstream of Barela	Doña Ana	Doña Ana			sewer main rupture	9/11/2007	soil removal	closed	11/9/2007
Cooperative Assoc.	lateral diversion, E side of canal						3/11/2007			11/0/2007

	New I	Mexico Envi	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive S	tate Clean Up S	lites		
¹ Latitude and Longitude accuracy	may vary. Coordinates may have be	en determined us	ing google ea	rth, but other less	accurate methods	may have been used .				
2	ty, then alphabetically by Site Name									
³ Status may consist of closed/no f	urther action or CAR approved, or re	ferred to another	program for	processing such as	SOS/CERCLA, HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may be archived or tr	ansferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Qwest	Doña Ana School Rd and El Camino Real intersection	Doña Ana	Doña Ana			disposal of drilling mud in EBID right-of-way	2/14/07	Excavation contractor returned to clean-up neighbor's yard	closed	2/20/2007
SLO trespass dumping	32.431671; -106.706373	East Mesa	Doña Ana	32.431671	-106.706373	drums of waste oil released near city well	undetermined	City of LC hired Terracon, SLO performing CA through Rhino	closed	
SLO trespass dumping	32.431671; -106.706373	East Mesa	Doña Ana	32.431671	-106.706373	drums of waste oil released near city well	undetermined	City of LC hired Terracon, SLO performing CA through Rhino	closed	
Fort Bliss, Doña Ana Range Camp El Paso Electric Co.	Fort Bliss 250 Nightwatchers	Fort Bliss Garfield	Doña Ana Doña Ana	34.166233 32.757087		hydraulic lift leak in 1995 transformer oil	pre 1995 8/5/2011	soil excavation soil excavation	closed closed	6/17/1995 8/23/2011
El Paso Electric Co.	2617 Loma Parda	Garfield	Doña Ana	32.75744	-107.264851	transformer oil	8/5/2011	soil excavation	closed	8/23/2011
Crop Production Services	1300 B.B. Romig	Hatch	Doña Ana	32.6786	-107.2001	fertilizers & diesel fuel	4/7/2009	soil excavation	closed	1/24/14
El Paso Electric Co.	56753 W. Barker	Hatch	Doña Ana	32.650378	-107.198495	transformer oil spill	4/4/05	soil excavation	closed	09/23/05
El Paso Electric Co.	607 Franklin	Hatch	Doña Ana	32.673563		transformer oil spill	7/1/2003	soil excavation	closed	2/22/2005
El Paso Electric Co.	700 Franklin	Hatch	Doña Ana	32.674593		transformer oil	7/10/2000	soil excavation	closed	11/15/2000
El Paso Electric Co.	SS Packing Plant	Hatch	Doña Ana	32.650378	-107.198495	transformer oil	8/16/2001	soil excavation	closed	9/17/2001
Milagro Colonia	near Hatch	Hatch	Doña Ana	32.650378	-107.198495	leachfield overflow	continuous	sampled leachate for VOCs, major ions, nitrate, TKN, ammonia, metals	referred to EHD	
Pete Kaiser Well	Hatch Elementary School	Hatch	Doña Ana	32.650378	-107,198495	report of LNAPL in well	2/22/2002	well sample showed clean	closed	2/2/2007
Placitas Gravel Pit	1.5 miles W of Hatch	Hatch	Doña Ana	02.000010	1011100100	diesel	unknown	soil excavation	closed	11/13/1996
Ritter Distributing Bulk Plant		Hatch	Doña Ana			report of diesel cont. soil	before 7-95	unknown	inactive	11/10/1000
El Paso Electric Co.	1229 Co. Road	La Mesa	Doña Ana	32.124785		hydraulic fluid leak from EPEC truck	12/21/04	soil excavation	closed	1/27/2006
El Paso Electric Co.	15795 Hwy. 28	La Mesa	Doña Ana	32.115567	-106.703215		8/5/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	15795 Hwy. 28	La Mesa	Doña Ana	32.115567	-106.703215		8/5/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	190 Victoria	La Mesa	Doña Ana	32.136111		transformer oil	11/16/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	Westside Canal Road & Gavilan Avenue	La Mesa	Doña Ana	32.139617°		8 gal transformer oil spill	1/8/2018	soil excavation	closed	5/23/2018
El Paso Electric Co.	108 W. Afton Road	La Mesa	Doña Ana	32.082636°	-106 684458°	13 gal. Transformer oil spill	1/3/2017	soil excavation	closed	7/7/2017
Lane Property	1285 W. San Miguel	La Mesa	Doña Ana	32.124785	-106.708078		10/2/2009	soil excavation Inspected 1M gal. tank	closed	8/30/2011
PNM Afton Gen. Station	10100 W. Afton Road	La Mesa	Doña Ana	32.124785		bulk plant investigation	none	and piping. No leaks observed.	closed	3/6/2006
El Paso Electric Co. El Paso Electric Co.	1443 S. Alvarez 1640 County Rd.	La Union La Union	Doña Ana Doña Ana	31.931512		transformer oil transformer oil	6/5/2010 8/20/2014	soil excavation soil excavation	closed closed	6/30/2011 9/19/14
abandoned truckstop	2500 W. Picacho Ave.	Las Cruces	Doña Ana	32.310786	-106.811265	historic spills of diesel fuel dispensed from ASTs at old truck stop	pre-1988	soil excavation	closed	7/25/2007
Agri-Tech	1730 W. Picacho	Las Cruces	Doña Ana	32.312042	-106.801821	motor oil spill discovered by neighbor	10/6/05	soil excavation	closed	8/11/2006
Alameda Laundry & Dry Cleaners	Alameda & Main Street	Las Cruces	Doña Ana	32.30347800	-106.77799800	PCE in soil gas in vicinity needs next Tier of Assessment	unknown	soil vapor	transferred to Superfund	4/21/2016
All About Kars	1695 Pichaco	Las Cruces	Doña Ana			PSTB site where P&T through zeolite was proposed	unknown	referred to PSTB	referred	
Amador Auto Body and Paint shop		Las Cruces	Doña Ana	32.308722	-106.770454	HWB concern over stains in bldg	pre 1992	unknown	referred to HWB	
Antix Cabinets	717 W. Organ Ave.	Las Cruces	Doña Ana			overflow of waste barrel	Sep-08	soil removal	closed	pending
B&H Mechanical	3701 Doña Ana Rd.	Las Cruces	Doña Ana	32.334762	-106.795368	mineral spirit-based oil	10/15/2010	soil excavation	closed	9/7/12
Border International	1670 S. Valley	Las Cruces	Doña Ana			petroleum	5/28/2008	soil excavation, MW sampling	closed	5/9/14
Cabrera Automotive		Las Cruces	Doña Ana			soil contamination	2003	site visit and soil excavation	closed	6/25/2004
Chevron/Jornada Range pipeline spill	7 miles NW of Las Cruces	Las Cruces	Doña Ana			diesel	unknown	soil excavation	inactive	
Comet Cleaners	2001 E. Lohman	Las Cruces	Doña Ana	32.311074	-106.756651	PCE	pre-2002	soil borings, samples taken	closed	9/21/12
DAC Fleet Maintenance Yard, Las Cruces	2025 E. Griggs	Las Cruces	Doña Ana	32.314312	-106.760527	multiple areas of soil contamination	unknown	soil excavation	closed	9/7/2012
E. Lohman Landfill	E. Lohman Ave & Roadrunner Parkway	Las Cruces	Doña Ana	32.21313889		No Further Action	none	No further Action	Closed	5/9/2016
El Paso Electric Co.	4807 El Camino Real	Las Cruces	Doña Ana			transformer oil	4/29/2016	soil excavation	closed	7/8/2016
El Paso Electric Co.	1053 Hayner	Las Cruces	Doña Ana	32.308615		transformer oil	7/29/2003	soil excavation	closed	9/23/2003
El Paso Electric Co.	110 Onnies Acres	Las Cruces	Doña Ana	32.337077		transformer oil spill	5/21/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	1115 May	Las Cruces	Doña Ana	32.311133		transformer oil spill	7/1/08	soil excavation	closed	6/30/2011
El Paso Electric Co.	1300 Lujan Hills	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil spill	12/23/08	soil excavation	closed	6/30/2011
El Paso Electric Co.	1404 Diana Maura	Las Cruces	Doña Ana			transformer oil	8/19/2014	soil excavation	closed	9/19/14
El Paso Electric Co.	1410 Jeanie Ct.	Las Cruces	Doña Ana	32.337077		transformer oil	11/9/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	1490 6th St.	Las Cruces	Doña Ana	32.318207		transformer oil	3/2/2012	soil excavation	closed	4/5/2012
El Paso Electric Co.	1551 Avenida de Mesilla	Las Cruces	Doña Ana	32.283098		transformer oil spill	4/5/05	soil excavation	closed	09/23/05
El Paso Electric Co.	1785 Walden	Las Cruces	Doña Ana	32.297077	-106 751935	transformer oil	12/3/2012	soil excavation	closed	12/20/12

						ter Quality Bureau - Closed/Inactive St	ale clean up	01105		
-	curacy may vary. Coordinates may have be		sing google ear	th, but other less o	accurate methods	may have been used .				
, ,,	county, then alphabetically by Site Name									
Status may consist of close	d/no further action or CAR approved, or re	ferred to another	r program for p	rocessing such as	SOS/CERCLA, HWE	3/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may be archived or t	transferred with the referral.		
ite Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Paso Electric Co.	1815 & 1825 Baldwin	Las Cruces	Doña Ana	32.296078		transformer oil	7/22/2010	soil excavation	closed	6/30/201
Paso Electric Co.	18151 Hwy. 70 East	Las Cruces	Doña Ana	32.337077		transformer oil	7/23/2008	soil excavation	closed	6/30/20
Paso Electric Co.	18205 Hwy. 70 East	Las Cruces	Doña Ana	32.337077		transformer oil	4/28/2011	soil excavation	closed	6/30/20
Paso Electric Co.	2050 Amador	Las Cruces	Doña Ana	32.299677		transformer oil spill	7/22/04	soil excavation	closed	1/27/20
Paso Electric Co.	2102 Desert Greens	Las Cruces	Doña Ana	32.295562		transformer oil	8/16/2011	soil excavation	closed	9/1/20
Paso Electric Co. Paso Electric Co.	2111-2115 Jordan 2218 S. Valley	Las Cruces Las Cruces	Doña Ana Doña Ana	32.289738 32.285344		transformer oil spill transformer oil	4/17/10 8/18/2006	soil excavation soil excavation	closed closed	6/30/20 7/3/20
Paso Electric Co.	2250 Hixon Dr.	Las Cruces	Doña Ana	32.283862		transformer oil	5/10/2013	soil excavation	closed	6/19/1
Paso Electric Co.	2330 E. Nevada, Bldg. #8	Las Cruces	Doña Ana	32.30837		transformer oil	9/11/2006	soil excavation	closed	7/3/20
Paso Electric Co.	2720 Sunrise Point	Las Cruces	Doña Ana	32.339112		transformer oil	5/25/2007	soil excavation	closed	7/3/20
Paso Electric Co.	2958 Sundance	Las Cruces	Doña Ana	32.311353		transformer oil	9/5/2006	soil excavation	closed	7/3/20
Paso Electric Co.	2962 Sundance	Las Cruces	Doña Ana	32.311388		transformer oil	9/5/2006	soil excavation	closed	7/3/20
Paso Electric Co.	301 Roadrunner Parkway	Las Cruces	Doña Ana	32.322561		transformer oil spill	7/8/03	soil excavation	closed	2/22/20
Paso Electric Co.	3010 Thurmond	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil spill	6/26/08	soil excavation	closed	6/30/20
Paso Electric Co.	3011 N. Main	Las Cruces	Doña Ana	32.340734	-106.775898	transformer oil	7/19/2007	soil excavation	closed	7/3/20
Paso Electric Co.	3108 Pebble Beach	Las Cruces	Doña Ana	32.295714		transformer oil spill	5/23/05	soil excavation	closed	09/23/
Paso Electric Co.	3200 Bowman	Las Cruces	Doña Ana	32.274435		transformer oil	6/26/2012	soil excavation	closed	9/12/1
Paso Electric Co.	331 Capri Arc	Las Cruces	Doña Ana	32.337077		transformer oil	7/8/2012	soil excavation	closed	8/6/12
Paso Electric Co.	3519 Foothills Road	Las Cruces	Doña Ana	32.314887		transformer oil spill	7/22/03	soil excavation	closed	2/22/20
Paso Electric Co.	3601 Doña Ana Rd.	Las Cruces	Doña Ana	32.334762		transformer oil	5/3/2012	soil excavation	closed	5/17/20
Paso Electric Co.	3785 N. Valley	Las Cruces	Doña Ana	32.337077		transformer oil	9/13/2013	soil excavation	closed	10/1/
Paso Electric Co.	3819 Stoney Brook Circle	Las Cruces	Doña Ana	32.337077		transformer oil	4/4/2007	soil excavation	closed	7/3/20
Paso Electric Co.	400 Milton	Las Cruces	Doña Ana	32.286681		transformer oil spill	9/17/09	soil excavation	closed	6/30/20
Paso Electric Co.	4261 Pacana Trail	Las Cruces	Doña Ana	32.337077		transformer oil	8/10/2011	soil excavation	closed	8/25/20
Paso Electric Co.	4440 Los Arboles	Las Cruces	Doña Ana	32.317475		transformer oil	6/27/2012	soil excavation	closed	8/6/1
Paso Electric Co.	4849 Lohman 4849 Lohman	Las Cruces	Doña Ana	32.337077 32.337077		transformer oil transformer oil	11/4/2005	soil excavation soil excavation	closed	7/3/20
Paso Electric Co. Paso Electric Co.	4849 Lohman 4849 Lohman	Las Cruces Las Cruces	Doña Ana Doña Ana	32.337077		transformer oll	6/18/2008 1/12/2011		closed	7/3/20
Paso Electric Co.	4849 Lohman	Las Cruces	Doña Ana	32.337077		transformer oil	7/27/2014	soil excavation soil excavation	closed closed	9/2/1
Paso Electric Co.	4905 Snow	Las Cruces	Doña Ana	32.337077		transformer oil	12/11/2006	soil excavation	closed	7/3/20
Paso Electric Co.	5005 Big Tree Road	Las Cruces	Doña Ana	32.337077		transformer oil spill	6/5/03	soil excavation	closed	2/22/20
Paso Electric Co.	5158 Canary Ct.	Las Cruces	Doña Ana	32.337077		transformer oil	10/14/2005	soil excavation	closed	7/3/20
Paso Electric Co.	5223 Calle del Ranchero	Las Cruces	Doña Ana	32.389638		transformer oil	6/13/2008	soil excavation	closed	7/3/20
Paso Electric Co.	5300 Vista Sureste	Las Cruces	Doña Ana	32.375754		transformer oil spill	7/12/05	soil excavation	closed	1/27/20
Paso Electric Co.	750 N. Solano	Las Cruces	Doña Ana	32.317544		transformer oil	12/5/2006	Not on soil, replaced transformer.	closed	7/3/20
Paso Electric Co.	760 Scenic View	Las Cruces	Doña Ana			transformer oil	6/26/2014	soil excavation	closed	7/11/1
Paso Electric Co.	813 Morton	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	7/22/2010	soil excavation	closed	6/30/20
Paso Electric Co.	850 Holly Road, Space #B45	Las Cruces	Doña Ana	32.35099		transformer oil spill	5/9/05	soil excavation	closed	09/23/
Paso Electric Co.	Holman Rd. & Millard Ave.	Las Cruces	Doña Ana	32.337077		transformer oil	1/2/2011	soil excavation	closed	6/30/20
Paso Electric Co.	Hwy. 28 & Pajaro	Las Cruces	Doña Ana			hydraulic fluid spill	9/7/2006	soil excavation	closed	7/3/20
Paso Electric Co.	I-10, exit 116	Las Cruces	Doña Ana	32.337077		transformer oil	6/29/2011	soil excavation	closed	8/8/20
Paso Electric Co.	Main & Conway	Las Cruces	Doña Ana	32.27756		transformer oil	3/15/2002	soil excavation	closed	4/26/20
Paso Electric Co.	Twin Peaks Mtn.	Las Cruces	Doña Ana			transformer oil spill	4/7/09	soil excavation	closed	6/30/20
Paso Electric Co.	Twin Peaks Mtn.	Las Cruces	Doña Ana			transformer oil	4/27/2011	soil excavation	closed	6/30/20
Paso Electric Co.	1230 Tamony Ln.	Las Cruces	Doña Ana			transformer oil	5/2/2014	soil excavation	closed	6/6/1
Paso Electric Co.	664 Rouault	Las Cruces	Doña Ana	32.340556	106.785833	transformer oil	5/17/2015	soil excavation	closed	4/15/20
Paso Electric Co.	1767 Defiance	Las Cruces	Doña Ana	32.321667		transformer oil	7/24/2015	soil excavation	closed	4/15/20
Paso Electric Co.	5866 S. Main	Las Cruces	Doña Ana	32.239444		transformer oil	7/28/2015	soil excavation	closed	4/15/20
Paso Electric Co.	3928 Marble View	Las Cruces	Doña Ana	32.377778		transformer oil	8/17/2015	soil excavation	closed	4/15/20
Paso Electric Co.	1351 N. Alameda	Las Cruces	Doña Ana	32.321667		transformer oil	12/23/2015	soil excavation	closed	4/15/2
Paso Electric Co.	3850 E. Lohman	Las Cruces	Doña Ana			transformer oil	8/18/2016	soil excavation	closed	9/2/20
Paso Electric Co.	4124 Macaw Circle	Las Cruces	Doña Ana	32.265273°		2 gal transformer oil spill	6/18/2017	soil excavation	closed	5/23/20
Paso Electric Co.	4849 E. Lohman Avenue	Las Cruces	Doña Ana	32.332964°		30 gal transformer oil spill	7/6/2017	soil excavation	closed	5/23/2
Paso Electric Co.	435 Ithaca Court	Las Cruces	Doña Ana	32.325531°		12 gal transformer oil spill	8/25/2017	soil excavation	closed	5/23/2
Paso Electric Co. Paso Electric Co.	2027 Chateau Drive Fairway Village Drive & Picacho	Las Cruces Las Cruces	Doña Ana Doña Ana	32.326600° 32.309579°		10 gal transformer oil spill 20 gal transformer oil spill	9/4/2017 9/10/2017	soil excavation soil excavation	closed closed	5/23/2
	Hills Drive					•				
Paso Electric Co. Paso Electric Co.	NM Hwy. 478 & Salopek Road 2644 Cody Circle	Las Cruces	Doña Ana Doña Ana	32.220833° 32.335338°		10 gal transformer oil spill 5 gal transformer oil spill	4/10/2018 4/24/2018	soil excavation	closed	5/23/2
Paso Electric Co. Paso Electric Co.	3901 Watson Place	Las Cruces Las Cruces	Dona Ana Doña Ana	32.335338° 32.265191°		2 gal. Transformer oli spili	4/24/2018	soil excavation	closed	5/23/20
Paso Electric Co.	307 Pawnee	Las Cruces	Doña Ana	32.265191° 32.363630°		5 gal. Transformer oil spill	2/22/2017	soil excavation soil excavation	closed closed	7/7/20
Paso Electric Co.	3406 Harrelson Street	Las Cruces	Doña Ana	32.363630° 32.273561°		2 gal. Transformer oil spill	3/8/2017	soil excavation	closed	7/7/20
Paso Electric Co.	2022 Westwind Road	Las Cruces	Doña Ana	32.355153°		5 gal. Transformer oil spill	3/11/2017	soil excavation	closed	7/7/20
Paso Electric Co.	18205 San Augustin Drive	Las Cruces	Doña Ana	32.385331°		2 gal. Transformer oil spill	4/5/2017	soil excavation	closed	7/7/20
Paso Electric Co.	1025 Glendale Drive	Las Cruces	Doña Ana	32.365331 32.347167°		2 gal. Transformer oil spill	4/29/2017	soil excavation	closed	7/7/20
vergreen MHP	6345 Doña Ana Rd.	Las Cruces	Doña Ana	32.397657		untreated surfacing sewage	1/9/2007	sent Notif. of Discharge letter on 2/9/07	referred	111/20
/ergreen MHP	6345 N. Doña Ana Rd.	Las Cruces	Doña Ana	32.397657	106 924205	report asking for temporary DP until final DP is approved		referred to permitting	referred	

	New N	lexico Envi	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive S	tate Clean Up Si	ites		
	may vary. Coordinates may have bee	n determined usi	ing google ear	rth, but other less	accurate methods	may have been used .				
	y, then alphabetically by Site Name.		,	. ,						
		•		-		B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	· ·			Dete
Site Name ²	Location	City ²	County ²	Latitude '	Longitude	Event	Discharge Date	Action Taken	Status [°]	Date
Evergreen MHP	6345 N. Doña Ana Rd.	Las Cruces	Doña Ana	32.397657	-106.834205	surfacing septic tank effluent	1/9/07	Clogged system repaired and soil disinfected - dried out	closed	2/16/2007
Flying P Cattle Co.	S. of Hwy 70 2.5 miles on Baylor Canyron Rd	Las Cruces	Doña Ana	32.337077	-106.819454	Small public supply well showed interminant NO3 contamination.	unknown	site investigation and sampling did not reveal a source. If more info becomes available, than reassement will occur	closed	1/25/2011
Gasoline release to storm drain	1501 E. Amador	Las Cruces	Doña Ana	32.310363	-106.763447		1/22/2010	pumped out stormwater runoff pond	closed	4/28/2011
Graves Oil and Butane	202 S Compress Rd, and 801 W. Organ	Las Cruces	Doña Ana	32.306495	-106.787876	oil spill on Compress, and contaminated soil on W. Organ from small AST farm	pre 2000	soil excavation	closed	5/23/2000
Helweg and Farmer Transportation Co.	533 N 17th St.	Las Cruces	Doña Ana	32.307136	-106.804901	35 gal of diesel spill	9/11/2000	soil excavation	closed	10/18/2000
Home Depot	Telshore and Lohman	Las Cruces	Doña Ana			diesel fuel spill	pre 1/11/99	soil excavation	closed	1/11/1999
Hope Lumber (L&P Properties)	101 Archuleta Rd	Las Cruces	Doña Ana	32.303582		diesel contaminated soil	before 7/29/1999	soil excavation	closed	8/30/1999
Las Cruces RoadRunner Bus	1501A Hadley Ave	Las Cruces	Doña Ana	32.309059		215 diesel gallon spill at bus stop.	10/25/2006	soil excavation	closed	7/7/2007
Memorial Medical Center	2450 Telshor Blvd	Las Cruces	Doña Ana	32.292391	-106.735035	20 gal of diesel spilled	3/30/2002	soil excavation	closed	4/6/2001
Mesilla Valley Tyre	6375 W. Picacho	Las Cruces	Doña Ana	32.287187	-106.875272	petroleum hydrocarbons	ongoing, discovered June 2008	soil excavation	closed	4/10/2009
New Aces Pecan Company	2455 Entrada del Sol	Las Cruces	Doña Ana	32.31000000	-106.74750000	nitrate in temporary unauthorized discahrge	April 2015-April 2016	Characterized discharge, installed pretreatment improvements to prevent overflow	closed	5/31/2016
NMSU Boneyard	1/4 mile north of Geothermal Road and Aggie Rodeo Drive	Las Cruces	Doña Ana	32.289369°	-106.711759°	Soil contamination from various petroleum releases	unknown	soil excavation	closed	8/5/2014
Pena's Tile	817 Quesenberry	Las Cruces	Doña Ana	32.309012	-106.80451	motor oil spill	ongoing, discovered July 2008	soil excavation	closed	4/10/2009
Pep Boys Las Cruces	1203 Lohman Av	Las Cruces	Doña Ana	32.308605	-106.766096	O/W separator removal with low TPH	1997	soil excavation	closed	6/19/2005
Ramon's Garage	1500 E. Kansas	Las Cruces	Doña Ana	32.308285	-106.762785	spill of used oil and antifreeze	pre 2001	soil excavation	closed	6/24/2003
Rea Magnet Wire	301 Rea Blvd.	Las Cruces	Doña Ana	32.337077	-106.819454	2,300 gal. mineral oil spill from broken pipe	Nov. 2005	pipe repaired, soil excavated & sampled	closed	6/6/2006
Ritchie Chevron	2205 S. Valley	Las Cruces	Doña Ana	32.328184	-106 805259	motor oil spillage from overturned 55-gal. drums	Dec. 2005	soil excavation	closed	3/6/2006
RoadRunner Transit (bus)	1501A E. Hadley Ave.	Las Cruces	Doña Ana	32.317687		overfill at diesel pump island	10/25/06	soil excavation	closed	8/1/2007
Sara Lee Hosiery	T24SR2E 9	Las Cruces	Doña Ana			mineral oil spill	1992	SWQB oversaw corrective action	closed	1/8/1993
Shook Tire	717 N. Main	Las Cruces	Doña Ana	32.315277	-106.780262	hydraulic fluid	pre-2012	soil excavation	closed	
Sonoma Elementary	4201 Northrise	Las Cruces	Doña Ana	32.337077	-106.819454	curddled milk from dairy load lost by eqpt malfuntion on vaccum septic pumper	1/4/07	septage spill on property cleaned up by Southwest Envirotech	closed	2/5/2007
State Land Office Trespass Dumping	32.43203056,-106.7048167	Las Cruces	Doña Ana	32.43203056	-106.7048167	petroleum lubricants	unknown	soil excavation	closed	1/25/2011
Swift Transportation	I-10 (westbound), approximately ¼ mile east of exit 135	Las Cruces	Doña Ana			diesel spill	7/30/2008	soil excavation	closed	4/30/2009
Welch Dirt Work		Las Cruces	Doña Ana			petroleum hydrocarbon contaminated soil	soil excavation	soil excavation	closed	8/17/2007
Westside Recyclers	1961-81 Copper Loop	Las Cruces	Doña Ana	32.306008	-106.805226	Poor practices resulted in vehicle fluid spills	unknown	soil excavation and improved practices	closed	1/25/2011
Reliable Carriers Diesel Release	diesel release - US Hwy 70 east San Augustin Pass rest area	Las Cruces/Organ	Doña Ana			Truck was leaking diesel from saddle tanks.	12/22/2008	soil excavation and remova	closed	5/15/2009
Dick's Café de Mesilla	2000 Hwy. 292	Mesilla	Doña Ana	32.278214	-106.796874	wastewater from restaurant discharging onto property next door	3/7/07	inspected site, verified discharge, referred to EHD	closed	3/8/2007
El Paso Electric Co.	Hwy. 478 & MM19	Mesilla	Doña Ana			transformer oil	5/27/08	soil excavation	closed	7/3/2008
El Paso Electric Co.	620 Richardson	Mesilla Park	Doña Ana	34.166233	-106.026069	transformer oil dry fertilizer release during transfer from rail car to borner to trucke	6/17/2013	soil excavation	closed	7/30/13
Esslinger Trucking, Mesilla Park	3201 S. Harrelson	Mesilla Park	Doña Ana	34.166233		nopper to trucks	unknown	soil excavation and ceased	closed	1/31/2011
Harrelson Spill, Mesilla Park	110 Hanks	Mesilla Park	Doña Ana	34.166233		motor oil release from leaking 55-gal barrel	unknown	soil excavation soil excavation, soil &	closed	1/31/2011
Heil Pump Sales	255 Carver	Mesilla Park	Doña Ana	34.166233	-106.026069	various petroleum spills throughout	12/21/04	supply well sampling	closed	8/4/2006
Dona Anna Colonias	Los Palmeras Subdivision	Mesquite	Doña Ana	32.165699		Domestic Well Sampling	Oct-94	Results showed high TDS and Sulfate	closed	2/1/1996
El Paso Electric Co.	108 St. Thomas	Mesquite	Doña Ana Doña Ana	32.166485		transformer oil	7/19/2012	soil excavation	closed	9/28/12
El Paso Electric Co. El Paso Electric Co.	12560 Stern 13116 Smokey Rd.	Mesquite Mesquite	Dona Ana Doña Ana	32.165699 32.165699		transformer oil transformer oil	5/13/2002 4/1/2010	soil excavation soil excavation	closed closed	6/7/2002 6/30/2011
El Paso Electric Co.	13116 Smokey Rd. 13950 Stern	Mesquite	Dona Ana Doña Ana	32.165699		transformer oll	4/1/2010 4/1/10	soil excavation	closed	6/30/2011
El Paso Electric Co.	14310 Stern	Mesquite	Doña Ana	32.165699		transformer oil spill	6/7/10	soil excavation	closed	6/30/2011
El Paso Electric Co.	4000 Hwy. 478	Mesquite	Doña Ana	32.164622		transformer oil	3/14/2013	soil excavation	closed	5/30/13
Helena Chemical	251 John Grisham	Mesquite	Doña Ana	32.164167		small diesel spill found on northern property	2/5/07	soil excavation	closed	6/15/2007
Helena Chemical	251 John Grisham	Mesquite	Doña Ana	32.164167		30 pounds of sulfur dry fertilizer spill	8/23/07	sulfur removal	closed	7/3/2008
Mesquite Area Wells		Mesquite	Doña Ana			Sampling of domestice wells in village	unknown	Sampling of domestic wells	inactive	1978

	New	Mexico Envi	ronment	Department -	Ground Wa	ater Quality Bureau - Closed/Inactive St	tate Clean Up S	ites		
2	may vary. Coordinates may have be		ing google ear	th, but other less a	ccurate methods	may have been used .				
2	ty, then alphabetically by Site Name urther action or CAR approved, or r		proaram for i	processing such as :	SOS/CERCLA. HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may be archived or tro	ansferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Mesquite Mutual Domestic Water Consumers and Mutual Sewage Works Association	St. Thomas Avenue	Mesquite	Doña Ana	32.165699		6,000 gal of sewage spill	11/17/2007	soil excavation and disinfection	closed	7/3/2008
Lead in soil, Organ		Organ	Doña Ana			health dept samples showing high lead in horse dog and woman	pre 1995	soil excavation through CERCLA	referred	
NASA Well "I"	NASA Johnson Space Center WSTF	Organ	Doña Ana	32.424566	-106.599794	oil in supply well	1964 to present	well maintenance	closed	12/4/2008
Organ Mt. TCE and NO3		Organ	Doña Ana			TCE showed up in water supply back before 84, NO3 concerns due to WWTP		monitoring by PPS	inactive	
AIG Environmental	I-25 mile 32.2	Rincon	Doña Ana	32.672395	-107.073291	truck accident caused release of diesel	8/28/1998	soil excavation	closed	10/30/1998
El Paso Electric Co.	36000 Rincon Mtn.	Rincon	Doña Ana	32.672395		transformer oil	5/15/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	Rincon Mtn.	Rincon	Doña Ana	32.672395		transformer oil	3/24/2008	soil excavation	closed	7/3/2008
Helena Chemical Co.	2537 Hwy. 140	Rincon	Doña Ana	32.67299444	-107.06410556	liquid fertilizers	5/3/07 and 4/14/08	soil excavation	closed	9/23/13
Mesa Feed	2424 Rincon Rd	Rincon	Doña Ana	32.673312°	-107.062865°	Spills of cattle feed supplements, primarly urea and molasses	unknown	soil excavation	closed	7/14/2017
Valle del Rio subdivision	32.209243; -106.761349	Rio Grande floodplain	Doña Ana	32.209243	-106.761349	spots in field with no vegetation growing	undetermined	SLD eliminated Roundup but is analyzing for presence of other herbicides	closed	8/21/2007
Tommy's Garage	18617 S. Hwy. 28	San Miguel	Doña Ana	32.149927	-106.727513	various car fluids (motor oil, antifreeze) spilled on soil	4/12/05	Conducted site inspection, verified contamination.	referred to HWB	
El Paso Electric Co.	5301 McNutt	Santa Teresa	Doña Ana	31.848786	-106.6259	transformer oil spill	7/20/04	soil excavation	closed	1/27/2006
El Paso Electric Co.	101 Feathermoon	Santa Teresa	Doña Ana	31.843086		transformer oil	6/26/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	102 Casas Bella	Santa Teresa	Doña Ana	31.869318		transformer oil spill	12/16/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	142 Feather Moon	Santa Teresa	Doña Ana	31.843809	-106.651399	transformer oil spill	7/23/03	soil excavation	closed	2/22/2005
El Paso Electric Co.	2750 Airport	Santa Teresa	Doña Ana	31.870534	-106.698905	transformer oil	12/27/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	300 Feather Moon	Santa Teresa	Doña Ana	31.843102	-106.653659	transformer oil	7/12/2000	soil excavation	closed	11/15/2000
El Paso Electric Co.	5535 Country Club Rd.	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	4/8/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	6909 Binational Ave.	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	6/4/2013	soil excavation	closed	6/30/2011
El Paso Electric Co.	7001 Pete Domenici	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	11/1/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	808 Green Bluff Ln.	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	1/12/2008	soil excavation	closed	7/3/2008
El Paso Electric Co.	Desert Pointe Apartments	Santa Teresa	Doña Ana			transformer oil	1/21/2002	soil excavation	closed	3/21/2002
El Paso Electric Co.	105 Comerciantes	Santa Teresa	Doña Ana	31.872778	106.653889	transformer oil	7/21/2015	soil excavation	closed	4/15/2016
Former Charter Hospital (Alliance Hospital)	100 Charter Court	Santa Teresa	Doña Ana	31.869318	-106.673361	emergency generator diesel spill	pre 2002	soil excavation	closed	7/22/2004
Lopez complaint	1154 Sandpiper	Santa Teresa	Doña Ana	31.869318	-106.673361	concerns over petroleum contaminated soil	Aug-92	inspection showed small area and not threat to GW	closed	9/10/1992
El Paso Electric Co.	1 Ardovino Lane	Sunland Park	Doña Ana	31.792268	-106 55726	transformer oil	8/30/2000	soil excavation	closed	11/15/2000
El Paso Electric Co.	107 Quinella	Sunland Park	Doña Ana	31.805225		transformer oil spill	8/24/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	3005 McNutt	Sunland Park	Doña Ana	31.805686		transformer oil	11/8/2012	soil excavation	closed	11/20/12
El Paso Electric Co.	383 Riverside	Sunland Park	Doña Ana	31.817387		transformer oil	6/23/2011	soil excavation	closed	8/8/2011
El Paso Electric Co.	Diablo Substation	Sunland Park	Doña Ana			transformer oil	10/1/2003	soil excavation	closed	10/28/2003
El Paso Electric Co.	Diablo Substation	Sunland Park	Doña Ana			transformer oil	7/14/2003	soil excavation	closed	10/22/2003
El Paso Electric Co.	104 Del Prado	Sunland Park	Doña Ana	31.798889	106.583611	transformer oil	6/23/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	295 Quinella Road	Sunland Park	Doña Ana	31.803142°	-106.571595°	8 gal transformer oil spill	12/12/2017	soil excavation	closed	5/23/2018
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	200 gal. diesel spill from pipeline	5/19/03	soil excavation	closed	2/22/2005
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	compressor oil	8/18/2014	soil excavation	closed	9/18/14
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	transformer oil	4/29/2008	soil excavation	closed	7/3/2008
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	transformer oil	2/23/10	soil excavation	closed	6/30/2011
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	transformer oil	9/13/2013	soil excavation	closed	1/10/14
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	diesel fuel	5/7/2013	soil excavation	closed	1/10/14
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	turbine oil	2/26/2015	soil excavation	closed	4/15/2016
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	turbine oil	3/25/2015	soil excavation	closed	4/15/2016
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan	Sunland Park	Doña Ana	31.834487	-106.588466	fuel oil	1990s	soil excavation	closed	6/17/2016
El Paso Electric Co., Rio Grande Power Plant, Sunland Park	3501 Doniphan Road	Sunland Park	Doña Ana	31.8044	-106.5464778	~12,000 gals. of fuel oil (#2) spilled around AST #3, Soil excavation completed, GW monitoring completed	2/25/2006	Soil excavation completed, GW monitoring completed	closed	6/17/2016
Rexene Products		Sunland Park	Doña Ana			draft AOC about old refinery with LNAPL	before 1991	unknown	inactive	

	New	Mexico Envi	ronment	Department -	Ground Wa	ater Quality Bureau - Closed/Inactive S	tate Clean Up S	ites		
, J	may vary. Coordinates may have be		ing google ear	rth, but other less a	ccurate methods	may have been used .				
	ty, then alphabetically by Site Name. further action or CAB approved, or re		nrogram for r	processing such as	SOS/CERCIA HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	0 may be archived or tr	ansferred with the referral		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Cervantes Enterprises	9926 Hwy. 478	Vado	Doña Ana	32.127955	-106 673269	anonymous caller claimed 4000 gal, spill of liquid	2/2/06	inspected site, no liquid fertilizer tanks on site, no evidence of spill found	closed	2/7/2007
El Paso Electric Co.	1400 Lechuga	Vado	Doña Ana	32.127537		transformer oil spill	4/25/05	soil excavation	closed	09/23/05
El Paso Electric Co. Golden West Truck Stop	8710 Highline I-10 and Vado Exit	Vado Vado	Doña Ana Doña Ana	32.127537	-106.656504	transformer oil report of fuel spill	9/23/2001 10/27/1995	soil excavation refer to PSTB	closed referred	10/12/2001
United Agri Products	NM 478 (200 yds. south of UAP)	Vado	Doña Ana	32.127537	-106 656504	small spill of dry fertilizer on road	1/26/07	fertilizer swept up &	closed	3/9/2007
	32.095847: -106.767828	West Mesa	Doña Ana	32.095847		drums of waste oil and antifreeze		reused SLO hired contractors		3/3/2001
SLO trespass dumping DC Carriers	MM 17 and 18, Hwy 213	White Sands	Doña Ana	32.095847		truck rollover lost 5,700 gallons of diesel	undetermined 10/12/2012	soil excavation	closed closed	2/8/13
WSMR Heating Oil	UST at LC-33	White Sands	Doña Ana			heating oil release from LUST	pre 1998	soil excavation	closed	6/20/1998
El Paso Electric Co.	Apollo Substation	White Sands Test Facility	Doña Ana	32.505556	106.611944	dielectric fluid	8/1/2015	soil excavation	closed	4/15/2016
HORVAC grease disposal	DP 1355 on west mesa near Afton siding; county rd. B007	Whitman	Doña Ana			2,000 gals of grease trap liquid waste spill	5/21/2007	Health threat mitigated by blading contaminated soil into berm along bar ditch	closed	8/21/2007
Idaho and Solano Sts.	Las Cruces		Doña Ana			report showing PID hits in one borehole but GW below laboratory detection in grab sample	unknown	data did not show contamination concern	inactive	
Illegal sludge dumping	west of San Miguel		Doña Ana			spill report and one sample on VOCs (ND)	Jan-88	unknown	inactive	
Artesia old landfill	Commerce and Pecos St	Artesia	Eddy	32.848005		surficial petroleum dumping on old landifll initiated subsurface investigation	unknown	MW installation and GW monitoring	closed	12/10/2013
Asphalt Terminal (Holly Asphalt Co.)	2411 N. Freeman	Artesia	Eddy	32.848005	-104.414958	bulk plant investigation	none	Large tanks have liquid asphalt only.	closed	Feb. 2006
Dowell Schlumberger Facility	500 E. Richey Ave	Artesia	Eddy	32.857246		chlorinated solvents found in GW during a PSTB investigation	pre 1993	GWQB began site assessment and discovered site was OCDs	referred to OCD	3/12/1996
Dowell Schlumberger Facility	Artesia	Artesia	Eddy			chlorinated solvents found at LUST site	pre 1994	NOD sent 9-8-94	refer to OCD	unknown
former Enertech Wireline Service Facility	6551 Seven Rivers Highway	Artesia	Eddy	32.81738	-104.395324	septic tank sample showed low levels of PCE	unknown	soil borings by tank and leachfield showed ND for all VOCs	closed	2/2/2010
Mel Foley Ranch	56 miles west of	Artesia	Eddy	32.848005	-104.414958	215 gal diesel spill	10/22/1998	soil excavation	closed	12/21/1998
Navajo Refinery	T17S. R26E, 8 and 9	Artesia	Eddy			synopsis of petroleum cont. at refinery	1985	synopsis refers to HWB and OCD oversight	referred	
PCE Artesia, DP#550 mon wells		Artesia	Eddy			discovery of PCE in MWs shows a tresspassing plume on permitted site	unknown	determine source of PCE	inactive	
Steere Tank Lines	1713 Roselawn	Artesia	Eddy	32.848005	-104.414958	small AST farm with historic spills	pre 99	LNAPL recovery and MNA in GW - referred to PSTB with new regs	referred	6/24/2001
Texaco Bulk Plant	306 N. First St.	Artesia	Eddy	32.844564	-104.397723	Phase 2 ESA showed VOCs in soil and in one MW	pre 1992	GWQB responded saying that prioritization ranking was low would not be assigned	inactive	1/11/1992
502 North Canal St, Carlsbad	502 North Canal St	Carlsbad	Eddy	32.415338°	-104.228683°	Phase I ESA and Phase II indicated release of petroleum and chlorinated solvents, but below reportable level	unknown	soil excavation	closed	8/17/2017
American Auto & Equipment Auctions	1400 San Jose	Carlsbad	Eddy	32.397259	-104.215582	report of petroleum hydrocarbon releases from salvage yard	unknown	new property owner and no further releases of automotive fluids	inactive	
Ballard Wells	T25S, R24E,34.1	Carlsbad	Eddy			natural gas in domestic wells	1989	sampled of wells and results showed no GW contamination	closed	6/11/1989
Beker Industries		Carlsbad	Eddy			well samples with high TKN	1977	unknown	inactive	
Carlsbad Ford	2802 W. Pierce St.	Carlsbad	Eddy	32.445405		CAR / property transfer. Investigation/ clean up and refinancing of Carlsbad Ford dealership to new owner	unknown	CAR reports conditionally approved and investigation and abatement completed	closed	7/25/2014
Carlsbad Municipal Water Wells		Carlsbad	Eddy			Evaluation of City wellfields		evaluation of wellfield	inactive	12/15/1987
Carlsbad Pesticides	4409 Ferguson	Carlsbad	Eddy	32.371136	-104.140744	neighbor complaint about possible contamination	unknown	sampled soil and various tanks/drums for VOCs, SVOCs, pesticides, metals	referred to HWB	
Chaparral Cattle Co.	5300 Seven Rivers Hwy	Carlsbad	Eddy	32.611059	-104.417576	motor oil and chlorinated pesticides discharged on-site	pre 1998	soil excavation and GW monitoring	closed	2/5/1998
former SW Purity Water	201 Blodgett St	Carlsbad	Eddy	32.432081	-104.227492	discharge of water softener waste	pre 1997	soil excavation and practice change	closed	4/26/1999
Gnome underground nuclear test	25 mi SE of Carlsbad, T23S,R30E,34	Carlsbad	Eddy	32.397259	-104.215582	nuclear test site in 1961, 3-kiloton bomb	1961	assessment and soil removal	VRP site	ongoing
Harris well	1205 Central Av	Carlsbad	Eddy	32.397259	-104.215582	cont. water from domestic well possibly from Oil well	1976	referred complaint to OCD	referred	

	New I	Mexico Envi	ronment [Department -	Ground Wa	ter Quality Bureau - Closed/Inactive S	tate Clean Up S	ites		
	may vary. Coordinates may have be		ing google ear	th, but other less a	ccurate methods	may have been used .				
2	y, then alphabetically by Site Name uther action or CAR approved, or re		nroaram for n	rocessing such as s	SOS/CERCIA HWI	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000) may be archived or tra	unsferred with the referral		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Intrepid Potash East Plant	210 Red Cloud	Carlsbad	Eddy	32.397259	-104.215582		2/7/2012	soil excavation	closed	2/10/2012
Moffat Hay Company	2216 Smedley Rd.	Carlsbad	Eddy	32.397259		8 barrels of leaking used oil	pre 3/1993	soil excavation Has 60K tank but is empty	closed	7/8/1993
MPI East	210 Red Cloud	Carlsbad	Eddy	32.397259	-104.215582	bulk plant investigation	none	and hasn't been used for a while.	closed	Feb. 2006
MPI West	1996 Potash Mines Road	Carlsbad	Eddy	32.397259	-104.215582	bulk plant investigation	none	No tanks over 55K gals.	closed	Feb. 2006
N-Ren Plant	5 mile E of Carlsbad on Hwy 62/180	Carlsbad	Eddy			old fertilizer plant showed high Nitrogen in soil and GW	pre 1992	site assessment showed unusual high N background	inactive	6/15/1995
Odorless Cleaners	405 West Fox	Carlsbad	Eddy	32.419117		discovery of old USTB MWs	pre 1993	resampled MWs and below standards	referred to PSTB	11/5/2012
Standpipe Rd NO3 contamination	Standpipe road	Carlsbad	Eddy	32.397259	-104.215582	22 domestic wells had high nitrate presumably from septic systems	pre 1992	presumed connection to city water	inactive	
WIPP site		Carlsbad	Eddy			25 gal sewage spill	10/3/1995	disinfected soil	closed	
WIPP site		Carlsbad	Eddy			70 gal of diesel spill	9/10/94	soil excavation and land farming	closed	11/1/1994
F-4E AF plane crash near Hope	T19S, R21E,15	Hope	Eddy			cont. soil from plane crash	12/12/1995	soil excavation	closed	3/5/1996
ATSF derailment		Loving	Eddy			locomotive tank leak of 700 gal of diesel	5/13/93	soil excavation and on-site treatment	closed	6/28/1993
Tebuthiuron Herbicide - BLM	11 miles W of Malaga on Black River Village Rd	Malaga	Eddy			Aerial application of herbicide by BLM on 7/2003. Storm 2 days later caused runoff to get into irrigation ditch killing ~90 acres of crops.	7/18/03	NMED sampled domestic and a public well along with Black River and found ND	closed	3/19/2003
Chevron Helbing Federal Oil Well	T22S, R23E, 15.1		Eddy			site assessment of oil well sent to OCD	Aug-94	part of OCD case load	referred	
Crop Production Services	60 E. Compress Rd.	Artesia	Eddy	32.848005	-104.414958	petroleum contaminated soils and fertilizer	unknown	soil excavation and GW monitoring	closed	10/1/2009
Arenas Valley Solvents	W of Central	Arenas Valley	Grant			domestic wells with TCA hits	before 7-16-97	sampling showed low concentrations	inactive	
Cameron Creek	T17S, R13W, S2	Fort Bayard	Grant			anonymous dumping of used oil in arroyo	pre 11/03	soil results showed no threat to GW	closed	7/30/2004
Separ siding on Union Pacific RR	Separ Exit, north side of I-10	Separ	Grant	32.202034	-108.422699	report of floating product in supply well	historic, anecdotal	Contractor exposed reported well with oil and well was dry. Well and adjacent producing well were P&A'd by D&J Drilling out of Deming.	closed	4/5/2006
Separ Truck stop	I-10 and Exit 42	Separ	Grant	32.202034	-108.422699	bulk plant investigation	none	Inspected site. Truck stop and 100K gal. diesel tank are closed. No leaks observed. PSTB conducted previous soil investigation.	closed	3/6/2006
Allen Peterson Trailer Park	2108 N. Cactus Dr.	Silver City	Grant	32.786226		septic system overflow	May-96	leachfield replaced	closed	6/18/1996
CTS Dry Cleaners Domestic well low VOC hits	1330 N. Pope	Silver City	Grant	32.779054	-108.275676	PCE results of butanone in domestic well	unknown Jan-90	soil vapor monitoring	closed	3/2/2011
fmr San Man & Sons Construction	3535 Railroad Drive	Silver City	Grant			illegal storage of motor oil waste and releases	undetermined	unknown investigation of soil contamination and stockpiled waste oil removed	closed	in process
Ford Lincoln Mercury Dealer	Silver City Dealer	Silver City	Grant			during a LUST investigation additional contaminated soil was discovered	pre 2/92	soil excavation	closed	post 1992
Housely Distributing, Inc.	123 S. Railroad	Silver City	Grant			petroleum	unknown	ASTs NMED sampled domestic	referred to PSTB	
Lake Roberts	33 01' 57"N, 108 10' 02"W	Silver City	Grant	33.0325		Sediment placed by cabins near lake had some Pb.	Dec-98	wells and soil and results were ND	closed	8/19/1999
Verlane Jones	29 Rodeo Rd	Silver City	Grant	32.772986		report of petroleum hydrocarbon	10/8/1996	unknown	inactive	
Diamond Shamrock Cuervo Pump Station	11 miles N of Cuervo	Cuervo	Guadalupe			50 barrels of diesel and turbine fuel spilt when pump on pipeline failed	7/2/1999	soil excavation and MNA of soil	closed	4/1/2003
FAA Moon Ranch LUST	Hwy 84, 6 miles N of I-40, Dilia	Dilia	Guadalupe			diesel generator UST for FAA	pre 1992	soil excavation	closed	5/30/2003
ATA pipeline Spill -Milagro Pump Station	R9N, R16E, S3	Milagro	Guadalupe	34.166233		pipeline spill due to backhoe activities. Lost 938 barrels of diesel spilt	2/5/1990	soil excavation	closed	6/14/1990
Forward Air Inc Truck Accident	I-40 MM 300	Newkirk	Guadalupe	35.062549		truck accident released 100 gallon of diesel	9/22/2013	soil excavation	closed	6/27/2014
Puerto de Luna Acequia Diesel spill	Puerto de Luna Acequia	Perto de Luna	Guadalupe			sheen seen on Pecos River that came from a diesel irrigation pump used to supply water to acequia	5/28/2008	pump repaired and high flows in river dilluted carried residual contaminated soil downstream.	closed	7/31/2008
Air Road Express Truck Accident	I-40 mile 242	Santa Rosa	Guadalupe	34.930632	-104.672144	truck accident caused 150 gal of diesel spill	9/6/2000	soil excavation	closed	10/18/2000

	New N	lexico Envi	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive S	tate Clean Up S	ites		
•	may vary. Coordinates may have bee	en determined usi	ing google ear	th, but other less	accurate methods	may have been used .				
	y, then alphabetically by Site Name.	forrad to another	program for	rococcina cuch ac	SOS/CERCLA HIM	R/RCRA SIMP/RCRA ato Filos for sitos closed prior to 2000	may be archived or tre	anoforrad with the referral		
Site Name ²	Location	City ²		-		B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 Event	Discharge Date	Action Taken	Ctotus ³	Date
	Location	City	County ²	Latitude '	Longitude ¹		Discharge Date	initial soil results showed	Status ³	Date
Santa Rosa School District Heating oil Tank		Santa Rosa	Guadalupe			heating oil release from UST	6/19/1995	low levels of TPH adjacent to UST.	closed	2/2000
Waggoners Trucking	Derby Road near Dexter	Santa Rosa	Guadalupe			truck accident, 200 gal diesel	7/13/2000	soil excavation	closed	4/11/2001
BNSF Locomotive Derailment	mile post 792.7 5 mile W of Vaughn)	Tejon	Guadalupe	34.166233	-106.026069	locomotive derailment spilt diesel fuel1	12/20/1995	soil excavation	closed	4/1/1996
DOD Air Force F-16 Jet Crash	T5N, R17E, S5	Vaughn	Guadalupe			F-16 crash spilling jet fuel	5/12/1997	MNA of soil was shown through sampling	closed	9/5/1997
XL Insurance	Hwy 54 and Hwy 60, .7 mi e of Vaughn	Vaughn	Guadalupe			Tuck accident with diesel release	2/1/2005	soil excavation	closed	5/4/2005
Schneider National Truck Accident	I-40 and mile 305		Guadalupe			truck accident caused 100 gal diesel spill	10/15/2000	soil excavation	closed	1/3/2001
BOC Gasses	1463 Hwy 102	Bueyeros	Harding	34.166233	-106.026069	Former liquid CO2 and Dry ice manufacturing plant had residual diesel soil contamination	unknown	soil excavation	closed	2/15/2007
Amerigas Solano	1-2 miles SE of Solano	Solano	Harding			Phase II investigation showed petroluem hydrocarbons in GW at former CO2 facility	pre 1989	GW investigation	closed	6/16/1989
		Solano	Harding			domestic well sampling including Rad		domestic sampling	inactive	8/1/1998
BJ Cecil Trucking	Hwy 70 and SR464	Lordsburg	Hidalgo			truck accident caused release of 1600 gal of H2SO4	8/20/1999	soil excavation	closed	5/19/2000
Pyramid (Tri-State) Gen. Station	53 Ramos Farms	Lordsburg	Hidalgo	32.346903	-108.702482	bulk plant investigation	none	Inspected site. 1.5M gal. tank, berms, and liner in excellent condition. No leaks observed.	closed	3/6/2006
Pyramid Generating Station	No. 53 Ramos Ranch	Lordsburg	Hidalgo	32.346903	-108.702482	historic discovery of diesel spill and lube oil	pre 11/03	soil excavation	closed	4/16/2004
Steer Tank Lines	Hwy 70 mile 1	Lordsburg	Hidalgo			truck accident caused release of 8200 of diesel	6/7/1998	soil excavation	closed	6/20/1998
Western Refining	US 70, MM 24	Lordsburg	Hidalgo	32.346903	-108.702482		8/16/2008	soil excavation	closed	4/5/11
USA Petroleum #802	I-10 and Hwy. 80	Road Forks	Hidalgo	32.233572	-108.952767	spillage of diesel fuel from ASTs	Nov. 2003	soil excavation	closed	8/30/2005
Bell Gas Truck Accident	17.7 mi E of Hwy 62 on St Rd 176	Eunice	Lea			truck accident spilled 1000 gal gasoline	9/11/2005	soil excavation	closed	3/11/1999
Bulldog Services Accident Spill	Hwy 176, 4 mi W of Hwy8, 10 mi W of Eunice	Eunice	Lea			traffic accident,300 gal diesel, 200 gal anti-freeze	8/27/1998	soil excavation	closed	1/10/2003
Hondo Chemical Facility	railroad sidding	Eunice	Lea	32.449053	-103.191296	sulfur slurry improperly contained	pre 2002	removal of slurry and BMP	closed	2/19/2002
Axelson Facility	2730 W Maryland	Hobbs	Lea	32.739668		report of 95 soil and GW cont at the oil field service co.	9/14/1995	refer to OCD	referred	9/21/1995
Bar4 Dairy/Hobbs Drive-In Dairy	3600 Dal Paso	Hobbs	Lea	32.449053	-103.191296	pre 77 dairy that had modifications	pre 77	referred to PPS	referred	
Cline		Hobbs	Lea			spill of 60 gal of used oil	pre 1991	soil excavation	closed	post 1991
Conoco Travel Center	3305 W. Marland	Hobbs	Lea	32.696558	-103.178561	diesel and wash down water accumulated in stormwater pond contaminating soil	2/7/2000	soil excavation	closed	3/17/2003
Fire Training Pits	Lot 7-18, Block 35	Hobbs	Lea	32.727533	-103.16204	discovery of petroleum contaminated soil from former fire training pits	pre 1991	soil excavation	closed	post 1991
former Hobbs Spring Works	Turner and Grimes	Hobbs	Lea	32.727533	-103.16204	upon foreclosure petroleum contaminated soil was discovered	pre 1992	soil excavation	closed	post 1992
Hines Super Shell	Lea County Airport	Hobbs	Lea			chlorinated solvents detected in ground water at adjacent PSTB site	unknown	interviewed plant foreman and found out that there is a Discharge Plan.	referred to OCD	Aug. 2005
Hobbs Airport Firepit	adjacent to Hwy 62-180 in airport	Hobbs	Lea			fire training pit had soil contamination from fuels ignited and put out in training	pre 89	1320 yds of soil removed	closed	12/16/1991
Hobbs Municipal wells	various	Hobbs	Lea		105	Memo of petroleum concerns in city production wells	0/00/		referred to PSTB	7/4/1984
Kealing Distributing Co. Koch Hobbs	2900 W. Marland 2121 French Dr.	Hobbs	Lea Lea	32.696516 32.722992		5000 gal diesel spill from AST vandalism 900 gal diesel release in '92, soil removal	3/26/1999 Jul-92	soil excavation	closed	9/24/1999 3/12/1998
Marathon Oil, Lea Co	T20S, R37E,S5.33	Hobbs Hobbs	Lea	32.122992	-103.102103	Stage 2 AP required by OCD	8/21/2000	soil excavating referred to OCD	closed referred	3/12/1996
Melot Oil Company	1200 W.County Rd.	Hobbs	Lea	32.702477	-103.176074	AST spill release in 91	pre 91	NOV of 1/17/91	inactive	
Wagner Equipment (fmrly RUST Tractor)	1005 NW County Road	Hobbs	Lea	32.710494	-103.176078	sump overflow	unknown	ground water monitoring	closed	2/1/2006
Windmill Oil Company	4001 Mahan	Hobbs	Lea	32.727533	-103.16204	water windmill wells began pumping product off the water table in the 60s and group formed a company to sell the product	unknown	Windmill company stopped pumping in the 80s and Oil Conservation Division has regulatory jurisdiction	referred	
KW Fuels	US 62/180 mile 93	Hobbs/Carlsbad	Lea	34.166233		5000 gal of gasoline release in an accident	10/17/2000	soil excavation	closed	3/6/2001
Araho Well Site Davis Gas Plant	5 mile S Hwy 18 4 mi S of Hobbs Hwy 18	Loving	Lea Lea	32.707293	-103.115658	Assist City of Lovington on clean up of disposal well. bulk plant investigation	unknown none	referred to OCD Is being regulated by OCD since it's a natural gas	closed	12/15/99 Feb. 2006
						,		processing plant. well sampled for VOC,		
Mixon Domestic Well	T19S, R37E, S29	Lovington	Lea			Concern over dark domestic well water and greasy residue	unknown	SVOC, and FE, Mn. Results BDL with exception of Fe	closed	11/9/2011
Monument Well Water	T12S, R38E, S18.2	Monument	Lea			monument water supply well contaminated with crude	pre 84	referred to OCD	referred	

	New	Mexico Envi	ronment [Department -	Ground Wa	ater Quality Bureau - Closed/Inactive Sta	ate Clean Up S	Sites		
	may vary. Coordinates may have be		ing google ear	th, but other less a	ccurate methods	may have been used .				
2	ty, then alphabetically by Site Name. urther action or CAR approved, or re		program for p	processing such as s	SOS/CERCLA, HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 r	may be archived or ti	ransferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Domestic well NO3 cont	Hobbs Airport	Nadine	Lea	32.624197	-103.10777	domestic well results showing high NO3, source is old Custom Slaughter and Meat Co.	3/12/1987	referred to permitting	referred	
Melot Oil Truck Accident	Hwy 18, 4.5 miles E of Hobbs	Nadine	Lea			truck accident lost 6000 gal of gasoline	pre 1989	soil excavation and well sampling in 98 showed ND	closed	7/27/1998
Nadine Nitrate Water Wells		Nadine	Lea			Custom Slaughter and Meat Packing suspected of causing nitrate contamination	1987	sampling of domestic wells	inactive	
Western Bar and Grill	10 miles E of Tatum on Hwy 380	Tatum	Lea			AST with aviation fuel was blown over in the 50s spilling fuel.	1950s	sampling of new well in 1999 showed ND	closed	11/29/1999
Climax Chemical Co. Bankruptcy	313 W. Marland		Lea			Climax bankrupt/NMED, Public land commissioner got \$45K, property got sold. Probably transferred to OCD	pre 96	refer to OCD	referred	
Lea County Brine Contamination Report (OCD)			Lea			Report to Water Quality Control Commission on Brine Contamination				8/15/1973
O7 Ranch produce water pits	Sanger + West Co. Rd intersection		Lea			complaint of produce water pits and OCD not taking action	pre 1971	referred to OCD	referred	9/1/2002
Prime Inc. truck accident	Hwy 380 mile 53	Carrizozo	Lincoln			truck accident caused small fuel, oil, and antifreeze spill	1/21/2001	soil excavation	closed	3/8/2001
Transwestern Pipeline Co.		Corona	Lincoln			old pipeline pumping stations showed petroleum contaminated soil	pre 1990	EPA took lead and soil was excavated	closed	6/12/1995
DOD Air Force F-16 Jet Crash	2 miles NE of Village of Lincoln	Lincoln	Lincoln			jet cash and 120 gal of Jet fuel was lost	12/8/1997	most volatilized and location was remote with dtw >100 ft	closed	2/20/1998
Domestic wells contamination with gasoline	127 Reese Dr.	Ruidoso	Lincoln	33.323924	-105.63678	analytical results of 2 domestic wells showed BTEX	pre 10/82	referred to PSTB	referred	
Gavilan Creek, suspected petroleum	by Gavilan Canyon Trailer Park	Ruidoso	Lincoln			report of spill into creek. No evidence of such	pre 7/12/96	inspection showed no evidence of spill	closed	8/15/1996
McCarty Construction Miele Well	Walnut Dr and Gavilan Canyon Airport Rd	Ruidoso Ruidoso	Lincoln	33.324702		UST remediation concerns of domestic well quality affecting health	1988 6/26/2000	UST remediation sampling of well showed	referred closed	6/29/2000
Safe Haven RV Park	Hwy 70 West	Ruidoso	Lincoln			sewage lift pump constantly failing	pre 1993	high TDS only facility went out of	closed	6/20/1994
	Tiwy 70 West	Ruidoso	Lincoln				pie 1995	business airport changed directors,	ciosed	0/20/1994
Sierra Blanca Regional Airport	313 Cree Meadows Dr.	Ruidoso	Lincoln	33.348452	-105.665067	spillage of motor oil, filters, residual fluids	4/2/99	no knowledge of spills or location	inactive	11/30/2006
Village of Ruidoso WWTP spill Circle K Truck Spill	WWTP unknown	Ruidoso Ruidoso Downs	Lincoln Lincoln			300 gal of sewage spill 20 gal of gasoline spilled	3/4/1991 6/20/2000	soil disinfection adsorbed fuel	closed closed	9/13/1991 8/4/2000
Desert Fuels Tanker spill	101 Camino Entrada	Los Alamos	Los Alamos	35.876377°	-106.249798°	Spill of 50-100 gal of gasoline on concrete pad during fuel delivery	1/4/2018	application of absorbent, removal	closed	3/9/2018
El Cajete Pumice Mine	15 miles W of Los Alamos off hwy 4	Los Alamos	Los Alamos			refueling area (underlined with a HDPE liner) of the mine had contaminated soil	4/29/1999	soil excavation	closed	5/27/1999
Ethylene Glycol spill	off Orange St.	Los Alamos	Los Alamos	35.891922	-106.290042	discovery of antifreeze in canyon	pre 3/93	unknown	closed	post 1993
Las Ventanas, Los Alamos	29 Short Drive	Los Alamos	Los Alamos	35.880191	-106.305551	sewage backup in townhome showed sewer line was never connected to municipal line	6/21/2007	soil excavation and connect sewer line	closed	11/13/2007
Columbus Water Fair		Columbus	Luna			NMED water fair		water fair results from April 2004	closed	4/1/2004
NM National Guard	Early Identification Team Site	Columbus	Luna			temporary fueling area secondary containment area had a low volume leak. Unknown volume	unknown	soil excavation	closed	7/10/2007
NM National Guard Storage Yard	300 yards east of Transfer Station	Columbus	Luna	31.813464		release of 66 gallons of diesel from a stuck flow valve	5/31/2007	soil excavation	closed	7/10/2007
Beacon Truck Stop Kinder Morgan Booster Station	I-10 exit 68 5815 Baker	Deming Deming	Luna Luna	32.272465 32.272465		AST samples showed TPH at 59,300 ppm petroleum contaminated soil discovered	pre 1/94 5/16/2006	unknown soil excavation	inactive closed	9/22/2007
Meth lab	T26S, R9W, S1.1	Deming	Luna			meth waste discharged to septic	pre 7/89	samples were below detection limits	closed	7/1/1989
MSJ Trucking Inc., truck accident	I-10 mile 97	Deming	Luna			truck accident spilled diesel and sulfuric acid from batteries	8/26/2002	adsorbed fuel	closed	10/4/2002
NMDOT Deming	2912 E. Pine	Deming	Luna	32.268645		chlorinated solvents flushed down septic system	unknown	septic system removed, SVE system installed, GW sampling	closed	5/10/2005
PNM Transformer oil spill	1214 E. Motel Dr.	Deming	Luna	32.26878	-107.747265	transformer oil leak when vehicle accidentally hit transformer	4/21/1999	soil excavation	closed	5/3/1999
PNM Transformer oil spill	6475 Columbus Hwy SE	Deming	Luna	32.272465	-107.755722	transformer oil leak	7/23/2000	7 gal of oil leaked with <1ppm PCB oil. Soil excavation	closed	10/10/2000
Porter Oil AST Bulk Plant	2701 East Pine ST.	Deming	Luna	32.268757	-107.725026	Spill reports from ASTs	1990	repair pumps	referred	
Savoy Truck stop	14150 Hwy. 418, 13 miles W of Deming	Deming	Luna			bulk plant investigation	unknown	Inspected 420K gal. tank and piping. No leaks observed.	closed	3/6/2006
Churchrock Uranium Mill Tailing Spill	United Uranium Churchrock Location	Churchrock	McKinley			Mine tailing dam burst releasing millions of gallons	7/16/79	excavation and extensive assessment		

	New N	Nexico Envir	ronment	Department -	- Ground Wa	ater Quality Bureau - Closed/Inactive St	tate Clean Up S	Sites		
2	may vary. Coordinates may have bee		ng google eai	rth, but other less o	accurate methods	may have been used .				
2	y, then alphabetically by Site Name.		,	. ,				6 I. 11 I. 6 I.		
				-		B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000			3	Dette
Site Name ²	Location	City ²	County ²	Latitude '	Longitude	Event	Discharge Date	Action Taken	Status ³ transferred to	Date
Alpine Lunber	104 North 2nd St	Gallup	McKinley	35.529822°	-108.742849°	BTEX leak from UST	unknown	assessment	VRP - AC Houston	12/2/2016
BNSF Gallup - NGL Energy	T15N, R18W, S16	Gallup	McKinley			5 barrels of crude spilt at yard by a contractor	11/4/14	soil excavation	closed	1/5/2015
City of Gallup Transformers Contractor Freighters, Inc	1898 Warehouse Lane Thriftway store, 9 mi N of Gallup	Gallup Gallup	McKinley McKinley	35.521636	-108.769067	PCB oils contaminated soil 70 gal of diesel spill	pre 2000 10/15/1998	soil excavation	closed closed	5/10/2001 2/15/1999
		·				Adjacent Brownfields investigation showed solvents in				
Elite Cleaners Former Commercial Drivers	Hwy 66 and Puerco Dr.	Gallup	McKinley			GW truck washing at a warehouse 5 miles NW of Gallup had	unknown	site entered into the VRP site sampling and soil	referred	10/29/2013
Liscence facility	North CR 1	Gallup	McKinley	35.522459	-108.723478	diesel spill munitions decomissioning discharge volumes of TNT to	unknown	excavation	closed	8/27/2004
Ft. Wingate Depot	Ft. Wingate	Gallup	McKinley	35.522459	-108.723478	unlined lagoons	pre 1980	refered to HWB		
Giant Refinery - Ciniza Refinery	17miles East of Gallup exit 39 I40	Gallup	McKinley			Multiple fuel releases	1983	referred to OCD		
Just Getting By Inc. Truck Accident		Gallup	McKinley	35.522459		truck accident spilled 50 gal diesel	8/21/2000	soil excavation	closed	9/19/2000
Love's Truckstop P&J Mobile Home Park	I40 exit 16 416 W. Coal Ave	Gallup Gallup	McKinley McKinley	35.522459 35.523742		truck accident caused 200 gal of diesel spill surfacing sewage from a lift station	3/27/1999 9/12/1995	soil excavation city of Gallup fixed pump	closed closed	2/4/2005 10/18/1995
								soil excavation and MW		
Steere Tank Lines	Escarbada Canyon	Gallup	McKinley	35.522459		truck accident spilled JP-4 fuel	4/6/1993	installation	closed	post 1993
Stever Trucking	I-40 at Mile Marker 48	Gallup	McKinley	35.522459	-108.723478	diesel spill of 300 gal evaporative ponds at truck stop showed TPH in soil	11/2/1998	soil excavation	closed	2/26/1999
Unocal 76/Brurns Bo. Truck stop	West of Gallup	Gallup	McKinley			samples	pre 1992	soil excavation	closed	6/14/1994
Lobo Canyon	NE of Grants on NF	Grants	McKinley	35.150067	-107.848006	20 drums of herbicide dumped in 70's	1970s	FS to do non emergency CERCLA clean up	closed	6/18/1997
Gallup Truck Stop	Giant Travel Plaza, I-40 and exit 39	Jamestown	McKinley	35.4807		etching solution spilling from a truck	10/21/1997	material removed	closed	3/20/1998
JR Theroux Mobile Home Park	Navajo Rt 12, mile 56/65	Navajo	McKinley	35.903824	-109.031633	truck accident spilled 80 gal of diesel	8/31/2000	soil removal	closed	2/23/2001
Ojo Encino Heating Oil release Prewitt Refinery	BIA School 1/2 mi W of Prewitt PO	Ojo Encino Prewitt	McKinley McKinley			1000 gal heating oil released when truck hit tank refinery showed GW cont.	Nov-00 pre 83	soil excavation referred to CERCLA	closed closed	9/26/2003
DOT Ramah Patrol Yard	DOT Ramah Patrol Yard	Ramah	McKinley	35.143947	-108.491909	gas spill reported	pre 1992	soil excavation	closed	8/1/1992
BNSF Thoreau	High Ridge Trucking Facility, mile marker 125.6	Thoreau	McKinley			spill of potassium hydroxide	8/16/1999	material removed	closed	9/6/1999
Dial Oil	FR 456, 2 miles N of San Mateo	Thoreau	McKinley			Truck accident lost 1500 gal of diesel	4/19/2004	soil excavation	closed	8/1/2004
Ross Oil Company, truck accident	St Rd 121, mi 7 and 8	Chacon	Mora	34.166233	-106.026069	truck accident spilled 225 gal of gasoline	9/13/1997	clean up spill on surface	closed	6/20/1997
Ortiz Well	PO Box 11	Sapello	Mora	34.166233	-106.026069	concern over fire retardant discharge	Oct-00	sampled well and below laboratory detecting limits	closed	10/31/2000
Former Levi's Texaco/66	Hwy 85	Wagon Mound	Mora			LUST investigation showed DCE below stds and concerns of Pb from old batteries	Nov-94	P&T wanted to discharge to villages WWTP and solicited GWQB's input	inactive	5/24/1995
Cebolla Springs domestic well samples	Cebolla Springs Subdivision		Mora			domestic wells show some oil,	pre 91	unknown	inactive	
Alamo Disposal waste oil	W. Arnold + Lawndale	Alamogordo	Otero	22.022700		Poor practices resulted in vehicle fluid spills	unknown	soil excavation	closed	1/25/2011
Alamogordo Maintenance Yard Big A Auto Parts	2600 N. Florida 400 N White Sands	Alamogordo Alamogordo	Otero Otero	32.923706 32.893901		discovery of contaminated soil below service pit #1 septic tank leak with petroleum	pre 12/99 pre 96	soil excavation MW installation and soil	closed	1/18/2000 1/16/1996
Black Hills Aviation	Alamogordo Airport	Alamogordo	Otero	32.88315		used oil spillage from barrels	unknown	removal soil excavation	closed	8/5/1991
City of Alamogordo, Test well T-				32.00313	-103.907270			review and respond to		
4660	T12S,R10E, S31, by Snake Tank	Alamogordo	Otero			complaint of test well causing salt water intrusion	1/12/2007	technical report	closed	3/16/2007
DOT Alamogordo EEM Scrap Metal	RR and overpass of Hwy 70 2611 S. Walker	Alamogordo Alamogordo	Otero Otero	32.88315 32.855244	-105.967276	oil and tar seeping from a pit on DOT property. report of illegal smelter causing air polution on dioxin fall out	unknown pre 2008	unknown sampling of soil and domestic wells showed no contamination. Facility stopped smelting and implemented best management practices	inactive closed	5/1/2008
Groendyke Transport Truck Accident	Hwy 54 , 10 mile S of Alamogordo	Alamogordo	Otero			3200 gal of gas spill from truck accident	1/22/2000	ignition of spilled gas, soil excavation	closed	8/27/2001
Holloman AFB contaminated soil	Hensel-Phelps Construction Yard	Alamogordo	Otero			discovery of petroleum contaminated soil	1/29/1993	soil excavation	closed	3/17/1993
Holloman AFB Jet Crash	NW of HAFB	Alamogordo	Otero	32.88315		F-117A jet crash caused soil contamination with jet fuel	unknown	soil excavation	closed	7/23/1993
Presto Products Manufacturing Rudolph Automotive	1301 La Velle Rd 2600 N. White Sands Blvd.	Alamogordo Alamogordo	Otero Otero	32.874026 32.929059		release of petroleum from an oil water separator hydraulic lift contaminated soil	pre 9/98 pre 1994	soil excavation unknown	closed	10/30/1998
Panama Ranch Garbage Dump, USFS	T22S, R19E, S8	Carlsbad	Otero			Old cave where pesticides had been dumped along with trash	pre 1997	USFS conducted a removal under CERCLA emergency funds	closed	6/20/1997
CS McCrossan Construction	hwy 38, 20 miles w. of Carrizozo	Carrizozo	Otero			1000 gal of diesel spilt when AST vandalized	1/18/1999	soil excavation	closed	8/31/1999
Former Child Development Center, HAFB	Bldg. 790	Holloman AFB	Otero			heating oil (diesel or kerosene)	3/31/2010	soil excavation	closed	4/25/13
Holloman AFB LNAPL	Holloman AFB	Holloman AFB	Otero	32.88315		report showing LNAPL	pre 81	referred to HWB	referred	5/1/1981
Holloman AFB, UST	541 New Mexico Ave.	Holloman AFB	Otero	32.8406	-106.0792	petroleum contaminated soil		soil excavation	closed	4/25/13

	New N	Mexico Envi	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive St	ate Clean Up S	Sites		
¹ Latitude and Longitude accuracy i	may vary. Coordinates may have bee	en determined usi	ing google eai	rth, but other less	accurate methods	may have been used .				
2	y, then alphabetically by Site Name.									
•			•			B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000			•	
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Blankenship Sand & Gravel, La Luz	177 Griffin	La Luz	Otero	32.96981	-105.930262	various spills of motor oil, diesel fuel, & hydraulic fluid	4/7/2008	soil excavation RP hired VIVA	closed	5/8/2012
Mesa Verde Enterprises/Coastal Transport	Mesa Verde Ranch Rd, La Luz/10955 Railroad Drive	La Luz	Otero	32.96981	-105.930262	spill of 850 gals diesel during fuel delivery overfill to AST at gravel quarry	9/25/05	Environmental same day as spill occurred. Response and cleanup was rapid after tank overfill.	closed	2/1/2006
Diamond Shamrock Piñon Pump Station	17 miles S-SE of Piñon	Piñon	Otero			75 gal of gasoline released from faulty pipeline connections	11/14/2000	soil excavation	closed	1/3/2001
Mesilla Valley Transport Truck Accident	Mesilla Valley Transport US70 and US54	Tularosa	Otero	33.073455	-106.014916	truck accident caused 100 gal of diesel spill	9/20/07	soil excavation	closed	11/19/2007
Jet Crash at WSMR	WSMR remote location	White Sands	Otero			Jet crash and spill of 6500 pounds JP-8	10/14/1998	soil excavation	closed	5/5/2000
WSMR Russ Site	White Sands Missile Range	White Sands	Otero			300 gal of diesel spilt from vandalized fuel pod	5/1/1998	soil excavation and land farming	closed	10/5/1998
High Energy Laser System Test Facility		White Sands Missile Range	Otero			spill of 100 gal of diesel from pump error from ASTs	11/10/98	soil excavation	closed	12/18/1998
House Co-Op AST	Hwy 252	House	Quay	34.647933°	-103.899801°	report of spills and broken line at small AST	pre 97	inspection showed no contamination and domestic wells nearby were clean	closed	8/7/1997
FFE Transportation Services Truck Accident	Hwy 469 and 54	Logan	Quay	35.342026°	-103.422879°	truck accident lost 20 gal of diesel	12/16/2000	soil excavation	closed	1/30/2001
Logan Ute Lake, NO3	NW part of town Hwy 540	Logan	Quay	35.360894°	-103.485781°	domestic well sampling showed NO3 above standards	8/16/1978	Water system improvements	closed	
Nara Vista Water Association Coop, NO3	T16N, R36E, S22.2	Nara Vista	Quay	35.605619°	-103.101734°	supply well impacted and recommended deeper well	pre 76	unknown	closed	
Diamond Shamrock Block Valve 72	Hwy 392, 11 miles NE of San Jon	San Jon	Quay	35.215342°	-103.164012°	84 gal of diesel/gas spill	5/1/2001	soil excavation	closed	7/27/2001
Terry's Service Center	NW corner Frontage Rd and Hwy 469	San Jon	Quay	35.115371	-103.336084	petroleum contaminated soil discovered	12/1/1998	soil excavation	closed	8/1/1999
Arch Hurley Conservation District Yard	101 E High St.	Tucumcari	Quay	35.176007	-103.726073	report of waste oil spill	pre 97	inspection showed no known contamination. MW associated with Worley Mills on-site is clean	closed	4/23/1997
Curry Ranch, Valero Logistics Operations	13 W. of Tucumcari	Tucumcari	Quay	35.130926	103.940644	pipeline break	16-Oct-95	soil treatment and passive vapor well	closed	10/27/2003
Southern Pacific RR Spill	SP Tucumcari Depot	Tucumcari	Quay	35.171747°	-103.745728°	unknown amount of diesel spill at RR yard	3/14/1995	soil excavation and borings	closed	6/2/1995
Swift Transportation	I-40, MM310	Tucumcari	Quay	35.142183	-103.814182	50 gal of diesel spill from truck accident	12/20/2015	excavation & Confirmation Sampling	Closed	4/1/2016
Versatile Construction Asphalt Plant	West Maple St.	Tucumcari	Quay	35.185971°	-103.734720°	35 gal of diesel spill	6/21/1999	soil excavation	closed	8/17/1999
Worley Mills	702 West Campbell Ave	Tucumcari	Quay	35.182106°	-103.734559°	Carbon Tetrachloride contamination in groundwater from grain elevator operation	unknown	monitoring	closed	8/31/2004
English Tank Grazing Allotment	Mesa Vallejos, Carson NF	Canjilon	Rio Arriba	36.481983	-106.430287	report of hauled livestock water containing petroleum	7/19/2011	interviews and water sample indicate no soil or groundwater concerns	closed	8/9/2011
F-18 Jet Crash, KAFB	10 miles NE of Canjilon Ranger Station, 25 miles SE of Chama	Canjilon	Rio Arriba			900 gallons of JP-5 jet fuel from jet crash	5/19/1995	soil monitoring	closed	
Arriba Construction	2246 St. Rd. 17	Chama	Rio Arriba	36.889834	-106.583581	report of diesel spill entering wetland	7/13/2001	sampling of wetland showed low TPH levels and no threat	closed	7/13/2005
Chama Sawmill	10th and Pine St	Chama	Rio Arriba	36.898096	-106.584022	AST diesel spill	98	soil removal and GW samples	closed	9/16/1999
Cumbres & Toltec Scenic RR Chamita Domestic wells	500 S. Terrrace Ave.	Chama Chamita	Rio Arriba Rio Arriba	36.90079700	-106.57825500	petroleum diesel, naphthalenes below NMED SSLs high NO3 in domestic wells	2003 Nov-95	no further action < SSLs continued monitoring	closed inactive	4/14/2016
O'Reilley Truck Accident	MM 17 Hwy 68	Embudo	Rio Arriba	34.166233	-106.026069	truck accident lost 175 gallon diesel	1/4/2012	soil excavation	closed	12/7/2012
AT&T Lucent Technologies Equipment Compound	2000 N Riverside Dr	Española	Rio Arriba	36.028793		discovery of PCE in soil	pre 1996	soil excavation	closed	8/1/1996
Big Rock Shopping Center		Española	Rio Arriba			discovery of BTEX in soil	Feb-84	referred to PSTB		
El Llano Solvents		Española	Rio Arriba			discovery of low concentration PCE	pre 1/94	closed since no new data indicates above stds.	closed	
Española Domestic Well logs		Española	Rio Arriba			well logs		11000103 00070 5105.		
Española Transmix Co.	PO Box 38	Española	Rio Arriba	36.00366	-106.069046	fish kill in pond and discharge to Rio Grande	May-89	pond taken out of commission	closed	
Española Valley Nursing & Rehabilitation Center, Española	720 Hacienda Street	Española	Rio Arriba	36.005065	-106.060835	small diesel AST spill from mid 90s	mid 90s	soil excavation and MNA	closed	7/1/2009
Hacienda Home Center		Española	Rio Arriba			500 gal of diesel spill	8/24/1994	soil excavation	closed	10/6/1994

-	New N	lexico Envi	ronment	Department ·	Ground Wa	ater Quality Bureau - Closed/Inactive St	ate Clean Up	Sites		
	may vary. Coordinates may have bee	n determined usi	ing google ear	rth, but other less o	accurate methods	may have been used .				
2	y, then alphabetically by Site Name. wither action or CAR approved, or ref	erred to another	nroaram for r	processing such as	SOS/CERCIA HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may he archived or t	ransferred with the referral		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Illegal Subdivision	T21N, R8Em S25.3	Española	Rio Arriba			domestic wells with slightly above stds for NO3	Aug-87	recommend city water	inactive	
John Professional Transmissions	406 Calle Chavez	Española	Rio Arriba	35.989034	-106.078492	complaint of spilled transmission oil from 5 brls	2/31/2000	no evidence of discharge	closed	
John's Transmission Shop	Chavez St, behind Cook's Mercantile	Española	Rio Arriba	35.989034	-106.078492	complaint of motor oil dumping	May-95		closed	
Lower San Pedro Community	by Rio Grande and Santa Cruz	Española	Rio Arriba			domestic wells with benzene	Jul-89	connect to City water and refer to PSTB	referred	
N. Riverside, Española	716 N. Riverside Drive	Española	Rio Arriba	36.028915	-106.064206	used oil tank spillage	7/19/2007	soil excavation	closed	7/3/2008
Parker Mine Storage yard	N of Fairview between Riverside Dr. and Hwy 285	Española	Rio Arriba	36.00366	-106.069046	AST spill	pre 97	soil removal and GW samples	closed	2/10/2003
Plateau Thriftway Gas Station #183	Hwy 68 and Riverside Dr.	Española	Rio Arriba			1800 gal of leaded gas from LUST	Jan-87	referred to PSTB	referred	
Black Mesa Quarry	11 mi N of Lyden Hwy 582	Lyden	Rio Arriba			Quarry diesel spill	pre 97	none	closed	
Garcia Property	PO Box 280	Velarde	Rio Arriba	36.160919	-105.967131	septage hauler alledged dumping	pre 2000	referred to PPS for a discharge permit	referred	7/15/2000
Velarde Domestic wells, Emilio Martinez	Postmaster, PO Box	Velarde	Rio Arriba	36.160919	-105.967131	high BTEX, MTBE in domestic well	Aug-87	referred to PSTB		
Used oil dumping J.D. Heiskell Maintenance Facility	Rt 1 Box 201 F	Dora Portales	Roosevelt	33.931017 34.188224°		dumping of 3 barrels of used oil 6,000 gals of mineral oil spilled by vandals from AST. The discharge flowed southeast from the maintenance	Aug-93	referred to HWB	referred	9/23/1993 5/15/2018
				04.100224		shop onto North and South Abilene Avenues terminating approximately 0.23 mile from the Site.				0/10/2010
Nunn Peanut Co. Portales Oxidation Ponds	T1S, R35E, S26.413 Portales WWTP	Portales Portales	Roosevelt Roosevelt	34.169413		377 gallons of diesel spill study of oxidation ponds	2/9/1994	soil referred to PPS	closed referred	9/23/1977
Fortales Oxidation Fords		Fontales	Rooseven	54.109415		BLM transferred land patent to City of Aztec for		lelelled to PPS	Teleffed	9/23/19/7
BLM Aztec Landfill	1.9 miles south of Aztec	Aztec	San Juan	36.805715°	-107.987801	construction of bypass around town. Aztec acknowledged acceptance of environmental liability for old dump	unknown	assessment only	inactive	5/25/2017
Four Way Co.	1558 Hwy 550	Aztec	San Juan	36.826717		dozer release of 210 gal diesel	3/25/1993	soil excavation	closed	4/23/1993
Hubbard property Plateau Environmental Services	W of Aztec Ruins Four-way Co yard	Aztec Aztec	San Juan San Juan			clean up batteries, drums, and soil 210 gal of diesel #2 spill	pre 8/00 3/25/1993	soil excavation soil excavation	closed closed	8/25/2000 4/23/1993
Sullivan AST	301 Ash	Aztec	San Juan	36.825033	-107.99715	limited Phase 2 showed some soil contamination	unknown	soil excavation	closed	6/24/1996
Unknown Diesel Release	Hwy 550 and CR 2621	Aztec	San Juan	36.76642	-108.190183	Report of diesel fuel in an irrigation ditch	unknown	HWB emergency funds provided assessment and soil excavation of unknown source of diesel release	closed	3/18/2010
JP-4 Steere Tank Lines, truck accident	north of Blanco, mile marker 84, hwy 64	Blanco	San Juan	36.726589	-107.843084	tanker truck spill 4900 gal of jet fuel	4/6/1993	soil excavation	closed	
Sierra West Truck Accident	Hwy 64 mile 72.8	Blanco	San Juan			truck accident lost 7200 gal of diesel that flowed into irrigation ditch	4/28/2002	soil excavation, LNAPL removal, and MNA	closed	7/4/2004
Berean Mission	Star Route 4, Box 4500	Bloomfield	San Juan			Water Supply sampling suspected hydrocarbons	unknown	Analytical results showed below regulatory levels	closed	9/23/1984
D&D Oil	road to Aztec from Bloomfield	Bloomfield	San Juan			HWB letter about soil results	pre 98	referred to HWB	referred	
Grieder Property - Salt Release	6673 Hwy 64	Bloomfield	San Juan	36.72723		Salt accumulation in farmer's field alleged from adjacent property runoff	unknown	site inspection and soil sampling did not indicate salt accumulation in adjacent business. Recommended BMP for business	closed	7/24/2014
Holly Energy Bulk Fuel Terminal	170 CR 4980	Bloomfield	San Juan	36.72723	-107.981551	bulk terminal inspection	none	inspection of facility revealed no discharges	closed	7/12/2007
Milagro Gas Plant Septic Tank Leachfield	T29N, R11, S11	Bloomfield	San Juan			non domestic waste sent to leachfield	pre 1996	soil excavation and OCD jurisdiction	referred	
Serrano's Septic	Serrano's Septic SVC 13 Rd 4904	Bloomfield	San Juan	36.72723	-107.981551	report of dumping solid waste and truck wash waste in wetlands	unknown	site inspection and soil and groundwater sampling showed no GWQB corrective action required. Refered to HWB	closed	12/15/2009
Thriftway Trucking	Broadway and 1st St.	Bloomfield	San Juan	36.711341	-107.979122	truck accident spill of 150 gallons of gasoline	9/28/1993	soil excavation at SW corner of intersection	closed	10/6/1993
Domestic well results		Cedar Hill	San Juan			results from domestic well	Jun-84	nothing above stds	closed	
Action Auto (Hi Country Leasing)	4320 W. Main St.	Farmington	San Juan	36.731687	-108.232338	Report of intentional burying of waste and barrels of used oil/fuel	unknown	following NOV soil excavation occurred in 2 phases	closed	5/11/2010
Basin Disposal Inc.		Farmington	San Juan	36.741075	-108.170869	Alledged Disposal of oil services waste	9/10/1987	soil boring to 60' showed no contamination	closed	11/18/1987
Basin Tire & Auto	2700 E. Main St.	Farmington	San Juan	36.74165	-108.26327	Phase II discovered Soil Contamination	pre-2014	soil excavation, soil and groundwater sampling	closed	5/14/2014

	New	Mexico Envi	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive St	tate Clean Up S	lites		
¹ Latitude and Longitude accuracy r	may vary. Coordinates may have be					·	•			
2	y, then alphabetically by Site Name.									
						B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000			•	_
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken soil investigation for used	Status ³	Date
Brady Trucking	4000 Lomas St	Farmington	San Juan			Phase II soil Investigation	3/1/2013	oil and OWS	closed	6/25/2013
Consolidated Construction	3995 Cliffside Dr	Farmington	San Juan	36.755883		spill, stockpiled soil	Sep-00	soil excavation	closed	6/22/2004
Consolidated Construction	3995 Cliffside Dr.	Farmington	San Juan	36.755883		petroleum hydrocarbon contaminated soil water and asphalt emulsion spill when transfer pump	pre 2004	soil excavation Soil excavation and pump	closed	5/14/2004
Dirt Bandit	101 E. Piñon	Farmington	San Juan	36.723063	-108.205548	failed	8/26/2009	repair	closed	9/21/2009
Farmington CR5290 Sewage Seep	66 CR5290	Farmington	San Juan			seepage of liquid waste into arroyo	Sep-13	sample collection and referral to LWP	referred	10/18/2013
Farmington Fire Pit	710 S. Tucker Ave.	Farmington	San Juan	36.73549	-108.17732	discovery of TPH and oily soil when a gas line was installed	unknown	soil excavation at private business and along Animas River greeen belt	closed	2/10/2010
Farmington solvents in domestic wells	Melba Lane and Hydro Plant Rd.	Farmington	San Juan	36.724421	-108.194895	domestic wells showed some PCE ~15 ppb	pre 1990	homes connected to city water and no source identified	closed	6/18/1997
GE Facility Sump discharges	3009 E. Main St	Farmington	San Juan	36.742743	-108.167904	discharges into drywell/sump	pre 1996	soil excavation	closed	6/19/1996
High Desert Auto	1700 E. San Juan Blvd.	Farmington	San Juan	36.733913	-108.186534	hydraulic oil release from auto lifts	pre 2000	soil excavation, LNAPL	closed	1/10/2003
Hubbard Acres Tank Farm	Hubbard Acres	Farmington	San Juan			soil contamination from former bulk terminal	pre 1993	soil excavation and on-site treatment	closed	11/12/1993
Industrial Repair Service	1113 Camina Entrada	Farmington	San Juan	36.719164	-108.185628	evap pit from wash bay floor drain	pre 2000	soil excavation	closed	12/20/2000
Nielson's Gravel Quarry	north of Farmington	Farmington	San Juan			petroleum contaminated soil	pre 86	soil excavation	closed	
Phoenix Fuel Bulk Plant	2405 E. Main St.	Farmington	San Juan	36.739541	-108.175387	Phase 2 showed soil contaminiation associated with adjacent fuel bulk plant	unknown	PSTB jurisdiction and oversight	referred	11/3/2007
Rag Top's Sportswear	500 Electric Ave	Farmington	San Juan	36.737877	-108.17527	report of discharges of solvent on site	pre 2000	inspection, soil vapor and soil sampling showed no contamination	closed	8/21/2002
RO Company	2517 E San Juan Blvd.	Farmington	San Juan	36.736658	-108.179719	old auto paint and body shop showed historic contaminated soil	pre 1999	soil excavation, and MNA for GW	closed	11/15/2000
Rust Tractor Farmington	1000 Troy King Rd	Farmington	San Juan	36.740388	-108.265557	Evaporative lagoon closure report	pre 1992	site associated with a LUST PSTB site. Soil excavation	closed	
San Juan Medical Foundation	622 W. Maple	Farmington	San Juan	36.724379		discovery of TPH contaminated soil	34394	soil excavation	closed	3/31/1994
San Juan Spring Co,	1516 W. Main	Farmington	San Juan	36.7282	-108.201	petroleum hydrocarbon contaminated soil	pre 2002	soil excavation soil investigation was	closed	3/15/2002
Sears Facility #2597	4601 E. Main St.	Farmington	San Juan	36.76441	-108.153358	hydraulic oil release	pre 96	clean away from bldg.	closed	3/30/1998
Sewage Seepage	66 CR 5290	Farmington	San Juan	36.76642	-108.190183	Field Office report of sewage seepage into adjacent arroyo	7/1/2013	Collection of samples for fecal coliforms, VOC, SVOC, major ions, nitrogen species. Results indicate sewage.	referred to EHD	10/29/2013
Steer Tank Lines Truck Accident	3205 Bloomfield Hwy	Farmington	San Juan	36.719204	-108.167359	loss of 1000 gal JP-4 fuel	12/1/1992	soil excavation	closed	6/15/1992
Steere Tank Lines	Hwy 64 between Farmington and Bloomfield	Farmington	San Juan			1500 gal asphalt emulsion spilt	6/9/1993	removal	closed	6/28/1993
Target Store	E. Main St and English Rd	Farmington	San Juan	36.766903	-108.148599	oil water separator discovered during property development	12/1/1994	removal and soil excavation	closed	12/16/1994
Tefteller, Farmington	5420 US Hwy 64	Farmington	San Juan	36.715606	-108.150454	PSTB MW showed PCE concentrations ~1000 ppb	unknown	tresspassing plume. Referred to OCD	referred	8/7/2007
Transmission Headquarters	445 S. Browing Parkway	Farmington	San Juan	36.726846		oil sump with TPH	pre 96	soil excavation	closed	7/0/0000
Webb Automotive Group	3911 E. Main St.	Farmington	San Juan	36.76642		wash bay and sludge oil improper disposal	pre 2002	soil excavation inspection did not reveal	closed	7/8/2002
Whiteway Laundry	E. Murry and Camina Entrada	Farmington	San Juan	35.594352		report of dry cleaning waste disposal	pre 2003	obvious releases	inactive	
	Carlton Avenue	Farmington	San Juan	36.764022	-108.153856	TPH contaminated soil <100 mg/kg supply well showed oil impact, 5 MWs installed and	pre 92	none	closed	9/10/1992
Flora Vista MWDA well study		Flora Vista	San Juan			clean	1986		closed	
Foutz Laundry	Nuevobarrio and Camino del Pueblo	Kirtland	San Juan	36.743679	-108.353392	laundry unlined wash water pond	pre 1983	DP required	referred	
Lower Valley Lagoon Decommissioning	CR6100 and CR6263	Kirtland	San Juan	36.743679	-108.353392	During a wastewater project to decommission DP-1116, soil borings identified pteroleum hydrocarbon contamination	unknown	Identified that the soil contamination was associated with the former Caribou refining under OCD jurisdiction	referred	6/23/2014
PNM's San Juan Generating Station	CR 6800	Kirtland	San Juan	36.743679		bulk terminal inspection	none	inspection of facility revealed no discharges	closed	7/11/2007
Dial Oil	Hwy 94 2.5 miles east of Navajo St Rd 539 1/2 mile south of	Navajo	San Juan	36.72723		truck accident caused fuel release	10/1/1992	soil excavation	closed	post 1992
Four-Four Inc. truck accident	Navajo Dam	San Juan river	San Juan	34.166233	-106.026069	truck accident spilled 600 diesel 200 gal oil	1998	soil excavation	closed	6/20/1998
San Juan County Oil and Gas	various	various	San Juan			analytical results from sumps		referred to OCD	closed	6/7/1995
Fieldsted explosives	T30N, R16W, S35.3	Waterflow	San Juan			5000 gal of diesel and NH4NO3 was spilled	pre 1992	soil excavation on-site treatment	closed	post 1992

						ater Quality Bureau - Closed/Inactive S	tate Clean Up S	lites		
	may vary. Coordinates may have be		ing google ear	th, but other less a	ccurate methods	may have been used .				
2	ity, then alphabetically by Site Name. further action or CAR approved. or re		proaram for p	rocessina such as	SOS/CERCLA. HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000) mav be archived or tr	ansferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
Private well BTEX cont Navajo Nation			San Juan			high BTEX in domestic well	pre 4/85	refer to Navajo Nation	referred	4/2/1985
South Conchas Lodge		Conchas Dam	San Miguel			250 gal of gasoline leaked into Conchas Lake	8/12/1991	preventative measures taken for future mishaps	closed	post 1991
APEX Gasoline	Alamo and Grand Ave	Las Vegas	San Miguel			100 gal diesel fuel from accident	4/3/1992	during fire suppression runoff made it to the Galinas River. Containment	closed	post 1992
Franken Oil Heating Oil LUST, Don Wales	503 12th St 1213 6th St	Las Vegas	San Miguel	35.591633 35.602231		report showing contaminated soil from LUST old heating oil LUST	Pre 92	refer to PSTB removed tank and soil	referred closed	8/4/1997
Mills Plaza	200-250 Mills Ave.	Las Vegas Las Vegas	San Miguel San Miguel	35.599953		former dry cleaner releases	pre 96 unknown	excavation, monitoring,	closed VRP	7/15/2012
		-	-	00.000000	100.200000	a glue vat hardened and runoff from vat was drunk by		referred to VRP		1/10/2012
New Mexico Adhesives	ATSF railyard	Las Vegas	San Miguel			cows and they died	88	soil removal	closed	
Oliver and Dolores Maddux	108 Pecos St	Las Vegas	San Miguel	35.587981	-105.212978	allege seware hook up to 60 ft well	pre 96	following search warrant PPS addressed discharge	closed	
Pino Gas Station	Grand Ave and Columbia	Las Vegas	San Miguel	35.59978	-105.212941	discharges from LUST	pre 95	refer to PSTB PRC decided to keep	referred	
PNM Las Vegas Transformer Station		Las Vegas	San Miguel			PRC deposition from Lavery of PNM about environmental assessment if decommissioned	unknown	station as an emergency station. Hale from PNM stated there was no know discharges	closed	11/26/2007
Carlos and Pepe Valles Garage	15 La Jara Lane	Pecos	San Miguel	35.577749	-105.679814	complaint of antifreeze and used oil discharges	pre 8/10/05	HWB referral and site practices were improved along with minor soil excavation	referred	9/15/2005
Artic Express Truck Accident	I-25 and Hwy 84	Romeroville	San Miguel	34.166233	-106.026069	truck accident spilled various VOCs	12/1/1999	soil removal and GW monitoring	closed	11/24/2003
Bernucci Property	Ilfeld-Rowe Fire and Rescue	Rowe	San Miguel			AST showing soil contamination	pre 99	soil removal	closed	8/27/1999
Seally Mattress truck accident Budaghers Outlet Mall	I-25 mile 321, south of Tecolote I-25 and Budaghers exit	Tecolote Algodones	San Miguel Sandoval			100 gal diesel fuel from accident AST had past releases	May-99 5/4/1993	soil removal soil excavation	closed closed	7/6/1999 7/1/1993
Plains Electric-Algodones Generating Station.	, as and a stargent time	Algodones	Sandoval			Spill, fuel oil, pipe	7/9/1996	dig and haul, land applied	closed	6/18/1996
Rocor Trucking	I-25 and mile 247	Algodones	Sandoval	35.38843	-106.47972	truck accident released 50 gal of diesel	12/17/1996	soil excavation	closed	3/24/1997
Advanced Manufacturing	850 S. Hill Road	Bernalillo	Sandoval	35.300634	-106.540839	MW showed high DCE and Toluene	1992	unknown	inactive	0/00/4007
BNSF Bernalillo Oil Spill Chevron (fmr.) Bulk Plant	BNSF ROW at S. Oak St. 318 Railroad Track Rd.	Bernalillo Bernalillo	Sandoval Sandoval	35.30457	-106.546732	250 gal of hydraulic oil spilled	2/14/1997 10/30/1994	soil excavation	closed closed	3/20/1997 7/22/1998
#5735323		Bernalillo					1/2/1997	CAR approval		6/19/1997
PNM Transformer oil spill	385 W Hwy 44 Nuevobarrio and Camino del		Sandoval	35.320337		transformer oil leak		soil excavation	closed	
PNM Transformer oil spill	Pueblo	Bernalillo	Sandoval	35.310237	-106.55292	40 gal of transformer oil spilled	4/18/2000	soil excavation removal via SWB	closed	8/8/2000
Richard Martinez property	35 Guadalupe St	Bernalillo	Sandoval	35.310237	-106.55292	trash, sewage, use oil spill on domestic property	pre 2/2/05	oversight	closed	9/8/2006
Arroyo del Tuerto	N 35 23.159; W 106 18.138	BLM land	Sandoval	35.3858	-106.3022	report of dumped sludge	pre 2004	discharge was old molasses to attract wildlife for poaching. BLM removed the molasses.	closed	2/15/2004
Corrales Domestic Well Results	Corrales	Corrales	Sandoval	35.239335	-106.622588	Domestic well sampling throughout community	6/27/1995	Report to community resulted in partial sewer line installation		
Former Duke City Lumber	1/4 mile from CR 11, 1 mile SE of Cuba	Cuba	Sandoval			diesel contaminated soil	Aug-99	soil removal	closed	9/10/1999
Jemez Pueblo Water System	Jemez Pueblo	Jemez	Sandoval	35.606401	-106.737633	NMED invited to assist in water system contaminants	Jul-92	sample collection and consultation	closed	Jul-92
Jemez Valley HS	Canon by Jemez pueblo	Jemez	Sandoval			transformer oil spill	1994	soil excavation	closed	
Placitas Landfill	41 Dusty Trails Dr.	Placitas	Sandoval	35.311765	-106.498968	neighborhood concern of leachfields over former landfill	pre 1989	soil sampling and liquid waste and well data review showed no impact	inactive	5/7/2007
Roberts Oil Truck spill - Regina	NM 96, MP 6.3	Regina	Sandoval	36.194414	-106.942162	Tanker truck accident caused soil contamination in arroyo	11/1/00	soll excavation and assessment	inactive	6/10/2010
Evanston Home	2100 Gazelle Rd	Rio Rancho	Sandoval	35.269519	-106.695733	resident was concerned city water was impacted home	2003	water samples and inspection revealed problem was due to construction	closed	6/25/2003
KL Stevens Co.	300 B Frontage Rd	Rio Rancho	Sandoval	35.286948	-106.716105	report petroleum and metal polishing waste discharges	pre 11/06	joint inspection with HWB showed no evidence of discharge. HWB followed up on haz waste disposal	closed	12/1/2006

-	New	Mexico Envii	ronment	Department	- Ground Wa	ater Quality Bureau - Closed/Inactive St	ate Clean Up S	Sites		
2	may vary. Coordinates may have be		ng google ea	rth, but other less	accurate methods	may have been used .				
	ty, then alphabetically by Site Name. wrther action or CAB approved, or re		program for	nrocessing such a	SOS/CERCIA HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	may be archived or t	ransferred with the referral		
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date
NM Utilities	Rd 528 and Sandoval County line	Rio Rancho	Sandoval	35.286948		5000 gal sewage spill	5/16/1994	sewage recovery and	closed	7/15/1994
PNM Transformer oil spill	1977 Lee Loop	Rio Rancho	Sandoval	35.284772		transformer oil leak	5/16/2011	disinfection soil excavation	closed	6/14/2011
Rio Rancho sewer line break	500 ft south of Co. Line St Rd 528	Rio Rancho	Sandoval	35.286948		sewer line manhole overflow, ~5000 gallons	5/17/1994	removal	closed	7/15/1994
Rio Rancho Sewer line Installation	Main Feed Sewer Line manhole							line was video taped and		
Testing Rio Rancho WWTP sewer line	#5 and #6	Rio Rancho	Sandoval	35.286948		alleged sewer line test was rigged	Jun-93	no evidence of leakage soil excavation and	closed	8/1/1994
break	Montoyo Arroyo and Hwy 528	Rio Rancho	Sandoval	35.286948	-106.716105	due to large storm seware line broke.	8/5/2006	sampling	closed	9/30/2006
Sunco Sign Lighting Co. Truck Accident	100 Frontage Rd	Rio Rancho	Sandoval	35.257784	-106.640747	truck accident lost 100 gal of gasoline	1/22/1998	soil excavation	closed	3/30/1998
Willow Creek Bosque, Rio Rancho Bosque	Rio Rancho Open Space	Rio Rancho	Sandoval	35.286948	-106.716105	shallow MWs showed high TDS	unknown	sampling of MWs and no identification of RP	closed	7/30/2006
Rosario Sludge Compost Plant	Santa Domingo Pueblo	Santo Domingo	Sandoval			proposed sludge composting plant		Comments on proposed plant	closed	7/1/1993
Arroyo Largo Mercury	T14N, R6E, S25.343		Sandoval			Concerns over mercury in soils in arroyo	4-1-992	soil sampling showed ND	closed	5/1/1992
Gary Williams Energy Truck Accident	Hwy 44 mile 55		Sandoval			truck accident	Dec-89	soil excavation	closed	2/1/1991
L-Bar Ranch	40 miles NW of Rio Rancho		Sandoval			ENTS 7774 showed spillt diesel in low volumes at a pump jack domestic well and leaking barrels of used oil	unknown	soil excavation and P2 measures on pump jack; soil excavation around leaking barrels	closed	6/10/2011
Mesa Gravel Inc	Arroyo Seco	Arroyo Seco	Santa Fe			diesel and oil spilled during gravel mining	pre 93	samples	closed	7/1/1994
NMDOT Cuyamungue	Mystic Lande, east of US84, 1/2 mile north of mile marker 177	Cuyamungue	Santa Fe	35.866691	-106.008022	Surface spill from diesel AST entered MW-2	6/1/1999	spare and vent, LNAPL recovery, soil excavation	closed	5/31/2006
Bennies Gulf Station	525 Riverside Dr.	Española	Santa Fe	35.98828	-106.064106	referral from PSTB about old leaky ASTs		NOD sent 7-7-95	inactive	
El Llano Landfill	2 mi E of Rio Grande and Española	Española	Santa Fe			report of GW concerns from landfill	Jul-89	referred to SWB since closed after 5-89	closed	
La Bajada Mine	Santa Fe River Canyon, La Bajada Hill	La Bajada	Santa Fe	35.54944167	-106.20791944	sulfate, TDS, Ur - MW3 exceeds standardsTDS, Sulfate and Ur in MW-3 continue to exceed WQCC HHS standards. TDS and sulfate concentrations have decreased since prior sampling, Ur concentrations have increased	Pre 1950s	Mine Reclamation performed ~1997-1999	Referred to MECS. File transferred 4/8/16	4/8/2016
La Cienegia Nitrate Study		La Cienega	Santa Fe	35.624764	-106.026378	Concerns about CSF WWTP	9/1/1999	Analytical results showed below regulatory levels	closed	9/1/2000
Ellis Well	Near Lamy Junction	Lamy	Santa Fe	35.485056	-105.884353	suspected domestic well contamination	1986	results showed no contamination	closed	6/8/1986
Sutters Trucking, Pojoaque	US 84/285 & SFCR 103	Pojoaque	Santa Fe	35.894657	-106.015167	tanker truck spill of 7000 gal gasoline.	1998	soil excavation and LNAPL recovery in cooperation with Pueblo	closed	6/26/2000
Santa Nino Lane	Santa Nino Lane	Santa Cruz	Santa Fe	35.994874		Domestic well sampling event	1985	samples collected	closed	1985
Affordable Housing Associates Army reserve Center	158 Calle Lazo Errante Santa Fe	Santa Fe Santa Fe	Santa Fe Santa Fe	35.670974 35.670974		hydrocarbon soils discovered 20 gal diesel spill	pre 2001 9/21/1995	soil excavation	closed closed	8/9/2001 9/21/1995
Associated Asphalt & Materials	3810 Oliver Rd	Santa Fe	Santa Fe	35.670974		300 gal of used oil spill	4/1/1995	soil excavation	closed	3/26/2003
Berridge Distributing Co	1255 Cerrillos Rd	Santa Fe	Santa Fe	35.673615		former bulk plant	10/27/1995	soil excavation	closed	12/6/1995
Buckman Well #8 Transformer spill		Santa Fe	Santa Fe			transformer 100 gal spill	1999	soil excavation	closed	3/10/2000
CAMPR Partners Ltd	1061 Pen Rd	Santa Fe	Santa Fe	35.676346		hydrocarbon soils discovered	pre 1992	soil excavation	closed	3/20/1992
CAMPR Partners Ltd	1096 St. Francis Dr.	Santa Fe	Santa Fe	35.716328		hydrocarbon soils discovered	pre 1992	soil excavation	closed	3/20/1992
Canoncito Area Capital Scrap Metals	Canoncito Area 1162 Cooks Ln	Santa Fe Santa Fe	Santa Fe Santa Fe	35.663722 35.647034		low levels of Atrazine found in water samples contaminated soil from car crushing operations	7/6/1987 pre 1999	resampled showed ND soil excavation	closed closed	12/1/1987 11/9/1999
Capshaw Jr. High Water Well	St. Francis and East Zia Rd	Santa Fe	Santa Fe	35.670974		Water Investigation at Jr. High School	6/1/1989	Corrected school's plumbing and disinfected water line	closed	7/1/1989
Catellus Development Corp.	SF well (Baca St)	Santa Fe	Santa Fe	35.662256	-105.991448	6 drums of used oil dumped near CAT-1 well	12/16/1996	removal and soil	closed	5/14/1997
Copola Concrete Supply	2820 Industrial Rd	Santa Fe	Santa Fe	35.670974		AST spill released diesel	pre 8/99	excavation soil excavation	closed	10/25/1999
DOT Santa Fe	St. Michaels and Old Pecos Trail	Santa Fe	Santa Fe	35.688537		weathered hydrocarbons found at site from past DOT	7/13/1993	soil excavation	closed	6/15/1994
Edwin Hyde	1708 Paseo de la Conquistadora	Santa Fe	Santa Fe			activities used oil spill	7/26/2000	soil excavation	closed	12/27/2002
Eldorado Domestic Well	1 Azul Loop	Santa Fe	Santa Fe	34.166233		Benzene detected in domestic well	4/1/2010	resampling showed benzene below standards. ND in all neighbor domestic wells	closed	5/1/2010
Exxon Station 6-7231	2045 Cerrillos Rd	Santa Fe	Santa Fe	35.662774	-105.977086	petroleum contamination	unknown	Settlement Agreement directed remediation	closed	1/3/1989
former Eberline - Thermo Fisher	5981 Airport Rd	Santa Fe	Santa Fe	35.637054		in the process to develop a decommissioning plan to terminate radioactive materials license, soil samples were collected	unknown	soil results showed no threat to GW	referred to HWB	7/7/2009
Garcia Honda	607 Cerrillos	Santa Fe	Santa Fe	35.6823	-105.945349	used oil LUST site	12/11/1989	soil excavation	closed	7/26/1990
23 of 26										6/12/201

	New N	lexico Envi	ronment	Department ·	- Ground Wa	ater Quality Bureau - Closed/Inactive S	tate Clean Up S	Sites						
	ntitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used . tes are listed by city, then county, then alphabetically by Site Name. atus may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.													
2		erred to another	program for	nrocessina such as	SOS/CERCIA HW	R/RCRA_SWR/RCRA etc_Eiles for sites closed prior to 200	0 may be archived or tr	ansferred with the referral						
Site Name ²	Location	City ²	County ²	Latitude ¹		Event	Discharge Date	Action Taken	Status ³	Date				
Geizer Domestic Well	Rt 5 Box 3600	Santa Fe	Santa Fe	35.670974		suspected domestic well contamination	Jan-83	Analytical results showed	closed	5/1/1983				
General Parts Inc.	Rt 6, 89A Agua Fria Rd	Santa Fe	Santa Fe	35.670974		drums of petroleum hydrocarbons	Dec-93	below regulatory levels drum removal by HWB	closed	6/16/1996				
Jiffy Lube	1975 Cerrillos	Santa Fe	Santa Fe	35.663583		500 gal tank overflowed with windshield wash containing		City removed 35 gal	closed	6/27/2005				
La Puerta Origin Ltd	4523 State Hwy. 14	Santa Fe	Santa Fe	35.679508	-105.955765	isopropyl alcohol	pre 11/22/04	soil excavation	closed	12/10/2004				
Martha Frank Water Sample	704 Onate Place	Santa Fe	Santa Fe	33.079300		Complaint of odors in water system	11/1/1989	samples were below	closed	12/21/1989				
	104 Onale Flace	Santa i e	Santa i e				11/1/1909	detection limits	ciosed	12/2 1/ 1909				
Masters Cleaners	238 Sandoval St.	Santa Fe	Santa Fe	35.68626	-105.943017	Phase 2 showed PCE of 12 mg/kg at 1-5 ft.	unknown	3 soil borings to 50 and 100 ft showed no GW and ND for VOCs, soil vapor at 25' showed 19 ug/lair.	closed	1/18/2006				
One Hour Martinizing, Santa Fe, WIRTCO	1091 St. Francis Dr.	Santa Fe	Santa Fe	35.674314	-105.953562	Release of PCE from Dry Cleaners	unknown	assessment	transferred to VRP	3/9/2018				
Osage Well		Santa Fe	Santa Fe			Soil sampling showed <100 ppm TPH	6/1/1995	no corrective action required	closed	7/5/1995				
Paradise Trucking	I-25 and Exit 294	Santa Fe	Santa Fe	35.670974		truck accident lost 100 gal of diesel	8/20/1999	soil excavation	closed	1/13/2000				
Phase One Realty PKG Building	Tano Rd and N. Ridgetop Rd 218 Montezuma	Santa Fe Santa Fe	Santa Fe Santa Fe	35.684341		kerosene spill indoor air and soil vapor showed low levels of CCI2F2	4/9/2001 1984	soil excavation	closed closed	2/28/2002 6/15/1984				
PNM Transformer oil spill	United Parcel Service on Camino	Santa Fe	Santa Fe			transformer oil spill	4/11/1994	soil excavation	closed	4/19/1994				
Pojoaque Pueblo Well Report	Ortiz Pojoaque Pueblo	Santa Fe	Santa Fe	35.670974		Domestic well sampling RE: Uranium		Domestic well report	closed	1/1/1998				
Quick Car Wash #8	995 Rodeo Dr.	Santa Fe	Santa Fe	35.638859	-105.934851	dumping of petroleum contaminated soil	12/29/1999	soil excavation	closed	2/2/2000				
Rabbit Rd Soil	253 Rabbit Rd	Santa Fe	Santa Fe	35.62786	-105.95551	Concern of creosote runoff from RR ties	5/27/2009	Sample results showed concentrations below guidance levels	closed	7/14/2009				
Robertson Well	T15N, R8E, S25.234	Santa Fe	Santa Fe			Domestic Well sampling	5/1/1987	Sample results showed low results	closed	5/1/1987				
Rocky Mt. Motors	4480 Cerrilos Rd	Santa Fe	Santa Fe			hydraulic lift contaminated soil	pre 1998	soil excavation	closed	5/22/1998				
Ruben Well	Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros	Santa Fe	Santa Fe			PCE discovered in domestic well	pre1997	CERCLA conducting an investigation to discover sources ampling of domestic wells in area. No source or RP identified. Concentrations have decreased over time.	referred to SOS					
Santa Fe Beaver Reintroduction by Forest Guardians	312 Montezuma	Santa Fe	Santa Fe	35.684628		beaver dam created by beaver reintroduction project creating diversion of potentially contaminated water making a reported threat to residents	unknown	investigation showed no ground water concerns	referred to SWQB	2/1/2014				
Santa Fe Chevrolet	4450 Cerrilos Rd	Santa Fe	Santa Fe	35.629593	-106.023096	motor oil release from an oil water separator	pre 1998	soil borings showed low levels of contamination	closed	6/17/1998				
Santa Fe County Groundwater Study		Santa Fe	Santa Fe	35.641931	-105.960488	Groundwater analsys of well across county	9/1/1986	Report to county commission	closed	9/1/1986				
Santa Fe County Maintenance Yard	2600 Galisteo	Santa Fe	Santa Fe	35.670974	-106.001899	diesel fuel LUST	Apr-07	soil borings	closed	3/4/2002				
Santa Fe KOA campground	Rt 3 Box 95-A	Santa Fe	Santa Fe	35.670974	-106.001899	nitrate up to 11 ppm in well	pre 1996	refer to DWB	closed					
Santa Fe Racing Landfill	Santa Fe Racetrack	Santa Fe	Santa Fe			sampling of domestic wells to evaluate impact of manure		sample results and refer to						
Santa Fe Summit Homeowner's Association	Bent Hill Rd. and Summit Dr.	Santa Fe	Santa Fe			landfill at least 3 sewage spills due to grinder pump failure	pre 2006	SWB equipment repair, best management practices established, certified operator hired	closed	5/25/2007				
Santa Fe WWTP	Santa Fe	Santa Fe	Santa Fe	35.670974	-106.001899	sampling of domestic wells near WWTP	Mar-87	none, no results above stds.						
SDC Country Club Estates Well		Santa Fe	Santa Fe			Sangre de Cristo's well showed PCE	1993	investigation showed PCE came from water system and not aquifer	closed					
Southwestern College	3952 San Felipe Rd	Santa Fe	Santa Fe	35.636340°	-106.053093°	Soil contamination from leaking heating oil UST	3/19/2015	soil excavation	closed	5/8/2015				
Sullivan well testing	Rt 7 Box 113-S	Santa Fe	Santa Fe	35.670974	-106.001899	Domestic well sampling	1/10/1990	sample results showed high sulfate and TDS	closed	1/23/1990				
Wilfred Padilla Fina	624 Old Las Vegas Hwy	Santa Fe	Santa Fe	35.634111	-105.92582	Reports of RV sewage dumping in a PSTB monitoring well	pre April 2007	allegations of disposing of RV waste into a monitoring well could not be confirmed	closed	4/1/2007				
Santa Fe Airport Jet fuel release	1000 ft N-new of runway 33	SF County Airport	Santa Fe			350 gal of jet fuel from accident	2/1/2000	soil excavation	closed					

4						ater Quality Bureau - Closed/Inactive S	tate Clean Up Si	tes		
	may vary. Coordinates may have be		ng google ear	th, but other less o	accurate methods	may have been used .				
² Sites are listed by city, then count	ty, then alphabetically by Site Name									
³ Status may consist of closed/no f	urther action or CAR approved, or re	eferred to another	program for p	processing such as	SOS/CERCLA, HW	B/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000	0 may be archived or tra	nsferred with the referral.		
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Rancho Encantado	St. Rd 592	Tesuque	Santa Fe	35.753513	-105.915371	heating oil release from LUST	pre 1995	soil excavation and subsurface soil samples allowed some TPH to remain in place	closed	4/20/1995
Tesuque Environmental Survey	Tesuque Valley	Tesuque	Santa Fe	35.753513		Survey showed domestic well impacts of fecal colliform and nitrate	5/1/1974	eventual connection to WWTP	closed	
Tesuque Hill Diesel Spill	Hwy 285 near flea market	Tesuque	Santa Fe			50 gal of diesel spill from truck accident	8/16/1999	soil excavation	closed	9/22/1999
Thompson Water Well	Rt. 5 Box 266B	Tesuque	Santa Fe			petroleum contaminated runoff	3/1/1998	Soil Excavation	closed	5/1/1998
El Paso Electric Co.	I-25 & Exit 59	Arrey	Sierra	32.847659		hydraulic fuel	10/17/2007	soil excavation	closed	7/3/2008
Caballo Emergency Truck Repair	I-25, exit 63	Caballo Caballo	Sierra	32.978676		motor oil spill junk area with tar sludge, solid waste	discovered Dec. 2007	soil excavation soil excavation	closed	4/10/2009 8/11/1995
Evergreen Farm Swift Transportation	HC 32, Box 31 I-25 Exit 89	Caballo	Sierra Sierra	34.166233		Truck Accident - release of 80 gal of diesel - ENTS#3803	pre 1994 Dec,7 2008	soil excavation	closed closed	2/15/2009
Porter Oil	I-25 and mile 57	Derry	Sierra			ENTS#3803 8000 gal of gas spill from truck accident	6/3/1992	soil excavation and MNA	closed	6/21/1999
Naval Space Surveillance Station	38 miles NE of Tor C	Elephant Butte	Sierra	33.183165		TPH surface soils	pre 1998	of GW soil excavation	closed	1/15/2003
Turtleback Mtn. Partners	120 Stagecoach Drive	Elephant Butte	Sierra			discharge of water exceeding Mn std.	1/16/07	installation of monitor wells and sampling	closed	7/8/2008
Hanna Towing	Co. Rd. B-076	Las Palomas	Sierra	33.059489	-107.297054	inspection revealed gasoline and oily contaminated soil	unknown	soil excavation and sampling; final report not yet submitted	inactive	1/5/13
Martin Motors	Co. Rd. B-076	Las Palomas	Sierra	33.059489	-107.297054	inspection revealed gasoline and oily contaminated soil	unknown	soil excavation and sampling; final report not yet submitted	inactive	1/5/13
Chavez Property	1409 N. Date	Truth or Consequences	Sierra	34.166233	-106.026069	tack oil spill	3/12/07	soil excavation	closed	3/21/2007
Loughridge Spill	N. Hwy. 181 (north of Desertaire Estates, Lot #24)	Truth or Consequences	Sierra	34.166233	-106.026069	spillage of diesel fuel from old tank	12/16/04	soil excavation	closed	Mar. 2005
Stovall residence	1365 E.Riverside	Truth or Consequences	Sierra	34.166233	-106.026069	excavation of unregulated UST	pre-1970	removal of tank and confirmatory sampling	closed	3/6/2006
Chevron Redi-Mart	Broadway and Van Patton	Williamsburg	Sierra	33.113028	-107.293657	Utility pole excavation discovered release	pre 1987	refined petroleum-all types	regulated by PSTB	10/6/1997
Essery Scrapyard	Animas Creek		Sierra			55-gal barrels and burning of electrical wires	pre 1992	soil sampling	closed	6/14/1993
Bailey Well		Lemitar	Socorro			Determination of cause of anerobic domestic well downgradient of DP-108	1981	sampled well and below laboratory detecting limits	closed	1981
Prime Inc. Truck Accident	I-25 South bound Mile 158	Lemitar	Socorro	34.155235	-106.91183	truck accident caused 80 gal of diesel spill	8/7/2009	soil excavation and sampling	closed	6/23/2009
Magdalena Airport	Magdalena	Magdalena	Socorro	34.107071	-107.234449	old well show low levels of BTEX	1998	sampling in 2003 showed no contamination	closed	6/25/2002
USFS Magdelena	203 1st St	Magdalena	Socorro	34.121087	-107.232156	discovery of heating oil release	unknown	monitoring	inactive	
Village of Magdalena	103 Chestnut St.	Magdalena	Socorro	34.119092	-107.238868	500 gal of sewage spill	8/24/1998	repair sewer and disinfect soil	closed	9/23/1998
BNSF Derailment Bosque del Apache NWR	10 miles south of San Antonio	San Antonio	Socorro			derailment released ~56,938 gallons of Vacuum Gas Oil	7/27/2010	soil excavation, LNAPL recovery, soil and ground water investigation	closed	8/31/2011
BNSF San Antonio Derailment	1 mile N. of San Antonio	San Antonio	Socorro			1000 gal of diesel spilt during locomotive derailment	9/18/1998	soil excavation, LNAPL removal, and MNA	closed	12/1/1999
BNSF San Antonio Lube Oil Spill	1/2 mile S. of San Antonio	San Antonio	Socorro			Locomotive engine block failure caused 25 gallons of lube oil release	6/30/2007	soil excavation and sampling	closed	7/3/2008
USFW Bosque del Apache	1001 Hwy 1	San Antonio	Socorro	33.915168		discovery of 250 gal of diesel release for a builling heater	unknown	soil and ground water analysis showed no impact	closed	9/15/2010
Circle W Station L&L Gas and Oil	1104 S. California 716 Bagley St	Socorro Socorro	Socorro Socorro	34.071647 34.049433		200 gal of diesel spill and 500 gal of water spill of gasoline and diesel while unloading	7/29/1998 10/8/1996	soil excavation soil excavation	closed closed	9/20/1998 1/17/1997
Socorro Armory	NM Army National Guard, BTRYA,	Socorro	Socorro	34.060462		460 gallon diesel spill	2/13/1997	soil excavation	closed	5/15/1997
SW Tire	3rd Battalion 1001 Grefco	Socorro	Socorro	34.060462		Tire fire in 2000 caused soil contamination	5/1/2000	GWQB installed MWs for SWB and has conducted annual sampling of	referred	6, 10, 1001
Ogleby Mica Mine	T23N, R12E, S24	Picuris Pueblo	Taos			Discovery of petroleum contaminated soil from former mica mine.	unknown	groundwater soil excavation and referral to GWQB's Mininng Env. Compliance Section	referred	9/2/2008
Burtis Property, Former Scheid Motor	237 Paseo del Pueblo Sur	Taos	Taos	36.402432°	-105.574540°	NMDOT PSI indentified TPH impacts to ROW, but no individual constituents above standards in groundwater. No assessment of potential chlorinated vapors of remainder of property.	unknown	assessment only	closed	3/6/2018
Exxon Station 6-7241	501 Paseo del Pueblo Norte	Taos	Taos	36.38925	-105.581578	BTEX plume from lust		remediation system	closed	11/13/2001
Navajo Express Diesel Spill	next to McD	Taos	Taos	36.38925	-105.581578	200 gal of diesel spill	12/16/2004	soil removal	closed	1/10/1995

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites												
Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used .												
Sites are listed by city, then county, then alphabetically by Site Name.												
Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.												
Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date		
Taos Area Domestic Nitrate Study		Taos	Taos			Domestic Well Sampling	1986	Sampled Domestic wells	closed	1986		
Taos Drug Lab	Weimar and Talpa Rd	Taos	Taos	36.38925	-105.581578	3 methylene chloride in soil	pre 88	remediation and soil removal via HWB funds	closed	8/24/1993		
Taos Ski Valley		Taos Ski Valley	Taos			AST and LUST sites	pre 95	soil excavation	closed	10/19/1995		