

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 4/13/2020													
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC). Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.													
Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
312 Central Ave NE	12210	312 Central Ave NE	Albuquerque	Bernalillo	35.08341100	-106.64401000	<1	PCE	unknown	unknown	Soil and Soil Vapor	CAR 1203.A	needs further assessment
8635 Rio Grande Boulevard	12210	8635 Rio Grande	Albuquerque	Bernalillo	35.183956°	-106.645014°	<1	petroleum	unknown	unknown	Soil	Submission required	Needs further assessment
8915 Adams St Ne	12210	8915 Adams St NE	Albuquerque	Bernalillo	35.18724400	-106.595103	<1	PCE	120	unknown	Soil and Soil Vapor	CAR 1203.A	Needs further assessment
Acoma Business Enterprises - Carnuel	Ball	I-40 overpass of NM-333, east of Carnuel	Carnuel	Bernalillo	35.065803°	-106.424571°	<1	gasoline and diesel	6	unknown	bedrock	Stage 1 AP	Needs further assessment
BNSF Albuquerque	Herrell	Between Copper and Iron; 1st and Edith	Albuquerque	Bernalillo	35.08051500	-106.64805100	54	diesel	35-90	east	soil and GW	Voluntary Stage 1 AP	Additional Site Investigation pending
Chava Trucking	Herrell	6313 State Rd. 47 (6020 Industrial Way) SE	Albuquerque	Bernalillo	34.99354722	-106.66135833	15	petroleum hydrocarbons	40-65	E	Soil and GW	Settlement Agreement	Excavation, soil investigation
Chevron Bulk Fuels Terminal (FORMER)	Herrell	3200 Broadway SE	Albuquerque	Bernalillo	35.04656000	-106.64610800	9	petroleum hydrocarbons	25	east	Soil and GW	Hydrocarbon Remediation Agreement	Monitored Natural Attenuation (MNA) Semi-annual GW monitoring.
ConocoPhillips South (formerly Phillips Pipeline)	Chamberlain	6356 State Rd. 47	Albuquerque	Bernalillo	34.99101944	-106.65957222	10	diesel, BTEX, EDC	80	E	Soil and GW	Admin Compliance Order / Stage 2 AP	Semi-annual GW monitoring; Proposed Abatement options under review
Davis Cleaners	12210	2906 Juan Tabo NE	Albuquerque	Bernalillo	35.114673	-106.514196	1	chlorinated solvents	700	unknown	Soil Vapor	CAR 1203.A	Needs further assessment
Digital/Compaq/HP (Former)	12210	5600 Jefferson NE	Albuquerque	Bernalillo	35.14318333	-106.59482500	50	TCA, DCE	170-250	SE	GW	Admin Order Consent (AOC)	Semi-Annual Monitoring
Fox & Associates	12210	3412 Bryn Mawr Drive NE	Albuquerque	Bernalillo	35.12080278	-106.60924444	1	TCE	50-220	E	Soil and GW	Stage 2 AP	SVES operated March 2009-2012, Annual GW monitoring. AP area defined as regional plume. Source property abatement completed
GTE Lenkurt/Copper Pointe Facility	12210	10500 Copper Ave NE	Albuquerque	Bernalillo	35.080006	-106.53236700	47	PCE	600	unknown	Soil vapor and GW	CAR 1203.A	Needs further assessment. Phase 2 work revealed soil vapor intrusion with chlorinated solvents.
Gulton Industries	Herrell	14800 Central Avenue SE	Albuquerque	Bernalillo	35.06375000	-106.48549444	10	TCE	20-120	E	GW	Consent Decree	In-situ bioremediation with injection of HRC® under Discharge Permit.
Holiday Park Cleaners	12210	2917 Juan Tabo NE	Albuquerque	Bernalillo	35.115684	-106.516069	1	chlorinated solvents	700	unknown	Soil Vapor	CAR 1203.A	Needs further assessment
KAFB Sewage Spill	12210	Randolph Ave and Fuel Drive	Albuquerque	Bernalillo	35.050917	-106.578931	2	nitrate, sulfate, chloride	400	NW	GW	CAR 1203.A	Needs further assessment
KAFB ST-105 Nitrate Plumes	12210	Near Wyoming and Randolph	Albuquerque	Bernalillo	35.04956389	-106.56965000	200	nitrate	250-550	various	GW	Stage 2 AP	Stage 2 AP Modification Requested by NMED Fall 2015. Current approved plan is pump and use for Plume 1 and MNA for other plumes.
Karler Packing (Former)	Ball	9151 Broadway SE	Albuquerque	Bernalillo	34.96129400	-106.66127300	50	nitrate	65	SE-E	GW	Stage 1 AP INACTIVE	Inactive due to Bankruptcy.
Laun-Dry Company, Inc	Ball	1500 12th St NW	Albuquerque	Bernalillo	35.10255556	-106.65795833	90+	PCE, TCE, Cis & trans DCE	35	E	Soil and GW	Stage 2 AP	Enhanced in-situ bioremediation with MNA and Long Term Monitoring

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 4/13/2020													
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC). Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.													
Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Los Angeles Landfill	Herrell	Paseo Del Norte and North Diversion Channel	Albuquerque	Bernalillo	35.18118333	-106.78078056	200	VOCs	120	E-SE	Soil and GW	Voluntary Stage 2 AP	Dissolved phase pump and treat, SVE, air sparging. Source control with landfill gas extraction and soil vapor extraction.
McCatharn Dairy	Ball	6363 State Rd. 47	Albuquerque	Bernalillo	34.98839900	-106.65918300	25	TDS, chloride, nitrate	80	E-SE	Soil and GW	Stage 1 AP FSIR	S2AP due
Mt. View Nitrate plume	Chamberlain	2nd St. and Tijeras Arroyo	Albuquerque	Bernalillo	35.00242778	-106.66257778	>500	nitrate	40-120	E	Soil and GW	ONRT project	MNA, annual monitoring
NuStar Albq Terminal	Chamberlain	6738 State Rd. 47	Albuquerque	Bernalillo	34.99199065	-106.65709655	15	diesel, gas	100	E-SE	GW	Stage 2 AP	LNAPL recovery and MNA
Petroglyph Plaza Dry Cleaner	Chamberlain	8201 Golf Course Rd	Albuquerque	Bernalillo	35.177291°	-106.688349°	<1	chlorinated solvents	unknown	unknown	soil vapor	CAR 1203.A	Needs further assessment; SVE performed
Prices Dairy (Former)	12210	618 Highway 528	Bernalillo	Bernalillo	35.31506500	-106.57204100	50	TDS, chloride, nitrate, sulfate	25 and 85	E-SE	GW	Stage 2 AP	Surface soil remediation completed under VRP. Groundwater extraction performed. Alternative Abatement Standards (AAS) Petition approved by WQCC.
Rek Chem	12210	105 Dale St. SE	Albuquerque	Bernalillo	35.00298056	-106.66074167	3	TCE	55	E	GW	Stage 1 AP SI	4 MWs, more site investigation needed.
Sparton Technologies	Herrell	9621 Coors Blvd NW	Albuquerque	Bernalillo	35.18955278	-106.66187222	500	TCE, chromium	90-220	W-NW	Soil and GW	Consent Decree	Ground water pump and treat. NMED HWB is lead.
United Petroleum Transport - Broadway and I-25	Ball	Broadway SE	Albuquerque	Bernalillo	34.95313800	-106.66215700	<1	gasoline	unknown	unknown	soil	CAR 1203.A	Excavation, soil investigation
UNM well 5	Chamberlain	UNM Main Campus	Albuquerque	Bernalillo	35.08402778	-106.61803333	20	TCE	300	N-NE	GW	Voluntary Stage 1	Semi-Annual Monitoring
Western Terrace	12210	Powers Way and Murchenson	Albuquerque	Bernalillo	34.97418333	-106.7293056	50	nitrate	70-120	S-SE	GW	No RP identified ORPHAN SITE - INACTIVE	Probable source is septic tank/drain fields or former dairy
AmeriPride	Chamberlain	515 North Virginia Avenue	Roswell	Chaves	33.39789800	-104.52082300	<5	BTEX, PCE, TCE, cis1,2-DCE, VC	15-20	E/NE	Soil and GW	Stage 2 AP	Semi-Annual Monitoring; ISCO injections are being evaluated
Helena Chemical, Lake Arthur	Chamberlain	504 Lake Arthur Highway	Lake Arthur	Chaves	32.93167500	-104.38724722	3	nitrate, TDS	20-25	E	Soil and GW	Stage 2 AP	Source removal and BMPs; MNA Semi-annual
Walker AFB	12210		Roswell	Chaves	33.307559	-104.517753	>2,000	TCE	40-120	E	Soil and GW	DOD Potential Responsible Party	NMED is waiting on eventual Federal Court decision for a determination of settlement amount that must precede further assessment of the site for abatement.
TA - Petro Truckstop, Milan	Herrell	I-40 & Horizon Blvd.	Milan	Cibola	35.18240800	-107.90090000		diesel	100+		Soil	CAR 1203.A Conditional NFA	Inactive - Final source removal to be performed when AST is taken out of service
Hooter Browns (aka ELCO Mfg. Inc), Raton	12210	931 Clayton Road	Raton	Colfax	36.88546400	-104.42839300	<5	chlorinated solvents	25	S-SE	Soil and GW	Stage 1 AP INACTIVE	Inactive due to Bankruptcy.
USDA Forest Service, Shuree Ponds	Herrell	Valle Vidal Unit, Carson National Forest	Shuree Ponds	Colfax	36.77097100	-106.19420000	25	diesel (iron and manganese)	5-10	E-SE	GW	Stage 1 AP SI	Quarterly GW monitoring

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 4/13/2020													
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC). Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.													
Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Comet Cleaners - Las Cruces	12210	2001 E. Lohman	Las Cruces	Doña Ana	32.31107400	-106.756651	<1	PCE	120	unknown	Soil Vapor	CAR 1203 A	Needs further assessment
Crop Production Services (former Agriliance), Vado	Chamberlain	8601 Highway 478	Vado	Doña Ana	32.11561400	-106.66533900	2	nitrate, TDS, fluoride, Fe, Mn	9.00	SE	Soil and GW	Stage 2 AP	Enhanced ISBR injections
Crop Production Services (former UAP), Vado	Chamberlain	8524 Highway 478	Vado	Doña Ana	32.11475560	-106.53331110	2.6	nitrate, TDS, fluoride, Fe, Mn	10	SE	Soil and GW	Stage 2 AP	MNA, semi-annual monitoring
DeGraaf/Wholesome Dairy (Former)	Herrell	Acosta Rd.and I-10	Anthony	Doña Ana	32.01616667	-106.59030560	unknown	nitrate, Cl, TDS	46-116	SW	Soil and GW	Stage 1 AP SI	Stage 1 AP Site Investigation for nitrates, chloride, TDS
Helena Chemical, Mesquite	Chamberlain	251 John Grisham Drive	Mesquite	Doña Ana	32.16449444	-106.69751944	14	nitrate, TDS	10	S	Soil and GW	Stage 2 AP	Stage 2 Remediation/Abatement - Enhanced biodenitrification with soil excavation / source removal
Santa Fe Pacific Pipeline (SFPP) Spill - Anthony	12210	near 4217 3 Saints Road	Anthony	Doña Ana	32.06152500	-106.649422	7	gasoline; 1,4-dioxane	10-12	unknown	Soil and GW	CAR 1203.A	Kinder Morgan addressing source in soil by excavation. GW needs further assessment.
SFPP Falc Trucking Yard	12210	Two areas: 435 E. Joy Drive and 32.038181, -106.613336	Anthony	Doña Ana	32.039753 32.038181	-106.609678 -106.613336	1	gasoline; 1,4-dioxane	12-15	unknown	Soil	CAR 1203.A	Needs further assessment
Sierra Vista Growers, La Mesa	Chamberlain	12701 Highway 28	La Mesa	Doña Ana	32.08773056	-106.68566940	unknown	nitrate, Cl, TDS	10	unknown	GW	Stage 1 AP	GW monitoring for nitrates, Cl, TDS.
911 West Main, Artesia	Herrell	911 West Main, Artesia	Artesia	Eddy	32.841867°	-104.408146°	<1	chlorinated solvents	45	unknown	GW, soil vapor	CAR 1203.A	Needs further assessment
Crop Production Services (former Agriliance), Artesia	Chamberlain	103 E. Mill Road	Artesia	Eddy	32.86853800	-104.39869200	3.5	nitrate, sulfate, TDS, Cl, fluoride, Fe, Mn	24	SE	Soil and GW	Stage 2 AP	Enhanced ISBR injections
Holly Energy, Artesia	12210	US 82 (3 miles E. of Artesia)	Artesia	Eddy	32.84234722	-104.35640000	1	gas, diesel, jet fuel	8	SE	Soil and GW	Stage 2 AP	Remediation/Abatement - soil excavation, mobile dual-phase extraction, hyd. peroxide injection, GW monititoring
Loving Salt, Malaga	Chamberlain	1624 Pecos Highway	Malaga	Eddy	32.2252	-104.0720278	unknown	salt	17	S	Soil and GW	Stage 1 AP	Pending Transfer to VRP
Southwest RR	Chamberlain	Diaz Ave. and 4th St.	Hurley	Grant	32.70159100	-108.13242600	4	petroleum hydrocarbons	unknown	unknown	soil	CAR 1203.A	Needs further assessment
Ladshaw Explosives	Chamberlain	0.7 mi W-SW of Hwy 18 on W Hiap Entrance Rd.	Hobbs	Lea	32.76321200	-103.19792700	30	nitrate	60	SE	GW	Settlement Agreement - INACTIVE	Inactive due to Bankruptcy.
BNSF Gallup	Herrell	811 Roundhouse	Gallup	McKinley	35.52603889	-108.75312222	>25	diesel	7	NE	Soil and GW	Voluntary Stage 2 AP	Performing remediation, LNAPL recovery trenches and wells, MNA for dissolved phase.
Lee Ranch Coal Mine	Chamberlain	Approx. 9 miles N from 192 Rd. and Rd.556	Grants	McKinley	35.50401000	-107.64556600	3	diesel	19-58	unknown	soil	Stage 1 AP SI	Site Investigation - LNAPL perched on clay layer above GW. LNAPL recovery ongoing.
Prewitt Pit	12210	Off I-40 between Grants and Thoreau (T13N R11W, Sec. 34)	Prewitt	McKinley	35.312357	-107.98518800		unknown	190	unknown	Soil and GW	CAR 1203.A	Notification of discharge sent to RP regarding alleged buried drums. Solid Waste Bureau lead agency
NMDOT La Cueva Patrol Yard	12210	NM 518, MM 23.6	Las Vegas	Mora	35.93458000	-105.25272900	<50	TDS, chloride	5-30	SW	Soil and GW	Stage 2 AP	Source removal, MNA

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 4/13/2020													
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC). Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.													
Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
ACME Hometown Cleaners (Former)	Chamberlain	901 E. 10th St.	Alamogordo	Otero	32.90019500	-105.95112200	unknown	PCE, TCE	55-60	SW	Soil Vapor, Soil, GW	Compliance Order	SVE system and air sampling; install additional MWs and monitor
Alamogordo Terminal (Epic Midstream, NuStar/STS Energy Pipeline Terminal)	12210	6026 Highway 54	Alamogordo	Otero	32.81379722	-105.97729170	unknown	petroleum, JP-4, Jet A	70	S-SE	Soil and GW	Stage 2 AP	LNAPL Recovery with MNA. Air Sparge Pilot test ongoing
Union Pacific, Alamogordo	Herrell	S. of Lawndale and 8th St.	Alamogordo	Otero	32.89618000	-105.96573300	25	Creosote, PAHs, DNAPL	45	W-SW	Soil and GW	Stage 1 AP SI	Semi-Annual Monitoring
ATA Montoya (T4 Ranch) Valero	Chamberlain	Montoya, NM & Interstate 40	Montoya	Quay	35.12715000	-104.07488056	30-70	refined petroleum - all types	20	E	GW	CAR 1203.A	LNAPL recovery and MNA
BNSF Clovis	Herrell	Main Street, Clovis, New Mexico	Clovis	Quay	34.39589167	-103.20850556	500	diesel	300	S-SE	Soil and GW	Voluntary Stage 2 AP	Performing Remediation/Abatement - LNAPL recovery through 4 wells & DAF treatment of Groundwater to POTW for up to 7 feet of free product on groundwater.
Diamond Shamrock Endee	Chamberlain	Endee New Mexico	San Jon	Quay	35.21526944	-103.23739444	4	diesel	25	SE	GW	Stage 2 AP	LNAPL recovery and MNA
Diamond Shamrock, Tucumcari	Chamberlain	3.5 miles E-NE of Tucumcari	Tucumcari	Quay	35.20498056	-103.65754444	13	gasoline & diesel	13-70	SW	Soil and GW	Stage 2 AP	Monitored Natural Attenuation
Shell Truck Stop (AST) Tucumcari	Chamberlain	Eastern I-40 Tucumcari Exit	Tucumcari	Quay	35.15787222	-103.77209167	<3	petroleum hydrocarbons	20	NE	unknown	CAR 1203.A	Needs further assessment
Tucumcari Landfill	Chamberlain	QR65 and Q Ap	Tucumcari	Quay	35.20238100	-103.73520000	15	PCE, TCE	70	NW	Soil and GW	CAR 1203.A	Needs further assessment
Tucumcari Power Plant (Xcel Energy)	Chamberlain	301 W. Railroad Ave.	Tucumcari	Quay	35.17912778	-106.72655556	1	diesel	37	NW	GW	Stage 2 AP	LNAPL Recovery, MNA for dissolved plume
Alta Fuels Hwy 17 Tanker Truck Spill	Herrell	Highway 17, 7.5 mi north of Chama, SB (West) Lane	Chama	Rio Arriba	36.99004800	-106.50508100	1	gasoline & diesel	~45-52	unknown	Soil	CAR 1203.A	Groundwater monitoring following source removal
Comet 1 Cleaners	Chamberlain	2810 East 20th Street	Farmington	San Juan	36.7485972	-108.1687972	3	PCE	25	S	GW	Stage 2 AP	Enhanced in-situ bioremediation
Downs RV Park	Chamberlain	5701 U.S. Hwy 64	Farmington	San Juan	36.70272900	-108.10488500	unknown	TDS, chloride, nitrate	30	S-SW	GW	Stage 1 AP	Quarterly Groundwater Monitoring
Finney Refinery	Ball	#28 County Rd.5050	Bloomfield	San Juan	36.68626300	-107.99374100	4	BTX, Naphthalenes	unknown	unknown	Soil	CAR 1203.A	CAR required
Halliburton - Farmington	Chamberlain	4109 East Main Street	Farmington	San Juan	36.75803400	-108.15339700	1	heavy metals, hydrocarbons	10	unknown	Soil	CAP 1203.A	Needs further assessment
Precision Engine	Ball	1706 E. Main Street	Farmington	San Juan	36.737311°	-108.186051°	<1	petroleum, PCE, TCE	9	unknown	Soil and GW	CAR 1203.A	Inactive
San Juan Springs Company	Ball	409 East Broadway	Farmington	San Juan	36.72818900	-108.201400	<5	chromium, metals, petroleum hydrocarbons	10-12	S	Soil and GW	Stage 2 AP	In-situ bioremediation and MNA.
NMDOT District 4 Service Center, Las Vegas Patrol Yard	12210	I-25 Frontage Rd, MM 344	Las Vegas	San Miguel	35.56902900	-105.22470500	>100	TCA, DCE, TDS, chloride, BTEX, MTBE	15-40	SE	Soil and GW	Stage 2 AP	Recovery trench, RO treatment, re-injection

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 4/13/2020													
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC). Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.													
Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Conoco Phillips (AST) - Bernalillo	Herrell	Calle Duranes and railroad tracks	Bernalillo	Sandoval	35.30600000	-106.54664167	1	gasoline	7	SW	GW	Stage 2 AP	LNAPL recovery. MNA in GW.
Plains Electric/PNM, Algodones	12210	1500 NM Highway 313	Algodones	Sandoval	35.38441700	-106.46454400	45	manganese, TDS, sulfate	30-40	W-SW	GW	CAR 1203.A	Monitoring on a 5 year basis
Quality Laundry, Bernalillo	12210	107 Calle Del Presidente	Bernalillo	Sandoval	35.30547778	-106.54777500	3	PCE	6	SW	GW	Stage 1 AP	Stage 2 AP needed.
NMDOT Main Yard/GOC	Herrell	1120 Cerrillos Road	Santa Fe	Santa Fe	36.67409200	-105.95727000	5	PCE, TCE	350, 127 perched zone (2011)	W	Soil, Soil Vapor	CAR 1203.A	Vapor Intrusion assessment needed.
Ortiz Landfill (Former)	Herrell	Camino de las Crucitas and Buckman Road	Santa Fe	Santa Fe	35.69644444	-105.96433333	unknown	nitrate, VOCs	360	SE	Soil and GW	Stage 1 AP	Additional site characterization needed for GW, vapor
PNM Baca St	Herrell	North of Shoofly Street and Flagman Way, Near Baca Street and Cerrillos Road	Santa Fe	Santa Fe	35.675372°	-105.961277°	15	PSTB Regulated: LNAPL and petroleum : benzene, toluene, ethylbenzene, total xylenes, 1,2-dibromoethane EDB, EDC, naphthalene; GWQB Regulated: PCE, TCE, 1,1,-DCE, VC, MC, CTET, nitrate	240-312	Generally E to W with localized variability and a recovering cone of depression	GW	Stage 1 AP	needs further assessment, GW monitoring ongoing
Santa Fe Railyard/ConocoPhillips/La Unica Dry Cleaners	Herrell	760 Cerrillos Road	Santa Fe	Santa Fe	35.67884200	-105.95095200	<50	PCE	70-130	E	GW	Stage 1 AP	File under review.
Stone Forrest	12210	4525 Agua Fria	Santa Fe	Santa Fe	35.653291	-106.030948	1	TPH, Selenium, Lead	400	unknown	Soil	CAR 1203.A	Needs further assessment
Truth or Consequences Landfill (TorC) (Former)	Chamberlain	T13S R4W S22	T or C/Elephant Butte	Sierra	33.16299300	-107.23229700	30	NO3, Cl, Mn	12-24'	S-SE	GW	CAR 1203.A	Site Investigation/Property Transfer
Salome Property	Herrell	327 McCutcheon Ave.	Socorro	Socorro	34.05544800	-106.89531200	<1	PCBs	unknown	unknown	Soil	CAR 1203.A	Soil removal and disposal.
Veguita, Abo Valley	Chamberlain	Wheeler Rd. and State Rd. 304	Socorro	Socorro	34.52008333	-106.75120278	>100	nitrate	45	S	GW	No RP identified, ORPHAN SITE - INACTIVE	Monitoring of Orphan Plume
Travel Centers of America, Moriarty	Herrell	1700 U.S. Route 66 West	Moriarty	Torrance	35.00770800	-106.06644700	<1	Diesel	145	unknown	Soil	CAR 1203.A Conditional NFA	Inactive - Final source removal to be performed when AST is taken out of service
Dry Cleaners, Clayton	Herrell	20 Peach Street	Clayton	Union	36.45502700	-103.18734100	<5	PCE, BTEX	40-45	S	Soil and GW	INACTIVE ORPHAN SITE - No viable RP	Monitoring and SV survey needed.
BNSF Belen Fueling Facility	Herrell	106 N. 1st St.	Belen	Valencia	34.65448333	-106.76809722	>100	diesel	5 to 15	S	Soil and GW	Stage 2 AP	Performing Remediation/abatement. LNAPL recovery trenches and wells, MNA for dissolved constituents. DP-278 for evap. lagoons to receive sump wastewater. DP-1715 for injection wells to receive extracted ground water for LNAPL recovery.
Mesa Oil	Ball	20 Lucero Rd.	Belen	Valencia	34.59728900	-106.73192000	5	petroleum hydrocarbons	80	S	Soil	CAR 1203.A	Under 2010 ACO

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 4/13/2020

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC).

Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Roadrunner Laundry	12210	512 Courthouse Rd.	Los Lunas	Valencia	34.80137500	-106.73296389	<1	PCE	5	S-SE	Soil and GW	Stage 1 AP INACTIVE	5 MWs. GW sampling performed by NMED in 2007 and 2011. Abatement Completion may be possible if 8 Qtrs. of samples collected.
TLC Dry Cleaner	12210	230 E. Reinken	Belen	Valencia	34.66099444	-106.76421944	3	PCE	5	S	GW	Stage 1 AP	Natural attenuation has addressed PCE. Cis-DCE remains. Additional investigation and remediation needed.
Please contact Justin Ball for questions about sites assigned to position 122210													